

SINUMERIK 840/840C  
SINUMERIK 850  
SINUMERIK 880/880 GA2  
Measuring Cycles Version 20 and higher

User's Guide

08.96 Edition

# **SINUMERIK 840/840C SINUMERIK 850 SINUMERIK 880/880 GA2 Measuring Cycles Version 20 and higher**

**User's Guide**

**User Documentation**

**Valid for:**

*Control*

SINUMERIK 840  
SINUMERIK 840C  
SINUMERIK 850  
SINUMERIK 880  
SINUMERIK 880 GA2

*Software Version*

from SW 01  
from SW 01  
from SW 04  
from SW 04  
from SW 01

**08.96 Edition**

## Printing history

Brief details of this edition and previous editions are listed below.

The status of each edition is shown by the code in the "Remarks" column.

*Status code in "Remarks" column:*

**A** . . . New documentation

**B** . . . Unrevised reprint with new Order No.

**C** . . . Revised edition with new status.

If factual changes have been made on a page since the last edition, this is indicated by a new edition coding in the header on that page.

<b>Edition</b>	<b>Order No.</b>	<b>Remarks</b>
07.90	6ZB5 410-0EX02-0BA0	<b>A</b>
10.91	6ZB5 410-0EX02-0BA1	<b>C</b>
01.93	6FC5 197-0AB70-0BP0	<b>C</b>
08.96	6FC5 197-0AB70-0BP1	<b>C</b>

Siemens quality for software and training  
to DIN ISO 9001, Reg. No. 2160-01

Other functions not described in this documentation might be executable in the control. This does not, however, represent an obligation to supply such functions with a new control or when servicing.

This publication was produced on the Siemens 5800 Office System.

The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design, are reserved.

We have checked that the contents of this publication agree with the hardware and software described herein. The information given in this publication is reviewed at regular intervals and any corrections that might be necessary are made in the subsequent printings. Suggestions for improvement are welcome at all times.


Subject to change without prior notice.

© Siemens AG 1992, 1993, 1994, 1995, 1996 All Rights Reserved


# Preliminary Remarks

## Technical Comments

Other functions not described in this documentation might be executable in the control. This does not, however, represent an obligation to supply such functions with a new control or when servicing.



***The symbol shown on the left appears in this documentation whenever the machine tool manufacturer has the possibility of influencing/modifying the functional behaviour described by changing a cycle machine data (MDC).***



Since the setting up of the cycle machine data range and of the cycle setting data range is variable, the relevant data in the examples are explained on the basis of the standard settings.

***This User's Guide is valid for:***  
***SINUMERIK 850/880 as from Software Version 4,***  
***SINUMERIK 880 GA2 as from Software Version 1,***  
***SINUMERIK 840 as from Software Version 1,***  
***SINUMERIK 840C as from Software Version 1,***  
***Measuring Cycles as from Version 20!***

Introduction	1
Defining Parameters	2
Measuring Cycle Auxiliary Programs	3
Measuring Cycles for Turning Machines	4
Measuring Cycles for Milling Machines and Machining Centres	5
Measuring Cycles for Turning and Milling Work	6
Measuring in JOG Mode (SINUMERIK 880/880 GA2)	7
Automatic Workpiece Measurement in JOG Mode (SINUMERIK 840 SW2)	8
Alarms	9
Lists	10
Abbreviations	11

# Contents

	Page
<b>1</b>	<b>Introduction</b> ..... 1-1
1.1	General ..... 1-1
1.2	Measurement variants ..... 1-2
1.2.1	Measurement variants for turning machines ..... 1-2
1.2.2	Measurement variants for milling machines and machining centres ..... 1-4
1.3	Probe ..... 1-7
1.3.1	Multidirectional probe (3D) ..... 1-8
1.3.2	Bidirectional probe ..... 1-8
1.3.3	Monodirectional probe ..... 1-8
1.4	Calibrating tool, workpiece probe in the TOA memory ..... 1-9
1.4.1	Assignment of calibrating tool in the TOA memory for turning machines ..... 1-9
1.4.2	Workpiece probe in the TOA memory for turning machines ..... 1-10
1.4.3	Workpiece probe in the TOA memory for milling machines and machining centres ..... 1-13
1.5	Measuring principle ..... 1-14
1.5.1	Probe signal evaluation ..... 1-14
1.5.2	In-process measurement ..... 1-15
1.5.3	Measuring accuracy ..... 1-17
1.5.4	Outline flowchart for workpiece measurement ..... 1-18
1.6	Measuring strategy and correction value determination ..... 1-20
1.6.1	Types of dimensional deviation ..... 1-20
1.6.2	Averaging ..... 1-21
1.7	Tolerance parameters (R33, R34, R36, R37, R40/R41) ..... 1-23
1.7.1	Tolerance parameters for workpiece measurement ..... 1-24
1.7.2	Tolerance parameters for tool measurement ..... 1-25
1.8	Plane definition ..... 1-26
1.9	Logging ..... 1-27
1.9.1	Logging via logging module ..... 1-27
1.9.2	Logging via CP315 with the SINUMERIK 840/880 ..... 1-28
1.9.2.1	General description ..... 1-28
1.9.2.2	Configuring the form ..... 1-29
1.9.2.3	Data transmission between NC and PLC ..... 1-33
1.9.2.4	Description of transfer parameters ..... 1-35
1.9.2.5	Error messages of logging function ..... 1-39
1.9.2.6	Example demonstrating the logging of measurement results for the SINUMERIK 840/880 ..... 1-39
1.10	Notes to ensure smooth running of the measuring cycles ..... 1-44
1.11	Reference points on machine and workpiece ..... 1-45
<b>2</b>	<b>Defining Parameters</b> ..... 2-1
2.1	R parameters used ..... 2-1
2.2	R10 Offset number ..... 2-1
2.2.1	R10 Tool offset memory number (workpiece measurement) ..... 2-1
2.2.1.1	D number known: Relative D number ..... 2-1
2.2.1.2	D number unknown ..... 2-2
2.2.2	R10 ZO memory number (ZO determination) ..... 2-2
2.3	R11 Empirical value/average value ..... 2-2

2.4	R12 Number of calibrating elements	2-4
2.5	R13 Compensating angle position for mono-directional probe, angular offset for driven tools	2-4
2.6	R22 Probe type/probe number	2-5
2.7	R23 Measurement variant	2-5
2.7.1	L972/L982 Tool measurement (T)	2-5
2.7.2	L973 Calibrating the workpiece probe (T)	2-7
2.7.3	L974 Workpiece measurement (T)	2-7
2.7.4	L976 Calibrating the workpiece probe (M)	2-8
2.7.5	L977/L979 Workpiece measurement (M)	2-8
2.7.6	L978 Workpiece measurement (M)	2-8
2.7.7	L981 Workpiece measurement (T/M)	2-8
2.8	R25 Variable measuring speed	2-9
2.9	R27 Multiple measurement at same location	2-9
2.10	R28 Multiplication factor for measurement path 2a	2-9
2.11	R29 Weighting factor k for averaging	2-9
2.12	R30 Number of measuring axis	2-10
2.13	R33...R37 Tolerance parameters	2-11

### **3 Measuring Cycle Auxiliary Programs** 3-1

3.1	Internal measuring cycle auxiliary programs	3-2
3.1.1	L931 Auxiliary cycle for tool or workpiece measuring cycles	3-2
3.1.2	L932 Check MDC and transfer parameters	3-2
3.1.3	L933 Auxiliary cycle for tool or workpiece measuring cycles	3-2
3.1.4	L934 Auxiliary cycle for tool or workpiece measuring cycles	3-2
3.1.5	L935 Measurement result display selection	3-2
3.1.6	L936 Measurement abort	3-3
3.1.7	L937 Auxiliary cycle for workpiece measuring cycles	3-3
3.1.8	L938 Auxiliary cycle for tool or workpiece measuring cycles	3-3
3.1.9	L939 Auxiliary cycle for tool measuring cycles	3-3
3.2	Internal/external measuring cycle auxiliary programs	3-3
3.2.1	L960 Transfer of ZO data blocks (external)	3-3
3.2.2	L961 Additive input of empirical values (external)	3-4
3.2.3	L962 Erase program EV/AV (external)	3-4
3.2.4	L963 Auxiliary cycle for workpiece measuring cycle (external)	3-5
3.2.5	L964 Auxiliary cycle for workpiece measuring cycles (internal)	3-5
3.2.6	L965 Determination of measuring plane (external)	3-5
3.2.7	L966 Auxiliary program for operator guidance macro (OGM)	3-6
3.2.8	L967 Presetting of transfer parameters (internal)	3-6
3.2.9	L969 Auxiliary cycle for coordinate rotation (internal)	3-6
3.2.10	L970 Prepositioning cycle (external)	3-6
3.2.11	L971 Auxiliary cycle for tool measuring cycles (internal)	3-9
3.2.12	L980 Auxiliary cycle for tool measuring cycle L981 (internal)	3-9
3.2.13	L988 Auxiliary cycle for workpiece measuring cycles (internal/external)	3-9
3.2.14	L989 Auxiliary cycle for workpiece measuring cycle L979	3-9

### **4 Measuring Cycles for Turning Machines** 4-1

4.1	L972/L982 Tool measurement	4-2
4.1.1	L972/L982 Calibrating the tool probe	4-10
4.1.2	L972/L982 Measure tool	4-13
4.1.3	L972/L982 Automatic tool measurement	4-17

4.2	L973 Calibrating the workpiece probe .....	4-20
4.2.1	L973 Calibrating on any surface .....	4-21
4.3	L974 Workpiece measurement .....	4-23
4.3.1	L974 1-point measurement ZO determination .....	4-24
4.3.2	L974 1-point measurement .....	4-26
4.3.3	L974 1-point measurement with reversal .....	4-30
4.3.4	L974 2-point measurement on diameter .....	4-34
4.3.5	L974 Multi-point measurement on circumference .....	4-38
4.3.6	L974 Multi-point measurement on cylinder .....	4-41
4.4	Examples of application for workpiece measurement (L973, L974) ....	4-44
4.5	Parameter recommendations for L973, L974 .....	4-45
<b>5</b>	<b>Measuring Cycles for Milling Machines and Machining Centres ...</b>	<b>5-1</b>
5.1	L976 Calibrating the workpiece probe .....	5-2
5.1.1	L976 Calibrating the workpiece probe in reference hole (plane) .....	5-3
5.1.2	L976 Calibrating workpiece probe in reference hole (applicate) .....	5-6
5.1.3	L976 Calibrating workpiece probe in any hole (plane) .....	5-9
5.1.4	L976 Calibrating workpiece probe on any surface (applicate) .....	5-12
5.2	L977 Workpiece measurement hole/shaft/slots/ZO determination (paraxial) .....	5-14
5.2.1	L977 Measure hole (paraxial) .....	5-15
5.2.2	L977 Measure shaft (paraxial) .....	5-19
5.2.3	L977 Measure slot (paraxial) .....	5-23
5.2.4	L977 Measure web (paraxial) .....	5-27
5.2.5	L977 ZO determination in hole (paraxial) .....	5-31
5.2.6	L977 ZO determination on shaft .....	5-34
5.2.7	L977 ZO determination in slot (paraxial) .....	5-37
5.2.8	L977 ZO determination on a web (paraxial) .....	5-40
5.3	L979 Workpiece measurement hole/shaft/slot/web/ZO determination (at random angles) .....	5-43
5.3.1	L979 Measure hole (at random angles) .....	5-46
5.3.2	L979 Measure shaft (at random angles) .....	5-49
5.3.3	L979 Measure slot (at random angles) .....	5-52
5.3.4	L979 Measure web (at random angles) .....	5-55
5.3.5	L979 ZO determination in hole (at random angles) .....	5-58
5.3.6	L979 ZO determination at shaft (at random angles) .....	5-60
5.3.7	L979 ZO determination in slot (at random angles) .....	5-62
5.3.8	L979 ZO determination at web (at random angles) .....	5-64
5.4	L978 Workpiece measurement surface/angle /ZO determination (with and without differential measurement) .....	5-66
5.4.1	L978 ZO determination on surface (1-point measuring cycle) .....	5-67
5.4.2	L978 1-point measurement .....	5-70
5.4.3	L978 Paraxial multipoint measurement .....	5-73
5.4.4	L978 Angular measurement (ZO determination) .....	5-76

<b>6</b>	<b>Measuring Cycles for Turning and Milling Work</b> .....	6-1
6.1	L981 Searching for a hole/slot .....	6-1
<b>7</b>	<b>Measuring in JOG Mode (SINUMERIK 880/880 GA2)</b> .....	7-1
7.1	Tool measurement .....	7-1
7.1.1	Operating and function sequence .....	7-2
7.2	Workpiece measurement .....	7-9
7.2.1	Operating and function sequence .....	7-9
<b>8</b>	<b>Automatic Workpiece Measurement in JOG Mode (SINUMERIK 840 SW2)</b>	8-1
8.1	General .....	8-1
8.2	Setting the parameters for workpiece measurement and calibration .....	8-4
8.3	Calibrating probe in any hole .....	8-5
8.4	Workpiece measurement .....	8-7
8.4.1	Measuring a hole .....	8-9
8.4.2	Measuring a shaft .....	8-11
8.4.3	Measuring a slot .....	8-14
8.4.4	Measuring a web .....	8-17
8.4.5	Measuring a surface .....	8-20
8.4.6	Measuring an angle .....	8-23
8.4.7	Measuring a reference point on the workpiece .....	8-26
<b>9</b>	<b>Alarms</b> .....	9-1
9.1	Measuring cycle alarms .....	9-1
9.2	Measuring cycle alarms .....	9-4
9.3	Alarm description .....	9-7
<b>10</b>	<b>Lists</b> .....	10-1
10.1	Overview of transfer parameters .....	10-1
10.1.1	Compatibility list, Version 10 to Version 20 .....	10-20
10.2	Result displays .....	10-21
10.3	Result parameters .....	10-23
10.4	Setting data for measuring cycles .....	10-32
10.4.1	Cycle setting data memory (SDC) .....	10-32
10.4.1.1	Channel-oriented values .....	10-32
10.4.1.2	Channel-oriented bits .....	10-32
10.4.2	SDC Channel-oriented values .....	10-33
10.4.3	Channel-oriented bits .....	10-33
<b>11</b>	<b>Abbreviations</b> .....	11-1

# 1 Introduction

## 1.1 General

The ever increasing rationalization and automation of manufacture makes additional demands on numerically controlled machine tools. Measuring on the machine is one of the new tasks to be coped with.

In order to be able:

- to use touch trigger probes,
- to use the path measuring systems of the machine for measuring actual values and
- to do without additional external electronic controls for measured value processing,

adapted functions are required in the control (CNC).

Before dealing in more detail with the measuring cycles created for measurement and measured value processing, some practical applications for measuring on the machine are given as an introduction to the subject.

The general purpose to be achieved by measurement on CNC turning machines and CNC milling machines and machining centres is to detect at an early stage impermissible dimensional deviations of the workpiece to enable suitable compensation measures to be initiated automatically.

Dimensional deviations are due to different causes:

- Tool wear and tool clamping
- Heat effects on the CNC machine, i.e. thermal expansion of the ball screw, machine bed or spindle head.

In addition to checking the workpiece for dimensional accuracy, measuring on a CNC machine offers further applications:

- Detection of tool breakage
- Measuring the tool geometry
- Determination of workpiece clamping tolerances
- Compensation for factors influencing the machining process (e.g. force and temperature)
- Identifying a pallet
- Determination of the centre point of a hole.

For this wide range of measuring tasks, specially tailored programmable measuring cycles are required putting the machine tool manufacturer and user in a position to achieve optimum solutions to the measuring tasks to be performed on his machine tool.

When measuring on the CNC machine, a distinction is made between two types of application, i.e. **tool measurement** and **workpiece measurement**:

### Tool measurement

For tool measurement, the changed tool (seated in the turret or in the tool spindle) is moved onto the probe. The probe is either stationary or is swivelled or slid into the machine work area by a mechanical device. The automatically determined tool geometry is subsequently entered into a tool compensation memory provided for this purpose.

### Workpiece measurement

For workpiece measurement, a probe is moved on the clamped workpiece in the same way as a tool. The probe is fitted in the turret or in the tool slide, depending on the design of the machine. The high flexibility of the measuring cycles enables nearly all measuring tasks capable of being performed on a turning or milling machine to be accomplished successfully.

On the following pages, different measurement variants are illustrated selected according to the criteria of flexibility, accuracy and duration of measurement.

## 1.2 Measurement variants

### 1.2.1 Measurement variants for turning machines




Fig. 1.1 Tool measurement







<p>1-point measurement outside</p>  <p>Calibrating      Measuring</p> <p><b>Result:</b> Actual dimension (diameter, length) deviation, tool offset, zero offset (G58)</p>	<p>1-point measurement inside</p>  <p>Calibrating      Measuring</p> <p><b>Result:</b> Actual dimension (diameter, length) deviation, tool offset, zero offset (G58)</p>
<p>1-point measurement outside with 180° spindle reversal</p>  <p>Calibrating      Measuring</p> <p><b>Result:</b> Actual dimension (diameter, length) deviation, tool offset</p>	<p>1-point measurement inside with 180° spindle reversal</p>  <p>Calibrating      Measuring</p> <p><b>Result:</b> Actual dimension (diameter, length) deviation, tool offset</p>
<p>Multi-point measurement on circumference</p>  <p>e.g.: R24=6 R26=60</p> <p><b>Result:</b> Actual dimension (diameter, length) deviation, tool offset</p>	<p>Multi-point measurement on cylinder</p>  <p>e.g.: R24=5 R19=10</p> <p><b>Result:</b> Actual dimension (diameter, length) deviation, tool offset</p>

Fig. 1.2 Workpiece measurement with calibration




Fig. 1.3 Workpiece measurement without calibration

### 1.2.2 Measurement variants for milling machines and machining centres




Fig. 1.4 Tool measurement





<p>Bore:</p>  <p><b>Result:</b> Actual dimension (diameter), deviation, centre point, tool offset, zero offset (G58)</p>	<p>Shaft:</p>  <p><b>Result:</b> Actual dimension (diameter), deviation, centre point, tool offset, zero offset (G58)</p>
<p>Slot:</p>  <p><b>Result:</b> Actual dimension (slot width), deviation, slot centre, tool offset, zero offset (G58)</p>	<p>Web:</p>  <p><b>Result:</b> Actual dimension (web width), deviation, web centre, tool offset, zero offset (G58)</p>

Fig. 1.5 Workpiece measurement







<p><b>Blank gauging</b></p>  <p><b>Result:</b> Position, deviation zero offset (G58)</p>	<p><b>1-point measurement</b></p>  <p><b>Result:</b> Actual dimension, deviation, tool offset</p>
<p><b>Multi point measurement paraxial</b></p>  <p><b>Result:</b> Actual dimension, deviation, tool offset</p>	<p><b>Angular measurement</b></p>  <p><b>Result:</b> Actual dimension (angle), deviation, zero offset (G58)</p>
<p><b>Measurement at random angles with 3-point measurement: hole, shaft, circular segment</b></p>  <p><b>Result:</b> Actual dimension (diameter), deviation, centre point, tool offset, zero offset (G58)</p>	<p><b>Measurement at random angles with 2-point measurement: slot, web</b></p>  <p><b>Result:</b> Actual dimension (slot width, web width), deviation, slot centre, web centre tool offset, zero offset (G58)</p>

Fig. 1.6 Workpiece measurement

### 1.3 Probe

For determining tool and workpiece dimensions a touch trigger probe is required which supplies a constant signal (no pulse) when deflected.

The probe must switch with almost no bounce. This is generally achieved by adjusting the probe mechanically. In addition, "Software debouncing" is carried out in the NC.

Various types of probe of different make are available on the market. Probes are therefore classified in three groups according to the number of directions in which the probe can be deflected (see figure below).




Fig. 1.7 Types of probe

	Turning machine		Milling machines and machining centres	
	Tool measurement	Workpiece measurement	Tool measurement	Workpiece measurement
Multidirectional probe	yes	yes	yes	yes
Bidirectional probe		yes		yes
Monodirectional probe				yes

While on turning machines a bidirectional probe can be used, milling machines and machining centres also permit the use of a monodirectional probe for workpiece measurement. In the cycles for milling machines and machining centres, the probe type is to be specified by an R parameter.

### 1.3.1 Multidirectional probe (3D)

With this type of probe, tool and workpiece measuring cycles can be used without restriction.

### 1.3.2 Bidirectional probe

This type of probe can be used on turning machines for workpiece measurement. When performing workpiece measurement on milling machines and machining centres, this probe type is treated as a monodirectional probe.

### 1.3.3 Monodirectional probe

This type cannot be used on turning machines. It can be used for workpiece measurement on milling machines and machining centres with some few restrictions (more information is given in the respective cycles).

It must be possible to position the spindle with the NC function "M19" and to transmit the probe switching signal through 380° to the receiving station (on the machine column).

The probe must be aligned mechanically in the spindle in such a way that measurements can be performed in the following directions with the spindle positioned to 0°.

	Measurement with 0 degr. spindle position
X-Y plane (G17)	Positive X direction
Z-X plane (G18)	Positive Z direction
Y-Z plane (G19)	Positive Y direction

Measurement takes longer with a monodirectional probe, because the spindle must be positioned in the cycle several times with M19.

## 1.4 Calibrating tool, workpiece probe in the TOA memory

### 1.4.1 Assignment of calibrating tool in the TOA memory for turning machines

On turning machines, the calibrating tool is treated same as a tool type 3 and, therefore, must be input in the TOA memory as such.




Fig. 1.8 Calibrating tool in the TOA memory for turning machines

### 1.4.2 Workpiece probe in the TOA memory for turning machines

On turning machines, measuring cycles are classified in the following types according to their respective locations:




Fig. 1.9 Workpiece probe type 5 in the TOA memory for turning machines




Fig. 1.10 Workpiece probe type 6 (8) in the TOA memory for turning machines  
(type in parentheses = in front of turning centre)

Dn	Type 7	
P0		Tool Number
P1	7	Tool type
P2	L1	L1 Geometry
P3	L2	L2 Geometry
P4	r	Diameter/radius
P5	0	L1 Wear
P6	0	L2 Wear
P7	0	Diameter/radius
P8	0	Base (add. TO)
P9	0	Base (add. TO)





Fig. 1.11 Workpiece probe type 7 in the TOA memory for turning machines

Dn	Type 8 (6)	
P0		Tool number
P1	8	Tool type
P2	L1	L1 Geometry
P3	L2	L2 Geometry
P4	r	Diameter/radius
P5	0	L1 Wear
P6	0	L2 Wear
P7	0	Diameter/radius
P8	0	Base (add. TO)
P9	0	Base (add. TO)


Fig. 1.12 Workpiece probe type 8 (6) in the TOA memory for turning machines  
(type in parentheses = in front of turning centre)

1.4.2 Workpiece probe in the TOA memory for turning machines

If double probes are used (Version 30 and higher) type 3 must be entered. The geometry data must be entered in two successive TOA memories, the data in  $D_n$  for measuring in the negative direction and the data in  $D_{n+1}$  for measuring in the positive direction.

	$D_n$	$D_{n+1}$	Type 3 axial
P0	P0		Tool number
P1	3	3	Tool type
P2	a	b	L1 Geometry
P3	c	d	L2 Geometry
P4	r	r	Diameter/radius
P5	0	0	L1 Wear
P6	0	0	L2 Wear
P7	0	0	Diameter/radius
P8	0	0	Base (add. TO)
P9	0	0	Base (add. TO)

	$D_n$	$D_{n+1}$	Type 3 radial
P0			Tool number
P1	3	3	Tool type
P2	e	f	L1 Geometry
P3	g	h	L2 Geometry
P4	r	r	Diameter/radius
P5	0	0	L1 Wear
P6	0	0	L2 Wear
P7	0	0	Diameter/radius
P8	0	0	Base (add. TO)
P9	0	0	Base (add. TO)


Fig. 1.13 Assignment of workpiece probes in the TOA memory for turning machines

### 1.4.3 Workpiece probe in the TO memory for milling machines and machining centres

On milling machines and machining centres, the probe is treated as a tool type 30 and, therefore, must be input in the TOA memory as such.

As from Version 3.5 it is now possible to define the length L1 to the end of the probe in cycle machine data 7004, bit 5. This setting takes effect in cycles L976/L978 calibration and measurement of the applicate (drilling axis).

Dn		
P0		Tool number
P1	30	Tool type
P2	L1	L1 Geometry
P3	L2	L2 Geometry
P4	r	Diameter/radius
P5	0	L1 Wear
P6	0	L2 Wear
P7	0	Diameter/radius
P8	0	Base (add. TO)
P9	0	Base (add. TO)



The diagram illustrates a workpiece probe with a cylindrical upper section and a tapered lower section. A force vector 'F' is applied to the top of the probe. Dimension 'L1' is the vertical distance from the top of the probe to the center of the tip. Dimension 'L2' is the horizontal distance from the vertical axis to the center of the tip. The radius of the tip is labeled 'r'. A dashed line indicates the vertical axis of the probe.

Fig 1.14 Workpiece probe in the TOA memory for milling machines and machining centres

## 1.5 Measuring principle

### 1.5.1 Probe signal evaluation

Two inputs for connecting touch trigger probes are provided on the SINUMERIK interface module.

If a measuring point is to be approached, a travel command is transmitted to the position control loop and the probe is moved towards the measuring point. A point behind the expected measuring point is defined as the position setpoint value. The actual axis value at the time of the switching position is measured and the drive is stopped as soon as the probe makes contact. The remaining "distance to go" is deleted.




Fig. 1.15 Probe signal evaluation



**Measurement path a/measuring speed**

Normally, the path increment is 1 mm. It can, however, be increased or reduced when calling the measuring cycles with parameter R 28. The approach speed increases automatically from 155 mm/min to 300 mm/min when defining the value for a>1. This value has been chosen to make sure that the deceleration distance is less than the permissible probe deflection.

For measuring cycles the measuring speed can be preset via parameter R 25 as desired. However, safe deceleration within the deflection path of the probe should be ensured.

Hence, the maximum approach speed (measuring speed) depends only on

- the permissible deflection path the probe used
- the delay until "delete distance to go" is executed and
- the deceleration behaviour of the axis.

**Example:**

Deceleration path calculation

$$s_b = \underbrace{v \cdot t}_{s_1} + \underbrace{\frac{v^2}{2b}}_{s_2} + s$$

$s_b$	Deceleration path	in m
$v$	Approach speed	in m/s
$t$	Delay	in s
$b$	Deceleration delay	in m/s <sup>2</sup>
$s$	Following error	in m




Fig. 1.17 Path/time diagram

The deflection of the probe until the axis reaches zero speed is approx. 12.6 mm in the case of an approach speed of 6 m/min and a delay of 1 m/s<sup>2</sup>.

### 1.5.3 Measuring accuracy

The repeat accuracy of SINUMERIK controls for in-process measurement is  $\pm 1 \mu\text{m}$ .

The attainable measuring accuracy therefore depends on the following factors:

- Repeat accuracy of machine
- Repeat accuracy of probe
- Resolution of measuring system

To give an example, the following series of measurements have been carried out on a turning machine:






Fig. 1.18 Measuring accuracy

### 1.5.4 Outline flowchart for workpiece measurement



1.5.4 Outline flowchart for workpiece measurement



## 1.6 Measuring strategy and correction value determination

Precise determination of actual workpiece dimensions is required to determine the actual dimensional deviations of the workpiece and to be able to correct these during subsequent machining operations and thus to obtain a permanent high standard of machining accuracy. When measuring on the machine, the actual dimensions are derived from the path measuring systems of the position-controlled CNC feed axes. For each dimensional deviation determined from the set and actual workpiece dimensions there is a multitude of causes which essentially can be classified in 3 categories.

### 1.6.1 Types of dimensional deviation

- **Dimensional deviations the causes of which do not follow a trend**, such as position dispersion range of the feed axes or differences in measured values between internal measurements (probe) and external measuring device (micrometer, measuring machine etc.).

Here, the possibility is provided of using so-called empirical values (R11) which are stored in separate memories. The set/actual difference determined is corrected automatically by the empirical value. See the descriptions of the various cycles and Section 2 for more details.

- **Dimensional deviations the causes of which follow a trend**, such as tool wear or thermal expansion of the ball screw.

These deviations are corrected by specifying fixed threshold values (e.g. R34) (see Section 1.7).

- **Random dimensional deviations**, e.g. due to temperature variations, coolant or slightly contaminated measuring points.

Presuming the ideal case, only those dimensional deviations can be taken into account for correction value determination the courses of which follow a trend. Considering the fact, however, that it is never known to which extent and in which direction random dimensional deviations influence the measurement result, a strategy (floating average value generation) is needed that derives the compensation value from the measured set/actual difference.

## 1.6.2 Averaging

Averaging in combination with higher-order measurement weighting has proved a suitable means to do this.

The formula of the average-value generation chosen is:

$$AV_{\text{new}} = AV_{\text{old}} - \frac{AV_{\text{old}} - D_i}{k}$$

$AV_{\text{new}}$  = Average value new = amount of correction

$AV_{\text{old}}$  = Average value of last measurement

$k$  = Weighting factor for calculating the average value (R29)

$D_i$  = Set/actual difference measured (minus empirical value, if any)

This formula takes into account the trend of the dimensional deviations of a series of machining operations. The weighting factor  $k$  (R29), on the basis of which the average value is generated, can be chosen.

A new measurement result affected by random dimensional deviations, as mentioned above, only influences the new tool offset to some extent, depending on the weighting factor.




Fig. 1.19 Computational variation of the average value with different weightings  $k$

**Effects:**

- The greater  $k$ , the slower the formula reacts when major deviations occur in computation or counter correction, however, at the same time random scatter is reduced with increasing  $k$ .
- The smaller  $k$ , the faster the formula reacts when major deviations occur in computation or counter correction, however, the greater the effect of random variations.
- The average value  $A_v$  is calculated from 0 onwards over the number of workpieces  $i$ , until the calculated average value exceeds the range of "Zero offset" (R33). From this limit onwards, the calculated average value is corrected.

**Example:** Average value generation

Lower limit = 4 $\mu\text{m}$			
	$D_i$	Average value $k=3$	Average value $k=2$
1st measurement	3 $\mu\text{m}$	1 $\mu\text{m}$	1.5 $\mu\text{m}$
2nd measurement	5 $\mu\text{m}$	2.33 $\mu\text{m}$	3.25 $\mu\text{m}$
3rd measurement	6 $\mu\text{m}$	3.55 $\mu\text{m}$	③ 4.62 $\mu\text{m}$
4th measurement	2 $\mu\text{m}$	3.03 $\mu\text{m}$	1 $\mu\text{m}$
5th measurement	4 $\mu\text{m}$	3.26 $\mu\text{m}$	2.5 $\mu\text{m}$
6th measurement	5 $\mu\text{m}$	3.84 $\mu\text{m}$	3.75 $\mu\text{m}$
7th measurement	5 $\mu\text{m}$	① 4.23 $\mu\text{m}$	④ 4.375 $\mu\text{m}$
8th measurement	3 $\mu\text{m}$	1 $\mu\text{m}$	1.5 $\mu\text{m}$
9th measurement	7 $\mu\text{m}$	3 $\mu\text{m}$	⑤ 4.25 $\mu\text{m}$
10th measurement	7 $\mu\text{m}$	② 4.33 $\mu\text{m}$	3.5 $\mu\text{m}$




Fig. 1.20 Computational variation of average values with two different weightings  $k$

## 1.7 Tolerance parameters (R33, R34, R36, R37, R40/R41)

Averaging by itself is not sufficient to ensure a permanent high standard of machining accuracy. For constant deviations (no trend), the dimensional deviation measured can be corrected by an empirical value. In addition, further corrections can be derived for deviations following a trend. For this purpose, tolerance bands must be allocated to the associated set dimension via parameters (R parameters) in the machining program prior to measuring cycle call.

The set workpiece dimension is placed in the middle of the permissible  $\pm$  tolerance band for reasons of symmetry.

The tolerance bands and the reactions derived from them have been specified as follows:

### Safe area (R36):

This limit has no influence on averaging. It is used for diagnostics. When this limit is reached, this means that there is a probe fault or that an incorrect setpoint position has been specified. AUTOMATIC operation is interrupted and the program cannot be continued. An alarm text appears on the display to warn the operator.

### Caution:

In the case of tool measurement, the "safe area" tolerance is derived from the difference between the old correction value (TOA memory) and the new tool length.

### Dimensional difference check (R37):

Tool wear from workpiece n to workpiece n+1.

This limit has no influence on correction value generation either. When this limit is reached, the tool is probably worn down and must be replaced.

An alarm is displayed to warn the operator. The program can be continued by NC Start.

This tolerance limit is generally used by the PLC for tool management (twin tools, wear monitoring).

### Caution:

For tool measurement, the tolerance is determined as in the case of the safe area.

### Workpiece tolerance (R40/R41):

When measuring a dimensional deviation ranging between "2/3 tolerance of the workpiece" and "dimensional difference check" (this might be the case when using a new tool, for instance), this dimensional deviation is regarded 100% as tool offset.

As a further step, the previous average value is erased.

This allows fast counteraction when major dimensional deviations occur. AUTOMATIC operation is interrupted when the tolerance limit of the workpiece is exceeded. "Oversize" or "undersize" is indicated to the operator on the control display monitor, depending on the tolerance zone position. Machining can be continued by NC Start.

**2/3 tolerance of workpiece (R34):**

Calculation of an average value is carried out within the range of "Lower limit" and "2/3 tolerance of workpiece" according to the formula as given in Section 1.6.2 (measuring strategy).

$A_{v_{new}}$  is compared with R33:


When  $A_{v_{new}}$  is **greater than** R33, correction is carried out by  $A_{v_{new}}$  and the associated average value memory is erased.

When  $A_{v_{new}}$  is **less than** the value in R33, no correction is carried out. This prevents too abrupt corrections from being made (depending on weighting factor k).


**Lower limit (zero offset range R33):**

This tolerance band conforms to the amount of maximum random dimensional deviations. It must be determined for every machine. Within these limits, no tool offset applies. However, the average value of this measuring point is updated and re-stored with the set/actual difference measured corrected by an empirical value if necessary.

**1.7.1 Tolerance parameters for workpiece measurement**



### 1.7.2 Tolerance parameters for tool measurement



## 1.8 Plane definition

Planes can be selected with G17, G18 and G19 or arbitrarily defined with G16. Length 1 and length 2 are allocated to the axes depending on the type of tool used as follows:

Plane selection according to DIN	Arbitrary plane selection	Tool type	Length 1 effective in axis	Length 2 effective in axis
G17	G16 XY	Types 1...9 Turning tool	Y	X
	G16 XYZ	Types 10..19 Drill	Z	—
	G16 XYZ	Types 20..29 Milling tool	Z	—
	G16 XYZX G16 XYZY	Types 30..39 Angle head	Z Z	X Y

Plane selection according to DIN	Arbitrary plane selection	Tool type	Length 1 effective in axis	Length 2 effective in axis
G18	G16 ZX	Types 1...9	X	Z
	G16 ZXY	Types 10..19	Y	—
	G16 ZXY	Types 20..29	Y	—
	G16 ZXYZ G16 ZXYX	Types 30..39	Y Y	Z X

Plane selection according to DIN	Arbitrary plane selection	Tool type	Length 1 effective in axis	Length 2 effective in axis
G19	G16 YZ	Types 1...9	Z	Y
	G16 YZX	Types 10..19	X	—
	G16 YZX	Types 20..29	X	—
	G16 YZXY G16 YZXZ	Types 30..39	X X	Y Z

## 1.9 Logging

### 1.9.1 Logging via logging module

The logging module together with an NC control enables measurement results to be logged.

The logging module can be used with all SINUMERIK controls where R parameters are output area by area.

Power supply to this module is from the connections on the front panel. The bus connector provided on the module is exclusively used for mechanical fixing in the module carrier.

The module can therefore be operated in the NC subrack of the SINUMERIK control and also in the external PLC subrack. Individual module holders can also be used. For more details see Logging Module Description. This description is supplied with each module.




Fig. 1.21 Logging module interface

## 1.9.2 Logging via CP315 with the SINUMERIK 840/880

Measurement results determined by workpiece measuring cycles can be logged with the CP315 and the subfunction FB package "Logging of measurement results". To do this, they are transferred to the PLC using the cycle L988. The PLC prepares the measurement results for log output. The measurement results are then transferred to the printer using the subfunction FB package "PLC controlled data output".

### 1.9.2.1 General description

The workpiece measuring cycles determine the data associated with a measuring point and store them in result parameters **R200 to R219**. These R parameters are available to the user for logging.

Using the cycle L988, the FB package "Logging of measurement results" picks those R parameters the user wants to be logged and outputs them on a printer (formatted). Data transmission is initiated by cycle L988, if the function has been activated via MDC.

The "Logging of measurement results" function is activated via **MDC 7000.6**. The output module is defined via MDC 7000.1.

Bit 7000.1=0:        Logging via P-PCB  
Bit 7000.1=1:        Logging via CP315

The CP315 output module is required for logging with L988.

Measurement results are output line by line.

When a workpiece has been completely machined, page feed can be effected via a control parameter to enable the log to be removed from the printer.

When a new workpiece is machined, the header and the plaintext for the measured value table is printed out for a new form. Automatic page feed takes place when the bottom of the page is reached. If some measuring points of the workpiece have not yet been recorded, the old header and plaintext are output once again, the page numbering on the following pages is incremented by 1 and the measuring point numbers are continued on the new page.

When machining of a new workpiece is started, a new protocol header is output and the page numbering of the protocol associated with the workpiece is reset to 1.

The user can influence the layout of the form. For example, the fixed texts on the form can be modified to suit the needs of the user. The data types logged on the form can also be freely chosen (within the scope of the available formats). The form is configured, i.e. texts for the form are entered via a part program.

The date and page number of the protocol pages associated with the workpiece can be output on the form.

The following procedure is used to log measurement results:

- Preparation of a part program for configuring the form and programming of initialization triggering transmission of the part program to the PLC.
- Programming of initialization triggering transmission of header data for the protocol to the PLC.
- Programming of a control parameter for protocol output and transmission to the PLC.
- Programming of initialization triggering transmission of measuring results to the PLC.

### 1.9.2.2 Configuring the form

The form for the protocol is configured in a part program that can be edited both at work scheduling and during manufacture.

The part program for configuring the form has the following structure:

- Part 1:       Description of format
- Part 2:       Description of fixed texts in the log header and measured value table  
Description of variables in the log header
- Part 3:       Description of the first and last line of the table frame
- Part 4:       Description of the variables of the basic line of a measuring point  
Description of the variables of the 1st supplementary line of a measuring point  
Description of the variables of the 2nd supplementary line of a measuring point  
              :  
              :  
              :  
Description of the variables of the 8th supplementary line of a measuring point
- Part 5:       End identifier


The form descriptions must be written in the part program as comments, i.e. with "(" and ")".

The part program must be terminated with "M30".


- Part 1

In part 1, the page format is described. Part 1 consists of:

- **Specification of character/line**



- **Specification of lines/page**




- Part 2

In Part 2, the fixed texts and variables of the log header are described as well as the locations of date, time of day and page number.


The maximum header size is 2000 characters:  
 (characters per line+6) · number of lines of header 2000.

Part 2 consists of:

– **Definition of fixed texts**




– **Definition of variables**



The last fixed text line must not be followed by a line with a variable without fixed text.  
 Remedy: Write additional fixed text, e.g. (@F\*ZZ\*SS @ @)LF in the line containing the variable.


The R parameters for header data must be programmed as a continuous area and in ascending sequence.

– **Definition of page numbers**




The page number has two decimal places. The column specifications refer to the 10th place.

### - Definition of time of day




### - Definition of date



- Part 3


Part 3 consists of the description of the first and last line of the table frame.




- Part 4

In Part 4, a description is given of the measuring points, the table frame and the variables of the basic and supplementary lines. Part 4 consists of:

### - Specification of locations of decimal points of the measuring points




– **Specification of location of tolerance violation**




– **Definition of perpendicular lines of the table frame**

The table frame must be input including blanks



– **Description of table variables**



– **Definition of time of day**

Code: see above

The variables of the basic line and all possible supplementary lines must be defined one. First define all variables of the basic line, then those of the first supplementary line etc.

• Part 5

Part 5 consists of the end identifier for form description.



### 1.9.2.3 Data transmission between NC and PLC

#### Data transmission, general

The following data must be transmitted from the NC to the PLC:

- Part program for form  
The part program is transmitted to the PLC using the "File transfer with PLC initiation" function.
- Control parameter for protocol output, data for protocol header and parameters for measuring point numbers. R parameters R39 to R45 are used for these.
- Measurement results and parameters for tolerance violations  
The measurement results are contained in the R parameters R200 to R219. The identifiers for tolerance violations are contained in the R parameters R38 and R39.


The type of data to be transmitted is defined in R39, 2nd digit:

- 0 = Part program for form
- 1 = Header data
- 2 = Measurement results + R39+R38 (+R45)
- 3 = Control function
- ⋮
- 9 = Control function


The part program number of the format description must be entered in R1. It is also possible to use a screen form to transmit the part program (for the form) and to enter the part program number.

#### Call of L988 (internal/external)


- Initiation for transmitting a part program with format description (external call of L988)




- Initiation for transmission for header data  
 (external call of L988)



- Transmission of control parameter R39  
 (External call of L988)



- Initiation for transfer of measurement results (internal call of L988)



#### 1.9.2.4 Description of transfer parameters

When using Siemens measuring cycles, the R parameters R38 to R45 are used as transfer parameters for logging output, protocol header information, measuring point numbers and tolerance violations. The values stored in the R parameters are transferred and not the R parameter numbers. This enables the R parameters to be freely chosen.

The R parameters R38 and R39 are control parameters (for Siemens measuring cycles).

The parameter addresses may have a maximum of 3 digits. The R parameter values may have a maximum of 8 digits with additional sign and decimal point. Leading zeros in R parameters can be ignored. In decimal-point notation, trailing zeros need not be written either.

With values less than 1, a 0 precedes the decimal point, e.g. 0.999 or 0.98.

Only negative signs are printed, positive signs are omitted. The sign is always printed in the same column irrespective of the succeeding number of decimal places of the value to be printed.

- Control parameter R39

R39 is an 8 digit control parameter.

- Configuration of R39
  - Digit 7 unassigned
  - Digit 6 unassigned
  - Digit 5 end of protocol
  - Digit 4 unassigned
  - Digit 3 specification of measuring point number
  - Digit 2 type of data to be transferred
  - Digit 1 modification of protocol
  - Digit 0 number of protocol lines of measuring point or number of space lines


1) R45 is required only if the measuring point number is preselected by the NC.

2) R38 is transferred only if the supplementary lines are marked with \* (tolerance exceeded).

- Description of decimal place 5  
R39=xx9xxxxx End of measurement result logging
- Description of decimal place 3  
R39=xxxx0xxx Measuring point number from the PLC  
R39=xxxx5xxx Measuring point number from R45
- Description of decimal place 2  
R39=xxxxx0xx Transfer of part program for a form  
R39=xxxxx1xx Transfer of workpiece-specific header data  
R39=xxxxx2xx Transfer of measurement results
- Description of decimal place 1  
R39=xxxxxx2x Do not mark the measurement result with a special character (base line)  
R39=xxxxxx3x Mark the measurement result with a special sign (base line)  
R39=xxxxxx5x Space line (with frame)  
R39=xxxxxx6x Page feed
- Description of decimal place 0  
R39=xxxxxxx 0 Number of protocol lines of a measuring point  
                  : or number of blanks  
                  9  
                  0 Output basic line only  
                  1 Output basic line + supplementary line  
                  2 Output basic line + 2 supplementary lines

• Control parameter R38

R38 is an 8-digit control parameter.



Mark measurement result with special character (1st to 8th supplementary line).  
Explanation: Special character = tolerance exceeded

• Transfer parameters for header data (R40 ... R45)

R39=xxxxy1xx	y=0 or 5 <sup>1)</sup>	
e.g. R40=7 ... 0	e.g. Part No.	
e.g. R41=15 ... 0	e.g. Order No.	(e.g. Digital places 8 ... 15 <sup>2)</sup> )
e.g. R42=7 ... 0	e.g. Order No.	(e.g. Digital places 0 ... 7 <sup>2)</sup> )
e.g. R43=3 ... 0	e.g. Program No.	
e.g. R44	not evaluated	
e.g. R45	not evaluated	

- Example showing header data

R39=11110100  
R40=100.4711  
R41=0  
R42=100  
R43=22

Header data must be output by the part program before the first measuring points are measured.

1) y=0: Automatic assignment of measuring point number  
y=5: Assignment by part programmer  
2) determined in the form description

The following data are output in the program header after the measuring data determined above.

Part number . . . . .	:	100.4711	Date: 16.08.88	Page: 1
Order number . . . . .	:	100		
Program number . . . . .	:	22		

- Transfer parameter for measuring point No. (4 digits) (R45)

The measuring point number can be generated in two ways, either automatically by the PLC or from parameter R45.

**Note:**

If the measuring point number is defined via R45 the measuring results must only be entered in R parameters R200-R219. Bit 7 must be set in cycle machine data 7000 (only enter result in R200-R219).

Which method is used is determined in parameter R39 with the command for output of the log header before the measurement results are logged. Once the decision has been made with log header output, change between automatic measuring point specification by the PLC and manual preselection by the part programmer is no longer possible.

With manual preselection, R45 must precede each measuring circle call.

The measuring point number has a total of 6 digits. The 4 left digital places are the actual measuring point number.

- Submeasuring point No. (decimal point and 1 decimal place)

The submeasuring point No. is used to designate supplementary lines whenever several measurements are to be made at one measuring point. How many submeasuring points of a measurement are to be logged is defined in R39. Submeasuring points must always be logged in ascending sequence and without a gap.

The assignment of the submeasuring point No. to a particular axis or function is made by the user.

The base line contains data of the diameter measured, the 1st supplementary line data of the horizontal axis and the 2nd supplementary line data of the particular axis when Siemens measuring cycles and submeasuring points are used. Further supplementary lines are not needed at present.


- Examples of parameter assignment

- Log output, basic line

R39=111102x0      Identification parameter  
                   x=      2 ... 3

R39=11110220 must be assigned for logging a measuring point. If a tolerance violation of the setpoint is detected after the measurement, the relevant measuring point can be given the identifier R39=11110230. The setpoint difference is marked with a special character.

- Log output, supplementary lines



R39=111022x can be assigned for logging submeasuring points.

x=1 ... 8: Number of supplementary lines

R39=11110230 can be assigned if a tolerance violation of one or several setpoints is ascertained after the measurement. In addition, the submeasuring points concerned must be marked in R38. The relevant setpoint difference is then marked with a special character.

- End of log, logging of measurement results

R39=11911311

End of log causes page feed to be activated and deselects the "Logging" mode in the PLC. The preceding log must be concluded with "End of protocol" before every new log (e.g. new header data, new part program for format description).

- Line feed

R39=1111035x

x=1 ... 9

The 0th digit in identification parameter R39 specifies the number of space lines. Up to 9 space lines can be programmed. Page feed does not cause the space lines to be transferred to the next page.

- Page feed

- Page feed selectively programmed

R39=11100361

Page feed can be programmed selectively, e.g. after "End of measurement result logging".

- Automatic page feed

Automatic page feed is always generated if:

- a page is full.
- a new log header is called.

### 1.9.2.5 Error messages of logging function

- Error message of auxiliary cycle L988
  - "Check MDC(N7000)": Is generated, if MDC 7000.1 and MDC 7000.6 are not set when L988 is called.
  - "PLC interface not ready": Is generated if the coordination bit is not reset by the PLC within 5 seconds.
- Error character when logging

Part number . . . . . :		1002458	Date: 24.12.88		Page: 1	
Order number . . . . . :		1000000001				
Program number . . . . . :		1234				
Measuring point	Setpoint	Actual value	Tolerance limit		Setpoint difference	Time of day
			+	-		
18	-9999.333	-9999.333	-1.999	-1.999	-1.999	11:39:28
****	-99999.333	-99999.333	#####	2.500	-1.700	11:39:29
19	#####	#####	1.200	#####	-1.700	11:39:30
20	44.000	44.000	1.200	2.500	-1.700	11:39:31

Explanation:

##### Measuring data exceeding the specified format.  
 \*\*\*\* Measuring point number in R45 too long

### 1.9.2.6 Example demonstrating the logging of measurement results for the SINUMERIK 840/880

- Task definition
  - Workpiece drawing
 

The axially symmetric workpiece shown is to be measured with a probe after it has been machined. The measuring data are logged.



- Suggestion for a solution

Prerequisites: configuration of the computer link via CP315, configuration of the FB package subfunctions "Logging of measurement results" and "PLC controlled data output" and activation of the logging function via MDC.

The following procedure is then suggested:

- **Preparation of a part program for configuring the form. The part program is as follows:**

```

_____ %MPF 200
Part 1 ( @C*80 )
      ( @L*72 )
      ( @F*1*1 @-----@ @-----@ @-----@ @-----@ @-----@
      @-----@ @-----@ @-----@ )
      ( @F*2*1 @I@ )
      ( @F*2*80 @I@ )
      ( @F*3*1 @I part number.....:@ )
      ( @F*3*52 @Datum:@ )
      ( @F*3*71 @Seite:@ )
      ( @F*3*80 @I@ )
      ( @F*4*1 @I@ )
      ( @F*4*80 @I@ )
      ( @F*5*1 @I order number.....:@ )
      ( @F*5*80 @I@ )
      ( @F*6*1 @I@ )
      ( @F*6*80 @I@ )
      ( @F*7*1 @I program number.....:@ )
      ( @F*7*45 @ serial number.....:@ )
      ( @F*7*80 @I@ )
Part 2 ( @F*8*1 @-----@ @-----@ @-----@ @-----@ @-----@
      @-----@ @-----@ @-----@ @-----@ @-----@
      ( @F*9*1 @I@ )
      ( @F*9*80 @I@ )
      ( @F*10*1 @I measuring@ @points@ )
      ( @F*10*15 @setpoint@ @ actual@ @value toleran@ @ce limit set@
      @ point Tim@ @e of day@ )
      ( @F*10*80 @I@ )
      ( @F*11*1 @I@ )
      ( @F*11*42 @+@ )
      ( @F*11*51 @- @ @ difference@ )
      ( @F*11*80 @I@ )
      ( @F*12*1 @-----@ @-----@ @-----@ @-----@ @-----@
      @-----@ @-----@ @-----@ @-----@ @-----@ )
      ( @V*3*23 @R40*F8.0 )
      ( @V*5*23 @R41*F8.0 )

      ( @V*7*23 @R43*F8.0 )
      ( @V*7*65 @R44*F8.0 )

      ( @D*3*58 )
      ( @S*3*77 )

```

```

Part 3 ( @A*13*1 @-----@ @-----@ @-----@ @-----@
@-----@ @-----@ @-----@ @-----@ )
( @M*15*8 )
( @O*64** )
( @R*14*1 @I @ @ I @ @ I @ @ I @ )
@ I I @ @ I @ @ I @ )
( @T*0*16 @R206*F8.3 )
( @T*0*28 @R209*F8.3 )
( @T*0*40 @R200*F5.3 )
( @T*0*49 @R203*F5.3 )
( @T*0*58 @R212*F5.3 )
( @Z*0*69 )
Part 4 ( @T*1*16 @R207*F8.3 )
( @T*1*28 @R210*F8.3 )
( @T*1*40 @R201*F5.3 )
( @T*1*49 @R204*F5.3 )
( @T*1*58 @R213*F5.3 )
( @Z*1*69 )
( @T*2*16 @R208*F8.3 )
( @T*2*28 @R211*F8.3 )
( @T*2*40 @R202*F5.3 )
( @T*2*49 @R205*F5.3 )
( @T*2*58 @R214*F5.3 )
( @Z*2*69 )
Part 5 ( @E )
M30
    
```

The supplementary lines need not be defined for this example.

– Programming of initiation triggering transfer of the part program to the PLC

```

%MPF 201
N1 R39=00000000 (Define control parameter)
N2 R1=200 (Specify MPF No.)
N3 L988 (Initiate transfer)
N4 M30
    
```

– Programming of part program for workpiece measurement

```

%MPF 202
N1 R900=R900+1 (Increment workpiece counter by 1)
R39=00000100 (Define control parameter for header data transfer)
R40=R900 (Header data)
R41=12343210 (Header data)
R43=974 (Header data)
R44=10002000 (Header data)
N4 L988 (Transfer header data to the PLC)

N5 G54 G00 X260 Z T1 D31 (Select ZO, call T No. and TO No.)
N10 R22=1 R23=22 R25=0 (Define parameter for calibration)
R27=1 R28=1 R30=1

N15 R31=1 R32=-20 R33=0 R36=1 (Calibrate probe in minus Z direction)
N20 L973 (Define parameter for calibration)
N25 R30=2 R32=240 (Calibrate probe in minus X direction)
N30 L973

N35 G54 G00 Z40 T2 D32 (Position MP1, call T No. and MC No.)
N40 R10=8 R11=0 R22=1 (Define parameter for measurement)
R23=21 R25=0 R27=1
R28=1 R29=1 R30=2

N45 R33=0.002 R34=0.005 (Define control parameter for transfer of measurement results)
R36=2 R37=1 R40=0.3
R41=-0.3 R42=200
N46 R39=11110220 (Measure MP1)
N55 L974
    
```

N60 G00 Z70 T1 D31	(Position probe to face MP2)
N65 X175	
N70 R10=9 R30=1	(Define parameter for measurement)
R40=0.2	
R41=-0.2 R42=50	
N71 R39=11110220	(Define control parameter for transfer of measurement results)
N80 L974	(Measure MP2)
N85 G00 Z80 T2 D32	(Position probe to face MP3)
N90 R10=10 R30=2	(Define parameter for measurement)
R40=0.5	
R41=-0.5 R42=150	
N91 R39=11110220	(Define control parameter for transfer of measurement results)
N100 L974	(Measure MP3)
N105 G00 Z150 T1 D31	(Position probe to face MP4)
N110 X50	
N115 R10=11 R30=1	(Define parameter for measurement)
R40=0.3	
R41=-0.3 R42=100	
N116 R39=11110220	(Define control parameter for transfer of measurement results)
N125 L974	(Measure MP4)
N130 G53 G00 Z250 T0	(Retract Z axis)
N135 G53 X280	(Retract X axis)
N140 R39=11911311	(Define end of protocol)
N145 L988	(and transfer to the PLC)
N150 M30	

#### – Log of programming example

Part number . . . . . :		17	Date: 30.08.91	Page: 1		
Order number . . . . . :		12343210				
Program number . . . . . :		974	Serial number . . . . . :	10002000		
Measuring point	Setpoint	Actual value	Tolerance limit		Setpoint difference	Time of day
			+	-		
1	200.000	200.104	0.300	- 0.300	- 0.104	09:36:20
2	50.000	50.797	0.200	- 0.200	-0.797 *	09:36:30
3	150.000	149.946	0.500	- 0.500	0.054	09:36:40
4	100.000	100.141	0.300	- 0.300	- 0.141	09:36:50

## 1.10 Notes to ensure smooth running of the measuring cycles

1. To ensure that the measuring cycles operate correctly it is imperative that the machine axes are set up according to DIN 66217.
2. Reference point approach must already have been performed.
3. GRC/CRC, (coordinate rotation) and scale modification must be deselected before a measuring cycle is called.
4. Inch/metric switchover.  
Measurements must be performed in the input system defined in MD 5002 bit 4, i.e. switchover with G70/G71 is not permitted.
5. Before the cycles are called, the axes must be positioned in such a way that they do not change direction when they move from the current position to approach the set position. Nor must the tool collide with the sensor or the workpiece probe collide with other machine parts when approaching the starting position with linear interpolation.
6. The parameters of the individual cycles must be defined before the cycles are called.
7. The cycles are automatically skipped in operating modes "Block search", "Dry run" and simulation.
8. All cycles can be exited with the following initial settings:  
T version G01, G90, G95  
M version G01, G90, G94
9. The cycle must be called no later than the 1st nesting depth.
10. Call cycle **L965**. This cycle must be started at least **once** after start-up and it must always be programmed when the measuring plane is changed.




Fig. 1.22 Nesting depth when calling measuring cycles

## 1.11 Reference points on machine and workpiece

The actual axis values of different actual value systems must be measured depending on the kind of measurement taken. For determining the tool length, for instance, it is advisable to use the machine actual value, while for measuring workpiece dimensions and for determining tool wear compensation it is more advantageous to use the workpiece zero point (Fig. 1.23). The machine actual value is the dimension between the machine zero point and the tool reference point.




Fig. 1.23 Reference points on machine and workpiece

- M = Machine zero point
- M' = Machine zero point displaced by DRF
- T = Control zero point by means of RESET displacement
- W = Workpiece zero point
- F = Tool reference point


END OF SECTION

## 2 Defining Parameters

### 2.1 R parameters used


The measuring cycles use the following R parameters:

R00 to R42	Transfer parameters
R40 to R49	Display parameters, measurement result,
R50	correction value
R51 to R99	Internal; are saved
R200 to R219	Display parameters; measurement result
R220 to R239	Internal
R488 to R499	Internal




### 2.2 R10 Offset number

#### 2.2.1 R10 Tool offset memory number (workpiece measurement)



##### 2.2.1.1 D number known: Relative D number




### 2.2.1.2 D number unknown

R8 = Extended T address

R9 = T address (tool number)

R10 = 0 No automatic tool offset

R10 = 8 7 6 5 4 3 2 1




### 2.2.2 R10 ZO memory number (ZO determination)

- R10 = 0 ZO memory not automatically included in calculation
- 1 ... 4 Automatic ZO memory inclusion in ZO G54 ... G57
- 5 Automatic ZO memory inclusion in ZO G58
- 6 Automatic ZO memory inclusion in the angle for coordinate rotation G58 (for angle measurement only)


The difference determined is

- included in ZO fine additive
- included in ZO coarse additive when MDC 804 bit 0 = 1 (ZO groups L960) is set.
- included in ZO coarse when measuring in JOG

### 2.3 R11 Empirical value / average value



***MDC determine the number of empirical and average values.***  
***(See machine tool manufacturer's specifications)***



Empirical values serve to suppress dimensional deviations **that do not follow a trend** (see explanation in Section 1.6.1).

R11 gives the number of the empirical value memory in the cycle setting data memory (SDC).




## 2.4 R12 Number of calibrating elements



The number of the calibrating element at which the workpiece probe is to be calibrated must be specified in R12.

## 2.5 R13 Compensating angle position for mono-directional probe, angular offset for driven tools



### Compensating angle position for mono-directional probe

When using a mono-directional probe, it may be necessary for machine-specific reasons (e.g. horizontal/vertical milling head) to compensate the position of the probe to be able to carry out the measurement. The determination in Section 1.3.3 (measuring direction/spindle position 0°) is no longer true because the milling head had been swivelled.

This wrong position can be compensated for by means of parameter R13. As a rule,  $R13=90^\circ$  or a multiple thereof.


If the direction changes because the milling head has been swivelled, then R13 must be preset with  $-360^\circ$  (usually  $0^\circ$ ).

### Angular offset for driven tools


For tool measurement with reversal of measurement (milling tools), the tool is automatically swivelled by 180 degrees for the 2nd measuring point.

If the 2nd measuring point cannot be measured in this angular position, for example with helical tooth T-slot mills, the angular position of the 2nd measuring point can additionally be displaced with parameter R13.

## 2.6 R22 Probe type/probe number



### Workpiece measurement:




### Tool measurement:



## 2.7 R23 Measurement variant

The measurement variant of the various cycles is determined via parameter R23.

### 2.7.1 L972/L982 Tool measurement (T)




Tool length in TO memory	
before measurement	after measurement
0 PF	PF
1*) PF	SF
2*) SF	SF

\*) Function implemented with Version 3.2 and higher




## 2.7.2 L973 Calibrating the workpiece probe (T)



## 2.7.3 L974 Workpiece measurement (T)

- R23 =
- 0 1-point measurement (ZO determination)
  - 21 1-point measurement
  - 22 1-point measurement with 180° reversal (workpiece)
  - 23 2-point measurement on diameter:
    - external measurement with R18/R19
    - internal measurement without R18/R19
  - 24 2-point measurement on diameter:
    - internal measurement **only** with R18/R19
  - 25 Multi-point measurement on circumference
  - 26 Multi-point measurement on cylinder

### 2.7.4 L976 Calibrating the workpiece probe (M)



### 2.7.5 L977/L979 Workpiece measurement (M)

- R23 =
- 1 Measure hole
  - 2 Measure shaft
  - 11 Measure slot
  - 12 Measure web
  - 21 ZO determination in the hole
  - 22 ZO determination at the shaft
  - 31 ZO determination in the slot
  - 32 ZO determination at a web

### 2.7.6 L978 Workpiece measurement (M)

- R23 =
- 0 1-point measurement (ZO determination at a surface)
  - 1 1-point measurement
  - 2 Multi-point measurement paraxial
  - 3 Angle measurement
  - 10 ZO determination at a surface with differential measurement \*)
  - 11 Measure surface with differential measurement \*)
  - 12 Multi-point measurement paraxial with differential measurement \*)
  - 13 Angle measurement with differential measurement \*)

### 2.7.7 L981 Workpiece measurement (T, M)

- R23=
- 1 Searching for a hole/slot on the end face
  - 2 Searching for a hole/slot at the cylinder

\*) Function implemented with Version 3.2 and higher

## 2.8 R25 Variable measuring speed

The measuring speed can be selected arbitrarily with R25. A feed rate of 150 mm/min is preset as standard when R25 = 0. This value increases automatically to 300 mm/min, when the measurement path a is modified via R28 (R28>1). The maximum measuring speed should be selected to be such that safe deceleration within the probe deflecting path is ensured (see Section 1.5.2, s-t diagram).

## 2.9 R27 Multiple measurement at same location

The number of measurements at the same location can be determined with R27. The set/actual difference D is determined arithmetically.

$$D = \frac{S_1 + S_2 + \dots + S_n}{n}$$

n = Number of measurements

### Note:

Make sure that the permissible R parameter value of +- 99 999.999 is not exceeded, because with multiple measurement actual values are summed up.

## 2.10 R28 Multiplication factor for measurement path 2a

Normally, the path increment a is 1 mm. It can, however, be increased when calling measuring cycles with parameter R28. The maximum value for R28 is calculated as follows:

$$R28_{\max} = \frac{\text{Axis traversing path}_{\max}}{2}$$

## 2.11 R29 Weighting factor k for averaging

Different weighting can be given to an individual measurement with weighting factor k. Hence, the new tool compensation is only partly influenced by an new measurement result, depending on k (see Section 1.6.2).

## 2.12 R30 Number of measuring axis

The axis number (1 ... 3) in the coordinate system (plane) must be specified with R30 (not the hardware axis number).

Measuring axis abscissa	R30 = 1
Measuring axis ordinate	R30 = 2
Measuring axis applicate	R30 = 3

### Example:

An NC machine has the following axis configuration: X1, Y1, Z1, X2, Y2, Z2.  
This results in the following programming:

```
%MPF...
:
:
G16      X2= Y2= Z2=      Define measuring plane
...      R30=1...        Measuring axis X2
...      R30=2...        Measuring axis Y2
...      R30=3...        Measuring axis Z2
:
:
G16      Z1= X2= X1=      Define measuring plane
...      R30=1...        Measuring axis Z1
...      R30=2...        Measuring axis X2
...      R30=3...        Measuring axis X1
:
:
M30
```


R30 must be defined with offset axis/measuring axis for certain measurement variants.

R30 = 4 3 2 1


Number of measuring axis  
Number of offset axis

### Note:


With a T version or G18 plane, the MDC 7002.1=axes not exchanged must be observed.



Axis definition via R30 in accordance with DIN 66217:



Axis definition via R30 (MDC 7002.1=0, axes exchanged):





## 2.13 R33...R37 Tolerance parameters

See Section 1.7

END OF SECTION

### 3 Measuring Cycle Auxiliary Programs

Some subroutines are called in the measuring cycles which can also be employed directly by the user.

	<i>Which programs can be used depends on the machine configuration and can also be partly determined via MDC. (See machine tool manufacturer's specifications)</i>	
---	--	---

Cycle	Function
L931	Auxiliary cycle for tool or workpiece measuring cycles
L932	Check MDC and transfer parameters
L933	Auxiliary cycle for tool or workpiece measuring cycles
L934	Auxiliary cycle for tool or workpiece measuring cycles
L935	Measuring result display selection
L936	Measurement abort
L937	Auxiliary cycle for workpiece measuring cycles
L938	Auxiliary cycle for tool or workpiece measuring cycles
L939	Auxiliary cycle for tool measuring cycles
L960	Transfer of ZO data blocks
L961	Additive input of empirical values
L962	Erase program empirical values/average values
L963	Auxiliary cycle for workpiece measuring cycle L979
L964	Auxiliary cycle for workpiece measuring cycles L973/L976
L965	Measuring plane (tool or workpiece measurement)
L966	Auxiliary program for operator guidance macro
L967	Presetting of transfer parameters
L969	Coordinate rotation
L970	Prepositioning
L971	Auxiliary cycle for tool measuring cycles
L980	Auxiliary cycle for workpiece measuring cycle L981
L988	Auxiliary cycle for workpiece measuring cycles
L989	Auxiliary cycle for workpiece measuring cycle L979



These programs **must be available**



Additional programs: Facilitate programming and operating.


### 3.1 Internal measuring cycle auxiliary programs

The "internal" auxiliary programs are called directly by the measuring cycles. They can therefore not be run when called directly by the user.

#### 3.1.1 L931 Auxiliary cycle for tool or workpiece measuring cycles

This cycle must be available in either the part program memory or in the UMS, because it is used by all measuring cycles.

#### 3.1.2 L932 Check MDC and transfer parameters \*)



This cycle checks the MDC or the transfer parameters. It is called by the measuring cycles automatically, if SDC 800 bit 0 or 800 bit 1 is set.


#### 3.1.3 L933 Auxiliary cycle for tool or workpiece measuring cycles

This cycle must be available in either the part program memory or in the UMS, because it is used by all measuring cycles.

#### 3.1.4 L934 Auxiliary cycle for tool or workpiece measuring cycles

This cycle must be available in either the part program memory or in the UMS, because it is used by all measuring cycles.


#### 3.1.5 L935 Measurement result display selection



If measurement result displays are stored in the UMS, these are displayed automatically at the end of the measuring cycle.

\*) Version 3.0 and higher

### 3.1.6 L936 Measurement abort



This cycle is required for the function "Measurement abort signal". This function provides the possibility of continuing the machining program when a cycle reset alarm occurs.

The measurement abort signal is normally initiated by the operator by pressing a key on the machine control panel.


### 3.1.7 L937 Auxiliary cycle for workpiece measuring cycles

This cycle must be available in either the part program memory or in the UMS, because it is used by all measuring cycles.

### 3.1.8 L938 Auxiliary cycle for tool or workpiece measuring cycles

This cycle must be available in either the part program memory or in the UMS, because it is used by all measuring cycles.

### 3.1.9 L939 Auxiliary cycle for tool measuring cycles



This cycle processes the PLC interface of the tool management, when MDC 7000 bit 4 or 5 is set.

## 3.2 Internal/external measuring cycle auxiliary programs


Part of the "external" cycles can also be called directly by the user.

### 3.2.1 L960 Transfer of ZO data blocks (external)

The cycle is used to transfer ZO data from the ZO memory to the MIB or R parameter and vice versa.

It is supplied with the standard cycles and described in the associated documentation.

### 3.2.2 L961 Additive input of empirical values (external) \*)



This subroutine enables a modification value to be entered in an "Empirical value memory" (SDC).


Transfer parameters for L961:      R11 = EV memory number  
   R12 = Value

**Example:** EV is to be modified by 0.002.

Procedure:

- Select MDI mode
- R11=10 R12=0.002 L961 LF    Press input key
- NC Start (without single block)
- Value of R12 is allowed for in EV memory number 10.

### 3.2.3 L962 Erase program EV/AV (external) \*)



This program serves for erasing empirical and average values (AV) in the empirical value memory area or in the average value memory area (SDC). This may become necessary, for instance, when changing the part program.

Transfer parameters for L962:      R40 = Start address  
   R41 = End address

**Example:** The empirical value memory numbers from 20 to 30 are to be erased.

Procedure:

- Select MDI mode
- R40=20 R41=30 L962 LF    Press input key
- NC Start (without single block)
- EV 20 ... 30 are erased.
- Average values 20 ... 30 are also erased if there is an average value memory.

\*) Version 3.0 and higher


### 3.2.4 L963 Auxiliary cycle for workpiece measuring cycle (external)

This cycle is called by measuring cycle L979.

It is used to calculate circle parameters ( $X_m$ ,  $Y_m$  and  $r$ ) from 3 or 4 coordinates.

It is configured in a way to allow also direct calls to be made.

Parameter definition for L963:



Output data:

$R_n$  Centrepoint abscissa  
 $R_{n+1}$  Centrepoint ordinate  
 $R_{n+2}$  Radius

Input data:

$R_m$	Number of circle points (3 or 4)
$R_{m+1}$	X1
$R_{m+2}$	Y1
$R_{m+3}$	X2
$R_{m+4}$	Y2
$R_{m+5}$	X3
$R_{m+6}$	Y3
$R_{m+7}$	X4
$R_{m+8}$	Y4

Execution time with 3 points depending on type of control up to approx. 3.5 s  
 4 points depending on type of control up to approx. 10 s

### 3.2.5 L964 Auxiliary cycle for workpiece measuring cycles (internal)

This cycle is called by cycles L973 and L976, when reference data are calibrated.


### 3.2.6 L965 Determination of measuring plane (external)

The cycle determines the axis data of the current plane and stores them internally. It must be started at least **once** on completion of installation.

Programming also becomes **necessary** when the measuring plane is changed or the function "Mirroring" has been activated or deactivated.


Transfer parameters: None

### 3.2.7 L966 Auxiliary program for operator guidance macro (OGM)




When editing parts of the measuring program via the input displays for measuring cycles, cycle L966 is cancelled when storing.

### 3.2.8 L967 Presetting of transfer parameters (internal)



### 3.2.9 L969 Auxiliary cycle for coordinate rotation (internal)

This cycle must be available in either the part program memory or in the UMS, if measurement is to be carried out with coordinate rotation.



### 3.2.10 L970 Prepositioning cycle (external)

This cycle offers the possibility of positioning the tools around the tool probe or the workpiece probe from measuring point to measuring point with active collision monitoring.

**The following parameters must be defined prior to call:**

Parameters	Description
R23 = 0 = 1	Tool measurement (G53) Workpiece measurement
R25 = ... = 0	Positioning speed Rapid traverse/reduced rapid traverse (MDC4 / MDC5)
R30	Axis number of plane
R32	Approach position referred to machine zero point (R23=0) referred to workpiece zero point (R23=1) if axis is transverse axis in the diameter enter value as diameter value

**Example of application:**

In the examples given in Section 5.6.1, the NC blocks N10, N15, N30, N35, N40, N55, N60 and N65 must be monitored.




Fig. 3.1 Z0 determination at surface

**Example: ZO determination at a workpiece with cycle L978 in the X and Y axes without L970**

Probe length (Z axis) in tool offset memory D99 (value 50)

```

%MPF  9782
N5     G54 T200                               T No. probe; ZO selection
N10    G00 G90 X-20 Y25                       Position probe to face the measuring surface in X/Y
N15    Z10 D99                                 Position probe in Z TO selection
N20    R10=1 R11=10 R22=1 R23=0              Define parameters for measuring cycle
        R25=0 R27=1 R28=2 R30=1
        R32=0 R36=3
N25    L978                                    Cycle call for ZO determination in X axis
N30    G00 X-20                                Retraction in X axis
N35    Y-20                                    Positioning in Y axis
N40    X50                                     Positioning in X axis
N45    R11=11 R30=2                            Define parameters for measuring cycle
N50    L978                                    ZO determination in Y axis
N55    G00 Y-20                                Retraction in Y axis
N60    Z100                                    Retraction in Z axis
N65    X-40 Y80                                Retraction in X/Y
:
:
Machining centre program
:
N900   M30
    
```

**Example: ZO determination at a workpiece with cycle L978 in the X and Y axes with L970**

Probe length (Z axis) in the tool offset memory D99 (value 50)

```

%MPF  9783
N5     G54 T200                               T No. probe; ZO selection
N10    R23=1 R25=0 R30 =1 R32=-20 L970       Position probe to face
        R30=2 R32=25 L970                    the measuring surface in X/Y
N15    R30=3 R32=10 D99 L970                 Position probe in Z
                                                TO selection
N20    R10=1 R11=10 R22=1 R23=0              Define parameters for measuring cycle
        R25=0 R27=1 R28=2 R30=1
        R32=0 R36=3
N25    L978                                    Cycle call for ZO determination in
                                                X axis
N30    R23=1 R30 =1 R32=-20 L970             Retraction in X axis
N35    R30=2 R32=-20 L970                    Positioning in Y axis
N40    R30=1 R32=50 L970                     Positioning in X axis
N45    R11=11 R23=0 R30=2 R32=0              Define parameters for measuring cycle
N50    L978                                    ZO determination in Y axis
N55    R23=1 R30 =2 R32=-20 L970             Retraction in Y axis
N60    R30=3 R32=100 L970                    Retraction in Z axis
N65    R30=1 R32=-40 L970                    Retraction in X/Y
        R30=2 R32=80 L970
:
:
Machining centre program
:
    
```


### 3.2.11 L971 Auxiliary cycle for tool measuring cycles (internal)

This cycle must be available in the part program memory or in the UMS for tool measurement.

### 3.2.12 L980 Auxiliary cycle for tool measuring cycle L981 (internal)

This cycle must be available in the part program memory or in the UMS when using measuring cycle L981 (searching for a hole/slot).

### 3.2.13 L988 Auxiliary cycle for workpiece measuring cycles (internal/external)



Measurement results obtained by the use of workpiece measuring cycles can be logged using the cycle L988 and the subfunction FB package "Logging of measurement results".


### 3.2.14 L989 Auxiliary cycle for workpiece measuring cycle L979 \*)

This cycle must be available either in the part program memory or in the UMS when using the workpiece measuring cycle L979.

END OF SECTION


\*) Version 3.0 and higher

## 4 Measuring Cycles for Turning Machines



*The possible scope of measurement depends on the machine configuration and can also be determined partly via MDC.*

*(See machine tool manufacturer's specifications)*



Cycle	Function		
L931	Auxiliary cycle for tool or workpiece measuring cycles	See Section 3 for auxiliary cycles	
L932	Check MDC and transfer parameters		
L933	Auxiliary cycle for tool or workpiece measuring cycles		
L934	Auxiliary cycle for tool or workpiece measuring cycles		
L935	Measurement result display selection		
L936	Measurement abort		
L937	Auxiliary cycle for workpiece measuring cycles		
L938	Auxiliary cycle for tool or workpiece measuring cycles		
L939	Auxiliary cycle for tool measuring cycles		
L961	Additive input of empirical values		
L962	Erase program EV/AV		
L964	Auxiliary cycle for tool measuring cycle L973		
L965	Measuring plane (tool or workpiece measurement)		
L966	Auxiliary program for operator guidance macro		
L967	Presetting of transfer parameters		
L970	Prepositioning		
L971	Auxiliary cycle for tool measurement		Tool measuring cycle
L972	Tool measurement		
L973	Calibrate workpiece probe		Workpiece measuring cycles
L974	Workpiece measurement		
L982	Tool measurement		
L988	Auxiliary cycle for workpiece measuring cycles		

These programs **must be available**.

Additional programs: facilitate programming and operating.


## 4.1 L972/L982 Tool measurement

Tool cycles with the following functions are available for tool measurement:

- L972 – Calibrate tool probe
  - Measure tool of L1 or L2 with tool types 1 ... 10, 26, 28, 31 ... 38 with one tool offset number
  - Automatic tool measurement of L1 and/or L2 with tool types 1 ... 10, 26, 28, 31 ... 38 with one tool offset number
- L982 – All functions of L972
  - Automatic tool measurement of L1 and/or L2 and R with tool types 28, 37, 38 with one or two tool offset numbers.  
 Selection: Length and/or radius compensation

Cycle L982 needs approx. 45 % more memory space than L972 and its running time is approx. 20 % slower.

The 3rd and 4th decimal place of R23 are additionally used for coding the measurement variant of L982.



With Version 3.2 and higher cycle L972 is available in two versions:

- L972-1 – Calibrate tool probe
  - Tool measurement of L1 or L2 with tool types 1 ... 8, PF-PF (basic function) **also automatically**
- L972-2 – Calibrate tool probe
  - Tool measurement of L1 or L2 with tool types 1 ... 10
  - also PF-SF; SF-SF for tool types 1 ... 8 **also automatically**
  - mirrored measurement
  - SF-SF for type 9 only

Cycle L982 is also available in two versions with Version 3.2 and higher:





- L982-1 – Tool measurement type 30-39 (basic functions)
- L982-2 – Tool measurement type 20-39 and mirrored measuring.

The version that you require must be loaded in the part program memory and/or linked into the user memory submodule.

**Description of tool types 26, 28, 31 ... 38****Tool types 31 ... 34, R23=00xx**

With tool types 31 ... 34, the lengths L1 and/or L2 are measured at the selected corner point of the milling cutter and compensated in the tool offset memory.

Axial tools

Tool type	Axial tool form	Tool geometry dimensions	Dimensions compensated
31		L1, L2, R=0	L1, L2
32		L1, L2, R=0	L1, L2
33		L1, L2, R=0	L1, L2
34		L1, L2, R=0	L1, L2




Radial tools

Tool type	Radial tool form	Tool geometry dimensions	Dimensions compensated
31		<p>L1, L2, R=0</p>	<p>L1, L2</p>
32		<p>L1, L2, R=0</p>	<p>L1, L2</p>
33		<p>L1, L2, R=0</p>	<p>L1, L2</p>
34		<p>L1, L2, R=0</p>	<p>L1, L2</p>




With tool types 35 and 37 only the length L2 and with tool types 26, 28, 36 and 38 only the length L1 is measured.

You select together with the cutter radius whether the measuring point is located on the tool centre (R=0) or displaced from the tool centre by the value R.

Axial tools

Tool type	Axial tool form	Tool geometry dimensions	Dimensions compensated
35		$L1=0$ $L2, R$	L2
37		$L1=0$ $L2,$ $R=0$	L2
37		$L1=0$ $L2, R$	L2

Radial tools

Tool type	Radial tool form	Tool geometry dimensions	Dimensions compensated
26 36		$L1, L2=0, R$ $L1, L2, R$	$L1$ $L1$
28 38		$L1, L2=0, R=0$ $L1, L2, R=0$	$L1$ $L1$
28 38		$L1, L2=0, R$ $L1, L2, R$	$L1$ $L1$

**Tool types 28, 37 and 38, R23=x1x2**

With tool type 28, L1 and  $\underline{R}$  are determined.

With tool types 37 and 38, L1, L2 and  $\underline{R}$  are determined.

The first measuring point is measured in the abscissa and ordinate. The tool is then turned through 180 degrees and the same cutting edge is measured again in the two axial directions.

The average values of the two measurements provide the L1 and L2 dimensions. The cutter radius is determined from half the dimensional difference between measuring point 1 and measuring point 2 in the ordinate.

**Axial tool**

Tool type	Axial tool form	Tool geometry dimensions	Dimension compensations
37		$L1=0$ $L2, R$	$L1, L2, R$

Calculation of tool geometry:

$$L1=(L1,1+L1,2)/2$$

$$L2=(L2,1+L2,2)/2$$

$$R=ABS((L1,1 - L1,2)/2)$$

**Radial tool**

Tool type	Axial tool form	Tool geometry dimensions	Dimension compensations
28 38		$L1, L2=0, R$ $L1, L2, R$	$L1, R$ $L1, L2, R$

Calculation of tool geometry:

$$L1=(L1,1+L1,2)/2$$

$$L2=(L2,1+L2,2)/2$$

$$R=ABS((L2,1 - L2,2)/2)$$

**Tool types 28, 37 and 38, R23=x2x2**

Using this variant, T slot cutters with two tool offset numbers can be measured.

With tool type 28, L1 and R of both tool offset numbers are determined.

With tool types 37 and 38, L1, L2 and R are determined.

Two consecutive offset numbers must be used. The 1st offset number is used for the greater tool length. The 2nd offset number (1st offset number+1) is called automatically by the cycle. In the tool geometry memory, the relevant tool dimensions L1, L2 and R must be stored in the two offset numbers. When tool management is used for the SINUMERIK 850 or 840/880, the 1st offset number must also be loaded first.

First, the 1st measuring point is measured in the absessor and ordinate. The tool is then swivelled by 180 degrees and the 2nd measuring point is measured at the same cutting edge in the two axial directions.

Axial tool

Tool type	Axial tool form	Tool geometry dimensions	Dimension compensation
37		Compensation 1 L1=0, L2, R  Compensation 2 L1=0, L2, R	Compensation 1 L1, L2, R  Compensation 2 L1, L2, R

The average value of the tool measurements in the ordinate provides tool dimension L1 for compensation 1 and 2.

Tool dimension L2 is measured separately for each compensation and stored. The cutter radius is determined from half the dimensional difference between measuring point 1 and measuring point 2 in the ordinate.

Calculation of tool geometry:

1st offset number

$$L1=(L1,1+L1,2)/2$$

$$L2=L2 \text{ (compensation 1)}$$

$$R=ABS((L1,1 - L1,2)/2)$$

2nd offset number

$$L1=(L1,1+L1,2)/2$$

$$L2=L2 \text{ (compensation 2)}$$

$$R=ABS((L1,1 - L1,2)/2)$$

## Radial tools

Tool type	Radial tool form	Tool geometry dimensions	Dimension compensations
28 38		Compensation 1	Compensation 1
		L1, L2=0,R	L1, R
		L1, L2, R	L1, L2, R
		Compensation 2	Compensation 2
L1, L2=0, R	L1, R		
L1, L2, R	L1, L2, R		

The tool dimension L1 is measured separately for each compensation and stored. The average value of the two measurements in the abscissa provides tool dimension L2 for the 1st and 2nd compensation.

The cutter radius is determined from half the dimensional difference between measuring point 1 and measuring point 2.

Calculation of tool geometry:

1st offset number

$L1=L1(\text{compensation 1})$

$L2=(L2,1+L2,2) / 2$

$R=ABS((L2,1 - L2,2) / 2)$

2nd offset number

$L1=L1(\text{compensation 2})$

$L2=(L2,1+L2,2) / 2$

$R=ABS((L2,1 - L2,2) / 2)$

### R26 start angle position of driven tools.

If a cutter is to be measured at off-centre measuring points, the tool must be moved to a defined angular position to the measuring cycle. To achieve this, the tool must be preset to the correct position.

The starting angle is specified with R26.

### R13 angular offset of driven tools when using reversal measurement.

When using reversal measurement, the tool is swivelled automatically by 180 degrees for the 2nd measuring point.

If measurement of the 2nd measuring point is not possible in this angular position, for example with helical-tooth T slot cutters, the angular position of the 2nd measuring point can be displaced additionally with parameter R13.

### 4.1.1 L972/L982 Calibrating the tool probe

#### Function and application

The cycle determines the current distances between machine zero point and probe trigger point with the aid of the calibrating tool and loads them automatically into the MDC area. Calculations are performed **without** empirical and average values.

The calibrating tool is located away from the measuring surface by R28 on completion of calibration.

Tool probes mirror-imaged in the ordinate or abscissa can also be calibrated with this cycle.

Mirror-imaging offers the advantage that probes can be fitted outside the machine work area. When calibrating, the calibration tool must be positioned in the turret rotated through 180 degrees under PLC control.

#### Preconditions:

- The side surfaces of the probe cube must be aligned parallel to the machining axes ordinate and abscissa.
- The calibrating axis must be programmed with **G53** and the **TO** memory number.
- Start position as shown in Fig. 4.1. The measuring cycle calculates the start position automatically.




Fig. 4.1 Start position when calibrating the tool probe

The calibrating tool must be prepositioned to these positions before the calibrating cycle is called (start position).

The following parameters must be defined prior to call:

Parameters	Description
R22	Tool probe No. (see Section 2.6)
R23 = 0	Calibrate tool probe
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30 = 1...3	Number of measuring axis (see Section 2.11)
R33	Zero offset range
R36	Safe area

See Section 8.2 for result display parameters.




Fig. 4.2 Calibrating the tool probe

The tool probe is stationary but supplies switching signal. The calibrating tool is positioned with the turret.

**Recommendation:** Create a machine-specific calibrating subroutine using cycle L972/L982.

This program can be used when required either for each tool measurement using the main program or via MDI (once a day).

**Example: Machine-specific calibration subroutine (see Fig. 4.2 for more details)**

On turning machines, the calibration tool is treated like tool type 3 and must be entered as such in the TOA memory.

Values in the TOA memory D9:

Tool type	3
L1 geometry	10
L2 geometry	40
R radius	5

The trigger points are always stored as radius values, even for a transverse axis.

Values in MDC:	MDC 1020=50	Minus direction of abscissa
	MDC 1021=20	Plus direction of abscissa
	MDC 1022=70	Minus direction of ordinate
	MDC 1023=40	Plus direction of ordinate

<code>%SPF 10</code>	
<code>N05 G00 G53 G94 Z300 G18</code>	Approach random change position
<code>N10 G53 X240 T7 D9</code>	Random change position with calibrating tool
<code>N20 M71</code>	Tool probe (e.g. swing-in)
<code>N25 R22=1 R23=0 R25=0 R27=1 R28=1</code>	Define parameters for calibration cycle
<code>R30=1 R33=0,004 R36=2</code>	
<code>N30 L972</code>	Calibrate in minus X direction
<code>N35 G00 G53 Z52 T7 D9</code>	Approach new start position with G53
<code>N40 R30=2 L972</code>	Calibrate in plus Z direction
<code>N45 G00 G53 X94</code>	Approach new start position with G53
<code>N50 R30=1 L972 T7 D9</code>	Calibrate in plus X direction
<code>N55 G00 G53 Z93</code>	Approach new start position with G53
<code>N60 R30=2 L972 T7 D9</code>	Calibrate in minus Z direction
<code>N65 G00 G53 Z300</code>	Approach random change position
<code>N70 G53 X240</code>	Approach random change position
<code>N75 M17</code>	

## 4.1.2 L972/L982 Measure tool

### Function and application

The cycle calculates the new tool length and checks whether the difference, after any necessary compensation by an empirical value, exceeds an amount defined in R36/R37 as compared with the old length. If this is not the case, the new tool length is loaded into the TOA memory under geometry, otherwise an alarm is triggered.

Compensation is also performed when the deviation exceeds a lower limit specified in R33. The old tool length is not modified if this is not the case. Such action serves to suppress random measuring errors.

The tools can also be measured mirror-imaged in the X or Z axis with this cycle (see also 4.1.1).

Averaging is not performed.

On completion of the cycle, the tool tip is now in a position facing the measuring surface by the amount R28.

### Preconditions:

- The tool probe must have been calibrated
- Tool geometry data have been input in the TOA memory with tool nose radius and type.

### Example:

	T No.	Type	Geometry			Wear		Base (add. TO)	
	P0	P1	P2	P3	P4	P5	P6	P8	P9
D20	3	3	50.	25	1.	0	0	0	0

- The measuring axis must be programmed with G53 (deselect zero offset) and the relevant tool offset number.
- Start position as shown in Fig. 4.3. The cycle calculates the approach position automatically.
- MD 5007.6 Tool wear is not active  
 = 0 Tool wear active  
 The wear memory is cleared by the cycle, the derived offset value is added to geometry L1 or L2.  
 = 1 Tool wear not active  
 The wear is not deleted.
- If tool management is active (MDC 7000.4 = 1, 7000.5 = 1), the calculated difference is added to the TOA memory the first time the tool is used and the wear value is deleted, otherwise the calculated difference is added to the wear memory if it is active.




Fig. 4.3 Start positions for tool measurement

The tool must be moved to these positions before the measuring cycle is called.

The following parameters must be defined prior to call:

Parameters	Description
R11 = 0 > 0	Without empirical value Empirical value memory number (see Section 2.3)
R22	Tool probe No.
R23 = 1	Measure tool
R25 R25=0	Variable measuring speed in mm/min Standard cycle value
R26	Starting angle (with tool types 26)
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R36	Safe area
R37	Dimensional deviation check

See Section 10.2 for result display parameters.



**Example: Calibrate tool probe and then measure a tool T3 as shown in Fig. 4.5**

```

%MPF 9721
:
:
N3 G53 X595 G18
N4 G53 Z250 D9 Call calibrating tool

-----
N5 R22=1 R23=0 R25=0 R27=2 R28=1
   R30=2 R33=0.004 R36=1 Parameter definition for L972
N6 L972 1st call calibration cycle X axis
N7 G53 G0 Z200
N8 R30=1 Parameter definition
N9 L972 2nd call calibration cycle Z axis
-----

L10

N10 G00 G53 Z520
N11 G53 X575
N12 T3 Call the tool to be measured
N13 Z250 D20
N14 R11=0 R22=1 R23=1 R25=0 R27=1 R28=1
   R30=2 R33=0.004 R36=1 R37=0.8 Parameter definition
N15 L972 Measure tool in minus X direction
N16 G00 Z400
N17 R30=1 Parameter definition
N19 L972 Measure tool in minus Z direction

N20 G00 G53 Z250 D0
N21 G53 X560
M30
    
```

Subroutine L10 can be used instead of blocks N3 - N9 (machine-specific calibration program, see Section 4.1.1).

For further simplification, the tool measurements can be performed with the measurement variant "Automatic tool measurement".

This measurement variant is described in the following Section 4.1.3.

### 4.1.3 L972/L982 Automatic tool measurement

#### Function and application

The cycle positions the tool to the tool probe depending on the tool type used. To begin with, the "Tool change position" F, stored in the MDC or programmed under R18/19, is approached. The tool is then measured in the abscissa and subsequently in the ordinate (see Fig. 4.7).

When empirical values are used (R11 = 0), the specified empirical value memory number R11 = m is used for the abscissa (see Section 2.1).

The cycle defines R11 = m+1 for the ordinate. Two consecutive memories are used.

R11<sub>max-1</sub> is specified for the constant when tool types 1-4 are used.

R11 = m+2 must be specified for the next tool.

Tool types 0, 5, 6, 7, 8, 10, 26, 28, 35 - 38 are measured in one axis only, if R23 = 00x2.

Tool type 9 cannot be measured with this variant.

The tool lengths are calculated according to "PN" or "SN", i.e. referred to the tool tip or tool nose radius centre, depending on the definition of R23.

"N" is located at the position stored in the MDC on completion of measurement and between the measuring points 1 and 2 (with R23 = 102) if R18/19 has been defined with the value 0. In the case of R18/19 = 0, "N" is positioned each time at a distance corresponding to the amount of R18/19 away from the tool probe.

#### Preconditions :

- The MDC (tool change position) must have been loaded.  
With these values, a position "**Tool change position**" **N** must be defined at which all tools which can possibly be used on this machine can be changed without collision at the tool probe.
- It must be possible to approach the change position without collision.
- The measuring axis must be programmed **with G53** and the associated **TO memory No.**

**The following parameters must be defined prior to call:**

Parameters	Description
R11 = 0 > 0	Without empirical value Empirical value memory number m
R13	Angular offset (with R23 102)
R18 = 0 0	Change position X axis (from MDC) (with reference to machine zero) Variable change position X axis (with reference to trigger points tool probe)
R19 = 0 0	Change position Z axis (from MDC) (with reference to machine zero) Variable change position Z axis (with reference to trigger points tool probe)
R22	Tool probe No.
R23	Measurement variant xxx 02 } see Section 2.7.1 xxx 12 } xxx 22 }
R25 R25=0	Variable measuring speed in mm/min Standard cycle value
R26	Starting angle (with tool type 26)
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R33	Zero offset range
R36	Safe area


**Example: Tool measuring program**

Fig. 4.6 Tool measurement towards spindle tool type 1

```
%MPF 9722
```

```
N5 L10 G18
```

```
N10 T9 D1
```

```
N15 R11=11 R18=0 R19=0 R22=1 R23=2
```

```
R25=0 R27=1 R28=1
```

```
R33=0.002 R36=1 R37=0.8
```

```
N20 L972
```

```
N25 T11
```

```
N30 R11=13 L972
```

```
N90 M30
```

Probe is calibrated (see Section 4.1.1)

Tool 9

R11=11: EV mem. no. 11 Z axis

EV mem. no. 12 X axis

R18=0: Change position X axis (MDC)

R19=0: Change position Z axis (MDC)

L972: Tool T9 is measured in the Z and X axes

Tool 11

R11=13: EV mem. no. 13 Z axis

EV mem. no. 14 X axis

L972: Tool T11 is measured in the Z and X axes

## 4.2 L973 Calibrating the workpiece probe

This cycle is used to calibrate the workpiece probe. Selection is made by definition of R23.

If double probes are used, L973 must always be called with the first of the two successive D numbers.

The measuring variant is selected by defining R23:

Definition of R23	Calibrate workpiece probe
R23 = xxx02 R23 = xxx22	In any hole (plane) On any cube/surface (plane)

### Probe types that can be used: (see Section 1.3)

- For turning machines, probe type 3, 5 - 8 must be entered in the TOA memory
- Multidirectional probe
- Bidirectional probe

## 4.2.1 L973 Calibrating on any surface

### Function and application

This measuring cycle can be used to calibrate the probe at any surface, e.g. the workpiece. As from Version 3.5 the function "Mirroring" can also be active in the axes concerned.

After calibration has been completed, the probe is at a distance "a" facing the calibration surface.

### Preconditions :

- The probe is called with tool offset and **without** G53 to face the calibration surface.
- When calibrating in a hole (groove/slot) the probe must be prepositioned to the centre point.
- When calibrating beneath the turning centre in plus-X direction or left of the workpiece zero point W in plus-Z direction, the setpoint (R32) must be specified as a **negative** value.
- When calibrating in a random hole (groove/slot) the probe must be prepositioned to the centre point.

The following parameters must be defined prior to call:

Parameters	Description
R22	Workpiece probe number
R23 = 22	Calibrating the workpiece probe on any surface (see Section 2.7.2)
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30 = 1...3	Number of measuring axis
R31 = 0 R31 = 1	Positive axis direction Negative axis direction
R32	Setpoint referred to workpiece zero point, for transverse axis in the diameter. When calibrating beneath the turning centre in plus-X direction or left of the workpiece zero point in plus-Z direction, the setpoint must be specified as a <b>negative</b> value. Where the measurement variant is any hole, R32 means diameter of hole, the approach position is the centre point.
R33	Zero offset range
R36	Safe area



## 4.3 L974 Workpiece measurement

### Function and application

The measuring cycle ascertains the actual value of the workpiece in the selected measuring axis with respect to the workpiece zero point and the set/actual difference. As from Version 3.5 the function "Mirroring" can also be active in the axes concerned.


An empirical value stored in the SDC is then allowed for with the correct sign. The average value is formed over several parts and the tolerance bands are checked as described in Section 1.7.

The cycle corrects automatically the zero offset memory/compensation memory selected via R10 in the measuring axis (define tool type).

Measurements can be performed in all axial directions without restriction (inside/outside diameters, holes, slots).

Selection of the measurement variant is carried out via definition of R23:

R23 = 0	1-point measurement ZO determination
R23 = 21	1-point measurement
R23 = 22	1-point measurement with reversal
R23 = 23 R23 = 24	2-point measurement on diameter; inside without protection zone 2-point measurement on diameter; inside with protection zone
R23 = 25	Multi-point measurement on circumference
R23 = 26	Multi-point measurement on cylinder



### Start position

- 1: - X Outside diameter
- 2: +X Inside diameter
- 3: +X Outside diameter  
(Calibrating and measuring beneath turning centre:  
Set value negative)
- 4: - Z Measure length
- 5: +Z Measure length:  
(left of workpiece zero point in +Z direction:  
Set value negative)

Fig. 4.8 Start positions

See Section 10.2 for result display parameters.

### 4.3.1 L974 1-point measurement ZO determination

#### Function and application

The measuring cycle ascertains the actual value of a blank in the selected measurement axis in relation to the workpiece zero point.

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

The probe is located at a distance "a" facing the measuring surface.

No automatic entry is carried out or additive entry of the difference of the measuring axis is made in the specified ZO memory, depending on the definition of R10.

#### Preconditions:

- The workpiece must be positioned with M19 prior to cycle call when necessary.
- The probe must have been calibrated in the direction of measurement.
- The probe must be positioned with tool offset and without G53 facing the surface to be measured (Fig. 4.9).
- The maximum diameter that can be measured depends on the traversing range of the turret slide in +X.

Outside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} + 2a$$

Inside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} - 2a$$

The following parameters must be defined prior to call:

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO entry Automatic ZO entry in ZO G54...G57 Automatic ZO entry in ZO G58
R11 = 0 > 0	Without empirical value Empirical value memory number (see Section 2.3)
R22	Probe number (see Section 2.6)
R23 = 0	ZO determination
R25 R25=0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30 = 1...3	Number of measuring axis (see Section 2.12)
R32	Set value referred to the workpiece zero point
R36	Safe area



## 4.3.2 L974 1-point measurement

### Function and application

The measuring cycle ascertains the actual value of the workpiece in the selected measuring axis in relation to the workpiece zero point and the set/actual difference.

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

In addition, the average value is formed over several parts and the tolerance bands are checked (Section 1.7.1).

The probe is located at a distance "a" facing the measuring surface on completion of measurement.

No automatic compensation or a length compensation is carried out, depending on the definition of R10.

### Preconditions:

- The workpiece must be positioned with M19 prior to cycle call when necessary.
- The probe must have been calibrated in the direction of measurement.
- The probe must be positioned with tool offset and without G53 to face the surface to be measured (Fig. 4.9).
- The maximum diameter that can be measured depends on the traversing range of the turret slide in +X.

Outside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} + 2a$$

Inside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} - 2a$$




Fig. 4.10 1-point measurement on outside diameter with CALIBRATE




Fig. 4.11 1-point measurement on inside diameter with CALIBRATE

**The following parameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory No./average value memory No. (see Section 2.3)
R22	Probe number (see Section 2.6)
R23 = 21	1-point measurement
R25 R25=0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1...3)
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R34	Average value compensation
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value (according to drawing)

See Section 10.2 for result display parameters.


**Example: Calibrate workpiece probe, 1-point measurement on outside and inside diameter**

Fig. 4.12 1-point measurement on outside and inside diameter

<code>%MPF</code>	<code>9741</code>	
<code>N5</code>	<code>T1 G18</code>	Call T No. with TO No.
<code>N10</code>	<code>G54 G0 Z30 D31 X</code>	Preposition probe
<code>N15</code>	<code>R10=8 R11=13 R22=1 R23=21 R25=0</code> <code>R27=1 R28=1 R29=2 R30=2</code> <code>R33=0.002 R34=0.005 R36=0.5 R37=0.04</code> <code>R40=0 R41=-0.01 R42=45</code>	Define parameters for measurement
<code>N25</code>	<code>L974</code>	Measure outside diameter
<code>N30</code>	<code>G0 G54 Z60</code>	Position probe to face MP2
<code>N35</code>	<code>X0</code>	
<code>N40</code>	<code>R10=9 R11=14 R22=1 R23=21 R25=0</code> <code>R27=1 R28=1 R29=2 R30=2</code> <code>R33=0.002 R34=0.005 R36=0.5 R37=0.04</code> <code>R40=0.015 R41=0 R42=35</code>	Define parameters for measurement
<code>N50</code>	<code>L974</code>	Measure inside diameter
<code>N55</code>	<code>G0 G53 Z110 D0</code>	Retraction
<code>N60</code>	<code>G53 X90</code>	
<code>N65</code>	<code>M30</code>	

### 4.3.3 L974 1-point measurement with reversal

#### Function and application

The measuring cycle ascertains the actual value of the workpiece in the selected measuring axis in relation to the workpiece zero point and the set/actual difference.

The workpiece is positioned to the value of R26 (start angle) prior to the first measurement using M19. The second measurement is preceded by a reversal through 180°. The measurement with reversal compensates any possibly existing eccentricity of the workpiece caused by a chuck with three jaws. The actual value and the set/actual difference are determined on the basis of the two measurements.

An empirical value stored in SDC is subsequently allowed for with the correct sign.

In addition, averaging is performed over several parts and the tolerance bands are checked (Section 1.7.1).

The probe is located at a distance "a" facing the measuring surface on completion of measurement.

No automatic compensation or a length compensation is carried out, depending on the definition of R10.

#### Preconditions :

- The probe must have been calibrated in the direction of measurement.
- The probe must be positioned with **tool offset** and **G53** to face the surface to be measured (Fig. 4.9).
- The maximum diameter that can be measured depends on the traversing range of the turret slide in +X.
- M19 oriented spindle stop with axis movement must be defined.

Outside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} + 2a$$

Inside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} - 2a$$




Fig. 4.13 1-point measurement with reversal on outside diameter with CALIBRATE




Fig. 4.14 1-point measurement with reversal on inside diameter with CALIBRATE

**The following parameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory No./average value memory No. (see Section 2.3)
R22	Probe number (see Section 2.6)
R23 = 22	1-point measurement with reversal
R25 R25=0	Variable measuring speed in mm/min Standard cycle value
R26= 0-359.5	Start angle (only positive)
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1...3)
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R34	Average value compensation
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value (according to drawing)

See Section 10.2 for result display parameters.


**Example: 1-point measurement with reversal on outside diameter (probe calibrated)**

Fig. 4.15 1-point measurement with reversal on outside diameter

```

%MPF  9742
N1    T8 G18
N5    G54 G00 Z30 D30
N10   R10=10 R11=20 R22=1 R23=22 R25=0
      R26=0 R27=1 R28=3 R29=1
      R30=2 R33=0 R34=0.2 R36=1
      R37=0.04 R40=0 R41=-0.01 R42=45
N20   L974
N25   G00 G53 Z110 D0
N30   G53 X90
N35   M30

```

Parameters for measuring cycle

Call for measuring cycle

Retraction

#### 4.3.4 L974 2-point measurement on diameter

The measuring cycle ascertains the actual value of the workpiece in relation to the workpiece zero point and the set/actual difference.

The cycle measures the diameter by measuring the upper (1st measurement) and the lower (2nd measurement) point without turning the part. In this case, the probe need not be calibrated anymore. Measuring must not be carried out in any other order as otherwise the protection zone will not have any effect!

A protection zone must be specified with R18 and R19 because the cycle positions automatically with G00 from the 1st to the 2nd measuring point. A negative setpoint is not possible.

If double sensors are used with 2D numbers, the protection zone always refers to the active D number. Therefore the protection zone dimensions required in the construction along the measuring axis must be increased by the amount  $2r$  (outside distance between the 2 probe balls).

The maximum diameter that can be measured depends on the traversing range of the turret slide in negative direction and on the geometry dimension of the probe in X.

The actual value and the set/actual difference are determined on the basis of the two measurements.

An empirical value stored in SDC is subsequently allowed for with the correct sign.

In addition, averaging is performed over several parts and the tolerance bands are checked (Section 1.7.1).



The probe is located outside the protection zone "X" and "Z" on completion of measurement.

No automatic compensation or a length compensation is carried out, depending on the definition of R10.

##### Preconditions:

- The workpiece must be positioned with M19 prior to cycle call when necessary.
- The probe must be positioned with **tool offset** and **G53** to face the surface to be measured (Fig. 4.9).

If double sensors are used with 2D numbers, the protection zone always refers to the active D number. Therefore the protection zone dimensions required in the construction along the measuring axis must be increased by the amount  $2r$  (outside distance between the 2 probe balls).

Fig. 4.16 2-point measurement on outside diameter **without CALIBRATE**Fig. 4.17 2-point measurement on inside diameter **without CALIBRATE**

**The following diameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory No./average value memory No. (see Section 2.3)
R18	Protection zone around workpiece ordinate (radius)
R19	Protection zone around workpiece abscissa
R22	Probe number (see Section 2.6)
R23 = 23 = 24	2-point measurement on diameter (for outside measurement with R18/R19; for inside measurement without R18/R19) 2-point measurement on diameter (for inside measurement only: with R18/R19)
R25 R25=0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1...3)
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R34	Average value compensation
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value (according to drawing)

See Section 10.2 for result display parameters


**Example: 2-point measurement outside and inside**

Fig. 4.18 Workpiece measurement, 2-point measurement outside and inside

<b>%MPF</b>	<b>9743</b>	
<b>N5</b>	<b>T1 G18</b>	Call probe
<b>N10</b>	<b>G00 G54 Z30 D31 X60</b>	ZO selection, position probe to face MP1
<b>N15</b>	<b>R10=3 R11=3 R18=30 R19=55 R22=1 R23=23 R25=0 R27=1 R28=1 R29=3 R30=2</b>	Define parameters for measurement
	<b>R33=0.002 R34=0.005 R36=0.5 R37=0.04 R40=0 R41=-0.01 R42=45</b>	
<b>N25</b>	<b>L974</b>	Measure MP1
<b>N30</b>	<b>G00 Z35</b>	Position probe to face MP2
<b>N35</b>	<b>X-5</b>	
<b>N37</b>	<b>Z30</b>	
<b>N40</b>	<b>R10=4 R11=4 R22=1 R23=23 R25=0 R27=1 R28=1 R29=3 R30=2 R33=0.002 R34=0.005 R36=0.5 R37=0.04 R40=0.015 R41=0 R42=35</b>	Define parameters for measurement
<b>N50</b>	<b>L974</b>	Measure MP2
<b>N55</b>	<b>G53 G00 Z110 T0</b>	
<b>N60</b>	<b>G53 X90</b>	
<b>N65</b>	<b>M30</b>	

## 4.3.5 L974 Multi-point measurement on circumference

### Function and application

The measuring cycle ascertains the actual value of the workpiece in relation to the workpiece zero point and the set/actual difference.

The number of measurements and the indexing angle (=start angle) are determined on the circumference via 2 R parameters.

The actual value and the set/actual difference are determined on the basis of the arithmetic mean of the measuring point.

An empirical value stored in SDC is subsequently allowed for with the correct sign.

In addition, averaging is carried out over several parts and the tolerance bands are checked (Section 1.7.1).

The probe is located at a distance "a" facing the last measuring point on completion of measurement.

No automatic compensation or a length compensation is carried out, depending on the definition of R10.

### Preconditions:

- The probe must have been calibrated in the direction of measurement.
- The probe must be positioned with **tool offset** and **G53** to face the surface to be measured (Fig. 4.9).
- The maximum diameter that can be measured depends on the traversing range of the turret slide in +X.

Outside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} + 2a$$

Inside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} - 2a$$

The following parameters must be defined prior to call:

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory No./mean value memory No. (see Section 2.3)
R22	Probe number (see Section 2.6)
R23 = 25	Multi-point measurement on circumference
R24	Number of measuring points on circumference
R25 R25=0	Variable measuring speed in mm/min Standard cycle value
R26= 0-359.5	Indexing angle = Start angle (only positive)
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1...3)
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R34	Average value compensation
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value (according to drawing) * The set value must be specified as a <b>negative</b> value when measuring below the turning centre in plus X direction.

See Section 10.2 for result display parameters.

**Example: Multi-point measurement on circumference (probe calibrated)**




Fig. 4.19 Multi-point measurement on circumference (outside diameter)

<code>%MPF</code>	<code>9744</code>	
<code>N1</code>	<code>T8 G18</code>	Select probe
<code>N5</code>	<code>G00 G54 Z25 D30</code>	Approach start position
<code>N10</code>	<code>X70</code>	
<code>N15</code>	<code>R10=10 R11=20 R22=1 R23=25 R24=6</code>	Parameters for measuring cycle
	<code>R25=0 R26=60 R27=1 R28=3</code>	
	<code>R29=1 R30=2 R33=0 R34=0.2</code>	
	<code>R36=1 R37=0.06 R40=0.03 R41=0.03</code>	
	<code>R42=60</code>	
<code>N25</code>	<code>L974</code>	Call for measuring cycle
<code>N30</code>	<code>G00 G53 Z110</code>	Approach reference point
<code>N35</code>	<code>X160</code>	
<code>N40</code>	<code>M30</code>	

### 4.3.6 L974 Multi-point measurement on cylinder

#### Function and application

The measuring cycle ascertains the actual value of the workpiece in relation to the workpiece zero point and the set/actual difference.

The number of measurements and the offset on the cylinder are determined via 2 R parameters.

The actual value and the set/actual difference are determined on the basis of the arithmetic mean of the measuring points.

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

In addition, averaging is carried out over several parts and the tolerance bands are checked (Section 1.7.1).

The probe is located at a distance "a" facing the last measuring point on completion of measurement.

No automatic compensation or a length compensation is carried out, depending on the definition of R10.

#### Preconditions :

- The probe must have been calibrated in the direction of measurement.
- The probe must be positioned with **tool offset** and **without G53** to face the surface to be measured (Fig. 4.9).
- The maximum diameter that can be measured depends on the traversing range of the turret slide in +X.

Outside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} + 2a$$

Inside diameter:

$$D_{\max} = 2 \times (X_{MF\max} - X_F) - \text{ball} - 2a$$




Fig. 4.20 Multi-point measurement on cylinder (outside diameter)

**The following parameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory No./average value memory No. (see Section 2.3)
R19	Offset of abscissa (incremental)
R22	Probe number (see Section 2.6)
R23 = 26	Multi-point measurement on cylinder
R24	Number of measuring points on cylinder
R25 R25=0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1...3)
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R34	Average value compensation
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value (according to drawing)

See Section 10.2 for result display parameters.



## 4.4 Examples of application for workpiece measurement (L973, L974)

The workpiece shown below is to be measured with the aid of a probe.




Fig. 4.22 Workpiece measurement

**Example: Calibrate workpiece probe, workpiece measurement with L973 and L974**  
(Data as in Fig. 4.22)

%931		
N5	G18 G53 T1 D31 X130	Call probe type 7
N10	R22=1 R23=2002 R25=0 R27=1 R28=1 R30=2 R32=20 R36=1 R33=0	Calibrate 2 axis direction -X,+X
N20	L973	
N25	R23=22 R30=1 R32=0	Calibrate in Z axis
N30	L973	Calibrate probe in minus Z direction
N35	G54 G00 Z40	Select ZO; position Z axis to face measuring point 1
N40	R10=8 R11=3 R22=1 R23=21 R25=0 R27=1 R28=1 R29=2 R30=2	Define parameters for measurement
N45	R33=0.002 R34=0.005 R36=0.3 R37=0.2 R40=0 R41=-0.01 R42=200	
N55	L974	Measure MP1
N60	G00 Z70	Position probe to face MP2
N65	X175	
N70	R10=9 R11=4 R30=1 R40=0.01 R41=-0.01 R42=50	Define parameters for measurement
N80	L974	Measure MP2
N85	G00 Z180	Position probe to face MP3
N90	R10=10 R11=5 R30=2 R40=0.005 R41=-0.003 R42=150	Define parameters for measurement
N100	L974	Measure MP3
N105	G00 Z150	Position probe to face MP4
N110	X50	
N115	R10=11 R11=6 R30=1 R40=0.01 R41=-0.01 R42=100	Define parameters for measurement
N125	L974	Measure MP4
N130	G00 Z250 D0 G53	Retraction Z
N135	G53 X280 M30	Retraction X

## 4.5 Parameter recommendations for L973, L974

### Parameter recommendations for reliable program run


#### Measure workpiece

- |    |                                   |      |                           |
|----|-----------------------------------|------|---------------------------|
| a) | Calibrate                         | L973 |                           |
|    | Zero offset range                 |      | R33=0.001                 |
|    | Compensation range with averaging |      | R34=0.010                 |
|    | Safe area                         |      | R36=1 (Continuous mode)   |
|    | Safe area                         |      | R36=3 (Setup mode)        |
| b) | Measure                           | L974 |                           |
|    | Zero offset range                 |      | R33=0.001                 |
|    | Compensation range with averaging |      | R34=0.010                 |
|    | Safe area                         |      | R36=1 (Continuous mode)   |
|    | Safe area                         |      | R36=3 (Setup mode)        |
|    | Dimensional difference check      |      | R37=0.3 (Continuous mode) |
|    | Dimensional difference check      |      | R37=3 (Setup mode)        |

All X-axis values are related to the diameter.


END OF SECTION

## 5 Measuring Cycles for Milling Machines and Machining Centres



*The possible scope of measurement depends on the machine configuration and can also be partly determined via MDC.*

*(See machine tool manufacturer's specifications)*



Cycle	Function
L931	Auxiliary cycle for tool or workpiece measuring cycles
L932	Check MDC and transfer parameters
L933	Auxiliary cycle for tool or workpiece cycles
L934	Auxiliary cycle for tool or workpiece cycles
L935	Measurement result display selection
L936	Measurement abort
L937	Auxiliary cycle for tool or workpiece measuring cycles
L938	Auxiliary cycle for tool or workpiece measuring cycles
L939	Auxiliary cycle for tool measuring cycle
L961	Additive input of empirical values
L962	Erase program empirical values/average values
L963	Auxiliary cycle for workpiece measuring cycle L979
L964	Auxiliary cycle for workpiece measuring cycle L976
L965	Measuring plane
L966	Auxiliary program for operator guidance macro
L967	Presetting of transfer parameters
L969	Coordinate rotation
L970	Pre-positioning
L976	Calibrate workpiece probe
L977	Workpiece measurement BWN
L978	Workpiece measurement
L979	Workpiece measurement 2D BWN
L988	Auxiliary cycles for workpiece measuring cycles
L989	Auxiliary cycle for workpiece measuring cycle L979

See Section 3 for auxiliary cycles

Workpiece measuring cycles



These programs **must be available**



Additional programs: Facilitate programming and operating.

## 5.1 L976 Calibrating the workpiece probe

On milling machines and machining centres, the probe is usually loaded into the spindle from a tool magazine. This may lead to errors in further measurements caused by clamping tolerances of the probe in the spindle.

In addition, the probe trigger point must be precisely determined in relation to the spindle centre. This is achieved by the calibration cycle which makes it possible to calibrate the probe either in a hole (plane) or at a surface (applicate).

The measuring variant is selected by defining R23:

Definition of R23	Workpiece probe type 30 calibration
R23 = xxx00 R23 = xxx10 R23 = xxx20 R23 = xxx01	In reference hole (plane) On reference ball (plane) On reference cube, surface (plane) In reference hole (applicate)
R23 = xxx02 R23 = xxx23	In random hole (plane) On any cube, surface (applicate)

### Applicable types of probe: (see Section 1.3)

- In the case of milling and machining centres the probe must be entered as type 30 in the TOA memory.
- Multidirectional probe
- Monodirectional probe
- Bidirectional probe

The various probe types are differentiated by defining R22 (see Section 2.6):

The probe ball diameter must only be calculated when the following cycles (measurement variants) are used:

L978 With differential measurement

L979 Workpiece measurement hole/shaft/slot/web at random angle

### 5.1.1 L976 Calibrating the workpiece probe in reference hole (plane)

#### Function and application

The measuring cycle calibrates the probe clamped in the spindle in a reference hole. The trigger points determined are loaded into the relevant MDC area.

The cycle positions the probe automatically into the selected reference hole. Positioning is paraxial with linear interpolation over the shortest distance.

The probe is at the centre of the hole on completion of calibration.

#### Preconditions:

- The probe must be called with **tool offset** and **G53**.
- The dimensions of the reference hole in relation to the machine zero point must have been input in the MDC area.
- The valid reference hole is specified with R12.
- Random start point
- The probe ball must be located above the upper edge of the reference hole.

#### The following parameters must be defined prior to call:

Parameters	Description
R12	Selection of reference hole
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe type/probe number (see Section 2.6)
R23 = 0	Calibrating in reference hole (plane) (see Section 2.7.4)
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30	Measuring axis (definition depending on R23)
R31 = 0 = 1	Axial direction (definition depending on R23) Positive axial direction Negative axial direction
R33	Zero offset range
R36	Safe area

See Section 10.2 for result display parameters.

## 5.1.1 L976 Calibrating the workpiece probe in reference hole (plane)




Fig. 5.1 Workpiece probe

**Example: Calibrating workpiece probe 1 in reference hole 1 in the X-Y plane**  
(Fig. 5.4)

```
%MPF 9761
```

```
N1 T200
```

```
N5 G53 G17 G00 D99 Z100
```

```
N10 R12=1 R22=1 R23=0 R25=0
```

```
R27=1 R28=1 R33=0 R36=1
```

```
N15 L976
```

```
N20 M30
```

T No. probe

Select length compensation without ZO

Parameters for calibrating cycle

Cycle call for calibrating  
in the X-Y plane

The new trigger values are stored in the relevant MDC area.




Fig. 5.2 Reference hole

## 5.1.2 L976 Calibrating workpiece probe in reference hole (applicator)

### Function and application

The measuring cycle makes it possible to calibrate the probe in the applicator in a reference hole, and thus to determine the trigger length. The cycle positions the probe automatically into the reference hole selected, positioning being paraxial with linear interpolation over the shortest distance.

As from Version 3.5, the length in the TOA memory can refer to the probe end (MDC 7004.5=1), otherwise it refers to the ball centre (see also Section 1.4.3).

The probe is located above the calibration surface by the amount "a" on completion of calibration.

### Preconditions:

- The probe must be called with **tool offset** and **G53**.
- The dimensions of the reference hole in relation to the machine zero point must have been input in the MDC area.
- The valid reference hole is specified with R12.
- Random start point
- The probe ball must be located above the upper edge of the reference hole.

### The following parameters must be defined prior to call:

Parameters	Description
R12	Selection of reference hole
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe type/probe number (see Section 2.6)
R23 = 1	Calibrating in reference hole (applicator) (see Section 2.7.4)
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30	Measuring axis (definition depending on R23)
R31 = 0 = 1	Axial direction (definition depending on R23) Positive axial direction Negative axial direction
R33	Zero offset range
R36	Safe area

See Section 10.2 for result display parameters.




Fig. 5.3 Workpiece probe

**Example: Calibrating workpiece probe 2 in reference hole 3  
in the Z axis** (Data as in Fig. 5.6)

The probe length (Z axis) must have been input prior to cycle call in the TO memory, e.g. D98 (in this case value 50).

<b>%MPF</b>	<b>9763</b>								
<b>N1</b>	<b>T200</b>								T No. probe
<b>N5</b>	<b>G53 G17 G00 D98 Z100</b>								Select length compensation, without ZO
<b>N10</b>	<b>R12=3 R22=2 R23=1 R25=0</b>								Parameters for calibrating cycle
	<b>R27=1 R28=1 R33=0 R36=1</b>								
<b>N15</b>	<b>L976</b>								Cycle call for calibrating in the Z axis
<b>N20</b>	<b>M30</b>								

The new trigger point is entered in accordance with the MDC.

5.1.2 L976 Calibrating workpiece probe in reference hole (applicate)




Fig. 5.4 Reference hole

### 5.1.3 L976 Calibrating workpiece probe in any hole (plane)

#### Function and application

The measuring cycle enables the probe to be calibrated in any hole, e.g. on the workpiece.

The trigger points determined are loaded automatically into the relevant MDC area.

The probe is located at the centre of the hole on completion of calibration. Where one point is measured, the probe is located above the calibration surface by the amount "a".

#### Preconditions:

- The probe must be called with **tool offset** and without **G53**.
- The probe must be positioned to the hole centre point in the abscissa and ordinate of the selected measuring plane and to the calibrating depth within the hole.

#### The following parameters must be defined prior to call:

Parameters	Description
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe type/probe number (see Section 2.6)
R23 = 2	Calibrating in any hole (plane) (see Section 2.7.5)
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30	Measuring axis (definition depending on R23)
R31 = 0 = 1	Axial direction (definition depending on R23) Positive axial direction Negative axial direction
R32	Set value for calibration=diameter of hole
R33	Zero offset range
R36	Safe area

See Section 10.2 for result display parameters.

**Example: Calibrating workpiece probe 3 in the X-Y plane**

The probe length (Z axis) must have been input in the TO memory prior to cycle call, e.g. D98 (in this case value 50).

<b>%MPF</b>	<b>9764</b>									
<b>N1</b>	<b>T200</b>									T No. probe
<b>N5</b>	<b>G59</b>	<b>X100</b>	<b>Y50</b>	<b>Z0</b>						Load ZO values
<b>N10</b>	<b>G54</b>	<b>G17</b>	<b>G00</b>	<b>X100</b>	<b>Y80</b>					Probe at centre point and ZO selection
<b>N15</b>	<b>D98</b>	<b>Z10</b>								Selection of length compensation Position probe in hole
<b>N20</b>	<b>R22=3</b>		<b>R23=2</b>			<b>R25=0</b>		<b>R27=1</b>		Parameters for calibrating cycle
	<b>R28=1</b>		<b>R32=100</b>			<b>R33=0</b>		<b>R36=1</b>		
<b>N25</b>	<b>L976</b>									Cycle call for calibrating in the X-Y-plane
<b>N20</b>	<b>M30</b>									

The new trigger values are stored in the relevant MDC areas.




Fig. 5.5 Any calibration hole

## 5.1.4 L976 Calibrating workpiece probe on any surface (applicatae)

### Function and application

The measuring cycle enables the probe to be calibrated in the applicatae on any surface, e.g. at the workpiece, and thus to determine the length.

As from Version 3.5, the length can refer to the probe end (MDC 7004.5=1), otherwise it refers to the ball centre (see also Section 1.4.3).

The probe is located above the calibration surface by the amount "a" on completion of calibration.

### Precondition:

The probe must be positioned **with** tool offset and **without G53** to face the calibration surface.

### The following parameters must be defined prior to call:

Parameters	Description
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe type/probe number (see Section 2.6)
R23 = 3	Calibrating on any surface (applicatae) (see Section 2.7.4)
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30	Measuring axis (definition depending on R23)
R31 = 0 = 1	Axial direction (definition depending on R23) Positive axial direction Negative axial direction
R32	Set value for calibration
R33	Zero offset range
R36	Safe area

See Section 10.2 for result display parameters.



## 5.2 L977 Workpiece measurement hole/shaft/slots/ZO determination (paraxial)

The cycle determines the dimensions of holes, shafts and slots (H-S-S measuring cycle) and performs automatic tool offset when necessary.

It also determines the zero offset (ZO) between the centre point of a hole, shaft or slot and the workpiece zero point.

For measuring variants hole and shaft, measurements can be performed with active coordinate rotation (see MDC 7004.1).

Selection is performed on the basis of the definition of R23:

Definition of R23	Prepositioning
R23= 1 Measure hole with tool offset	C. p., applicate for depth
R23= 2 Measure shaft with tool offset	C. p., applicate approx. 1 mm above shaft
R23= 11 Measure slot with tool offset	C. p., applicate for depth
R23= 12 Measure web with tool offset	C. p., applicate approx. 1 mm above web
R23= 21 ZO determination in hole with correction of the zero offset	C. p., applicate for depth
R23= 22 ZO determination at shaft with correction of the zero offset	C. p., applicate approx. 1 mm above shaft
R23= 31 ZO determination in slot with correction of the zero offset	C. p., applicate for depth
R23= 32 ZO determination at web with correction of the zero offset	C. p., applicate approx. 1 mm above web

### Applicable types of probe: (see Section 1.3)

- In the case of milling and machining centres the probe must be entered as type 30 in the TOA memory.
- Multidirectional probe
- Monodirectional probe
- Bidirectional probe

A distinction is made between the probe types by defining R22 (see Section 2.6).

## 5.2.1 L977 Measure hole (paraxial)

### Function and application

The measuring cycle measures points P1, P2, P3 and P4 in the abscissa and ordinate. These four measured values are used to calculate the actual value of the hole diameter and the position of the hole centre point in the abscissa and ordinate relative to the workpiece zero point (see Fig. 5.9).

The centre point of the abscissa is calculated from points P1 and P2. The probe is then positioned to the calculated centre point and points P3 and P4 are measured. These two points are used to calculate the hole centre point of the ordinate and the hole diameter.

The probe is at the determined hole centre on completion of measurement.

### Refers to hole diameter only:

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

In addition, averaging is performed over a number of parts and the tolerance bands are checked (see Section 1.7.1).

No automatic offset is carried out or alternatively length compensation or radius compensation (difference halved) is performed, depending on the definition of R10.

### Preconditions :

- The probe must be called **with** tool offset and **without G53**.
- The probe must be positioned to the hole centre point in the abscissa and ordinate and the probe ball must be positioned within the hole to the measuring height.

**The following parameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory for diameter) (see Section 2.3)
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe type/probe number (see Section 2.6)
R23 = 1	Measure hole
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1..3)
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value diameter (according to drawing)

See Section 10.2 for result display parameters.

**Example: Measure hole with measuring cycle L977**  
(Data as in Fig. 5.9)

Probe length (Z axis) in TO memory D99 (value 50).

```

%MPF
:
Machining program
:
N500   G54 T200           T No. probe; select ZO
N505   G00 X180 Y130     Position probe in X and Y axes
                               to hole centre point
N510   Z20 D99           Position Z axis in hole
N515   R10=2030          R11= 10      R22=1      R23=1      Define parameters for measuring cycle
        R25=0            R27= 1      R28=1      R29=3
        R33=0.002        R34= 0.03   R36=1      R37=0.06
        R40=0.03         R41=-0.03  R42=130
N525   L977             Cycle call for hole
                               measurement in X/Y
N530   G00 Z160         Withdraw Z axis from hole
N535   M30

```



## 5.2.2 L977 Measure shaft (paraxial)

### Function and application

The measuring cycle measures points P1, P2, P3 and P4 at a shaft in the abscissa and ordinate. These four measured values are used to calculate the actual shaft diameter and the position of the shaft centre point in the abscissa and ordinate relative to the workpiece zero point (see Fig. 5.10).

The centre point of the abscissa is calculated from points P1 and P2. The probe is then positioned at the calculated centre point and points P3 and P4 are measured. The shaft centre point of the ordinate and shaft diameter are calculated on the basis of these points.

The probe is located above the determined shaft centre on completion of measurement.

### Refers to shaft diameter only:

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

In addition, averaging is formed over several parts and the tolerance bands are checked (see Section 1.7.1).

No automatic offset is performed or alternatively length compensation or radius offset (difference halved) is carried out, depending on the definition of R10.

### Preconditions:

- The probe must be called **with** tool offset and **without G53**.
- The probe must be positioned at the shaft centre point in the abscissa and ordinate, the probe ball being positioned approx. 1 mm **above** the shaft in the applicate.
- R19 is calculated incrementally from the starting position.

**The following parameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory for diameter) (see Section 2.3)
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R19	Incremental infeed of applicate with sign (travel over the shaft)
R22 _	Probe type/probe number (see Section 2.6)
R23 = 2	Measure shaft
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1..3)
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value diameter (according to drawing)

See Section 10.2 for result display parameters.

**Example: Measure shaft with measuring cycle L977**  
(Data as in Fig. 5.10)

```

%MPF  9773
:
Machining program
:
N500  G54  T200
N505  G00  X180 Y130

N510  Z101 D99
N515  R10=2030  R11=10  R19=-30  R22=1
      R23=2  R25=0  R27= 1  R28=1
      R29=3  R33=0.002  R34= 0.03  R36=1
      R37=0.06  R40=0.03  R41=-0.03  R42=130

N530  L977
N535  G00  Z160
N540  M30

```

T No. probe; select ZO  
Position probe in X and Y axes at shaft centre point  
Position Z axis above shaft  
Define parameters for measuring cycle  
Cycle call for shaft measurement in X/Y  
Run up Z axis




Fig. 5.8 Measure shaft

### 5.2.3 L977 Measure slot (paraxial)

#### Function and application

The measuring cycle measures points P1 and P2 inside the slot in the measuring axis. These two measured values are used to calculate the actual value of the slot and the position of the slot centre point in the measuring axis in relation to the workpiece zero point (see Fig. 5.11).

The probe is located at the determined slot centre point on completion of measurement.

#### Refers to the slot width only:

An empirical value stored in the SDC is allowed for with the correct sign.

In addition, averaging is performed over several parts and the tolerance bands are checked, (see Section 1.7.1).

No automatic offset is carried out or alternatively length compensation or radius offset (difference halved) is performed, depending on the definition of R10.

#### Preconditions:

- The probe must be called **with** tool offset and **without G53**.
- The probe must be positioned at the slot centre point in the measuring axis, the probe ball being positioned in the applicator inside the slot.

**The following parameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory for diameter) (see Section 2.3)
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe type/probe number (see Section 2.6)
R23 = 11	Measure slot
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measuring path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1..3)
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value slot (according to drawing)

See Section 10.2 for result display parameters.

**Example: Measure slot with measuring cycle L977**  
(Data as in Fig. 5.11)

```

%MPF    9774
:
Machining program
:
N500    G54 T200
N505    G00 X150 Y130

N510    Z40 D99
N515    R10=2030    R11=10    R22= 1    R23=11
          R25=0    R27=1    R28= 1    R29=3
          R30=2    R33=0.002  R34= 0.03  R36=1
          R37=0.06  R40=0.03  R41=-0.03  R42=100

N525    L977
N530    G00 Z160
N535    M30

```

T number probe; select ZO  
Position probe in Y axis at slot  
centre point and in the X axis  
at measuring position  
Position Z axis inside slot  
Define parameters for measuring cycle  
Cycle call for slot measurement in Y  
Withdraw Z axis from slot



## 5.2.4 L977 Measure web (paraxial)

### Function and application

The measuring cycle measures two parallel surfaces (web) at points P1 and P2 in the measuring axis. These two measured values are used to calculate the actual distance of the parallel surfaces and the position of the centre point in the measuring axis (Fig. 5.12).

The probe is located above the determined centre point on completion of measurement.

### Refers to web width only:

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

In addition, averaging is performed over a number of parts and the tolerance bands are checked (see Section 1.7.1).

No automatic compensation is carried out or alternatively length compensation or a radius offset (difference is halved) is performed, depending on the definition of R10.

### Preconditions:

- The probe must be called **with** tool offset and **without G53**.
- The probe must be positioned on the centre point of the parallel surfaces and the probe ball approx. 1 mm above the parallel surfaces in the applicate.
- R19 is calculated incrementally from the starting position.

**The following parameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory for diameter) (see Section 2.3)
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R19	Incremental infeed of applicate with sign (travel over the web)
R22	Probe type/probe number (see Section 2.6)
R23 = 12	Measure web
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1...3)
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value web (according to drawing)

See Section 10.2 for result display parameters.

**Example: Measure web with measuring cycle L977**  
(Data as in Fig. 5.12)

```

%MPF  9775
:
Machining program
:
N500  G54          T200
N505  G00          X220          Y130

N510  Z101 D99
N515  R10=2030    R11=10        R19=-40        R22= 1

          R23=12    R25=0        R27= 1        R28= 1
          R29=3     R30=1        R33= 0.002    R34= 0.03
          R36=1     R37=0.06    R40= 0.03    R41=-0.03
          R42=60

N525  L977

N530  G00 Z160
N535  M30

```

T number probe; select ZO  
Position probe in X axis above  
slot centre point and in the  
Y axis at measuring position  
Position Z axis above web  
Define parameters for measuring  
cycles

Cycle call for web measurement  
in X direction  
Run up Z axis




Fig. 5.10 Measure web

## 5.2.5 L977 ZO determination in hole (paraxial)

### Function and application

The measuring cycle measures points P1, P2, P3 and P4 in the abscissa and ordinate. These four measured values are used to calculate the position of the hole centre point in the abscissa and ordinate in relation to the workpiece zero point (see Fig. 5.13).

The centre point of the abscissa is calculated from points P1 and P2. The probe is then positioned at the centre point calculated and points P3 and P4 are measured. These two points provide the hole centre point of the ordinate.

The difference is determined from the set centre point (start position) and the centre point determined.

The multiplication factor for measurement path "2a" makes it possible to take into account the variation range of the blanks (set value).

The probe is located at the centre of the hole when measurement is completed.

No automatic ZO entry is carried out or alternatively additive input of the difference between the two measuring axes in the ZO memory specified is performed, depending on the definition of R10.

### Preconditions:

- The probe must be called **with** tool offset and **without G53**.
- The spindle centre point must be positioned at the hole centre point in the abscissa and ordinate, the probe ball being positioned inside the hole in the applicator.

### The following must be defined prior to call:

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO determination Automatic ZO entry in ZO G54 ... G57 Automatic ZO entry in ZO G58
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe type/probe number (see Section 2.6)
R23 = 21	ZO determination in hole
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R32	Set value diameter
R36	Safe area (centre point coordinates)

See Section 10.2 for result display parameters.






Fig. 5.11 ZO determination in hole

## 5.2.6 L977 ZO determination on shaft

### Function and application

The measuring cycle measures points P1, P2, P3 and P4 in the abscissa and ordinate. These four measured values are used to calculate the position of the shaft centre point in the abscissa and ordinate in relation to the workpiece zero point (see Fig. 5.14).

Points P1 and P2 are used to calculate the centre point of the abscissa. The probe is then positioned at the centre point calculated and points P3 and P4 are measured. These two points provide the shaft centre point of the ordinate.

The difference is determined from the set centre point (start position) and the centre point determined.

The multiplication factor for measurement path "2a" makes it possible to take into account the variation range of the blanks (set value).

The probe is located above the shaft centre point when measurement is completed.

No automatic ZO entry is carried out or alternatively additive input of the difference of the two measuring axes is performed in the ZO memory specified, depending on the definition of R10.

### Preconditions:

- The probe must be called **with** tool offset and **without G53**.
- The probe must be positioned at the shaft centre point in the abscissa and ordinate, the probe ball being positioned approx. 1 mm above the shaft in the applicate.
- R19 is calculated incrementally from the starting position.

**The following parameters must be defined prior to call:**

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO determination Automatic ZO entry in ZO G54 ... G57 Automatic ZO entry in ZO G58
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R19	Incremental infeed of applicate with sign (travel over the shaft)
R22	Probe type/probe number (see Section 2.6)
R23 = 22	ZO determination at shaft
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R32	Set value diameter
R36	Safe area (centre point coordinates)

See Section 10.2 for result display parameters.

**Example: ZO determination on shaft with measuring cycle L977**  
(Data as in Fig. 5.14)

<b>%MPF</b>	<b>9777</b>					
<b>N5</b>	<b>G54 T200</b>					T number probe; select ZO
<b>N10</b>	<b>G00 X180 Y130</b>					Position probe in X and Y axes at shaft centre point
<b>N15</b>	<b>Z101 D99</b>					Position Z axis above shaft
<b>N20</b>	<b>R10=1</b>	<b>R19=-30</b>	<b>R22=1</b>	<b>R23=22</b>		Define parameters for measuring cycle
	<b>R25=0</b>	<b>R27= 1</b>	<b>R28=1</b>	<b>R32=130</b>		
	<b>R36=1</b>					
<b>N25</b>	<b>L977</b>					Cycle call for ZO determination in X/Y
<b>N30</b>	<b>G00 Z160</b>					Run up Z axis
	<b>:</b>					
	<b>Machining program</b>					
	<b>:</b>					
	<b>:</b>					
<b>N...</b>	<b>M30</b>					




Fig. 5.12 ZO determination at shaft

## 5.2.7 L977 ZO determination in slot (paraxial)

### Function and application

The measuring cycle measures points P1 and P2 in the measuring axis inside the slot. The two measured values are used to calculate the position of the slot centre point in the measuring axis in relation to the workpiece zero point (see Fig. 5.15).

The difference is determined from the set centre point (start position) and the centre point determined.

The multiplication factor for measurement path "2a" makes it possible to take into account the variation range of the blanks (set value).

The probe is located above the slot centre determined when measurement is completed.

No automatic ZO entry is carried out or alternatively additive input of the measuring axis difference is performed in the ZO memory specified, depending on the definition of R10.

### Preconditions :

- The probe must be called **with** tool offset and **without G53**.
- The probe must be positioned at the slot centre point in the measuring axis, the probe ball being positioned inside the slot in the applicate.

**The following parameters must be defined prior to call:**

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO determination Automatic ZO entry in ZO G54 ... G57 Automatic ZO entry in ZO G58
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe type/probe number (see Section 2.6)
R23 = 31	ZO determination in slot
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30 = 1...3	Number of measuring axis (see Section 2.12)
R32	Set value slot width
R36	Safe area (centre point coordinates)

See Section 10.2 for result display parameters.






Fig. 5.13 ZO determination in slot

## 5.2.8 L977 ZO determination on a web (paraxial)

### Function and application

The measuring cycle measures points P1 and P2 in the measuring axis on two parallel surfaces (web). The two measured values are used to calculate the position of the centre point in the measuring axis in relation to the workpiece zero point (see Fig. 5.16).

The difference is calculated from the set centre point (start position) and the centre point determined.

The multiplication factor for measurement path "2a" makes it possible to take into account the variation range of the blanks (set value).

The probe is located above the centre point of the parallel surfaces on completion of measurement.

No automatic ZO entry is carried out or alternatively additive input of the measuring axis difference is performed in the ZO memory specified, depending on the definition of R10.

### Preconditions:

- The probe must be called **with** tool offset and **without G53**.
- The spindle centre point must be positioned at the centre point of the parallel surfaces in the measuring axis, the probe ball being positioned above the parallel surfaces in the applicate.
- R19 is calculated incrementally from the starting position.

### The following parameters must be defined prior to call:

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO determination Automatic ZO entry in ZO G54 ... G57 Automatic ZO entry in ZO G58
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R19	Incremental infeed of applicate with sign (travel over the web)
R22	Probe type/probe number (see Section 2.6)
R23 = 32	Measure web
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1...3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30 = 1...3	Number of measuring axis (see Section 2.12)
R32	Set value web width
R36	Safe area (centre point coordinate)

See Section 10.2 for result display parameters.

**Example: ZO determination on a web with measuring cycle L977**  
(Data as in Fig. 5.16)

<b>%MPF</b>	<b>9779</b>					
<b>N5</b>	<b>G54 T200</b>					T number probe; select ZO
<b>N10</b>	<b>G00 X220 Y130</b>					Position probe in X axis above web centre point and in Y axis at measuring position
<b>N15</b>	<b>Z101 D99</b>					Position Z axis above web
<b>N20</b>	<b>R10=1</b>	<b>R19=-40</b>	<b>R22=1</b>	<b>R23=32</b>		Define parameters for measuring cycle
	<b>R25=0</b>	<b>R27= 1</b>	<b>R28=1</b>	<b>R30=1</b>		
	<b>R32=130</b>	<b>R36=1</b>				
<b>N25</b>	<b>L977</b>					Cycle call for ZO determination in X
<b>N30</b>	<b>G00 Z160</b>					Run up Z axis
	<b>:</b>					
	<b>Machining program</b>					
	<b>:</b>					
	<b>:</b>					
<b>N ...</b>	<b>M30</b>					




Fig. 5.14 ZO determination on a web

### 5.3 L979 Workpiece measurement hole/shaft/slot/web/ZO determination (at random angles)

#### Preconditions :

- Circle radius programming
- Polar coordinate programming
- Oriented spindle stop (M19) via NC with axis movement
- Optional positioning of probe in spindle between 0 and 360 degrees (all-round coverage)

The cycle has the same range of functions and the same preconditions as L977.

The hole or shaft is determined by this cycle by means of 3-point or 4-point measurement. It is thus possible to measure **circle segments** whose centre points are located outside the machine (see Fig. 5.17).

Measurement at points P1, P2, P3 and P4 is performed at random angles (2D = two-dimensional; measure in two axes simultaneously, depending on the angle of measurement).

The probe is positioned from P1 to P2, from P2 to P3 and from P3 to P4 with circular interpolation. The R28 distance between the probe and the contour is maintained. The probe is positioned at the relevant angle of measurements with M19 to ensure that P1 - P4 are always measured with the **same** probe point.

The probe must be calibrated in the plane. If a multidirectional probe is used, calibration must include determination of the position deviation (e.g. measuring variant R23=10002). The spindle must be positioned with 0°.

If cycle machine data MDC 7004.0=1 (spindle offset), parameter R13 takes effect even if a multidirectional probe is in use and can be used to adapt the positioning direction of the spindle.

- R13=0 Positioning direction of the spindle corresponds to M3
- R13=-360 Opposite positioning direction

At the end of the cycle, the probe is facing P3 (P4) by the amount of R28 (facing P2 in the case of slot measurement).

The measurement variant is selected by defining R23:


R23 = 1	Measure hole
R23 = 2	Measure shaft
R23 = 11	Measure slot
R23 = 12	Measure web
R23 = 21	ZO determination in hole
R23 = 22	ZO determination at shaft
R23 = 31	ZO determination in slot
R23 = 32	ZO determination at web

Prepositioning: Always facing and level with P1

**Applicable types of probe (see Section 1.3)**

- In the case of milling and machining centres the probe must be entered as type 30 in the TOA memory.
- Multidirectional probe
- Bidirectional probe
- Monodirectional probe

The various types of probe and the number of measuring points are differentiated by defining R22 (see Section 2.6)



An internal call of L963 is made by the cycle for calculation, parameter R00 is used for defining L963. Depending on the type of control, cycle L963 takes up to approx. 0.5 to 10 seconds for the 4-point measurement!




Fig. 5.15 Measure circle segment

### 5.3.1 L979 Measure hole (at random angles)

The following parameters must be defined prior to call:

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory for diameter) (see Section 2.3)
R13 = 0...359.5 R13 = 0/-360	Compensation angle position for monodirectional probe (see Section 2.5) Positioning direction of spindle with multidirectional probe and MDC 7004.0=1
R20	Centre point abscissa (in relation to workpiece zero point)
R21	Centre point ordinate (in relation to workpiece zero point)
R22	Number of measuring points/probe type/probe number
R23 = 1	Measure hole
R24 = 0...360	Start angle (with reference to abscissa (horizontal axis))
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R26 = 0...360	Indexing angle
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1..3)
R31	Velocity for circular interpolation
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing )
R42	Set value diameter (according to drawing)

See Section 10.2 for result display parameters.

**Example: Measure hole with measuring cycle L979**  
(Data as in Fig. 5.18)

```

%MPF    9791
:
Machining centre program
:
N500    G54 T200
N505    G00 X240 Y130

N510    Z20 D99
N515    R10=2030      R11=10 R13=0  R20= 180  R21=130
          R22=1  R23=1  R24= 10 R25=0
          R26=90 R27=1  R28= 1  R29=3
          R31=1000     R33=0.002   R34= 0.03 R36=1
          R37=0.06     R40=0.03    R41=-0.03 R42=130

N525    L979

N530    G00 Z160
N535    M30

```

T number probe; select Z0  
Position probe in X and Y axes  
near P1  
Position Z axis level with P1  
Define parameters for measuring cycle  
Cycle call for hole measurement  
in X/Y  
Withdraw Z axis from hole




Fig. 5.16 Measure hole

### 5.3.2 L979 Measure shaft (at random angles)

The following parameters must be defined prior to call:

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory number for diameter) (see Section 2.3)
R13 = 0...359.5 R13 = 0/-360	Compensation angle position for monodirectional probe (see Section 2.5) Positioning direction of spindle with multidirectional probe and MDC 7004.0=1
R20	Centre point abscissa (in relation to workpiece zero point)
R21	Centre point ordinate (in relation to workpiece zero point)
R22	Number of measuring points/probe type/probe number
R23 = 2	Measure shaft
R24 = 0...359.5	Start angle (with reference to abscissa (horizontal axis))
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R26 = 0...359.5	Indexing angle
R27 = 1...R <sub>max</sub>	Number of measurements at same locations (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1..3)
R31	Velocity for circular interpolation
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value diameter (according to drawing)

See Section 10.2 for result display parameters.

**Example: Measure shaft with measuring cycle L979**  
(Data as in Fig. 5.19)

```
%MPF 9792
:
Machining centre program
:
N500 G54 T200 T number probe; select ZO
N505 G00 X255 Y130 Position probe in X and
Y axes near P1
N510 Z20 D99 Position Z axis level with P1
N515 R10=2030 R11=10 R13=0 R20= 180 R21=130 Parameter für Meßzyklus definieren
R22=1 R23=2 R24= 10 R25=0
R26=90 R27=1 R28= 1 R29=3
R31=1000 R33=0.002 R34= 0.03 R36=1
R37=0.06 R40=0.03 R41=-0.03 R42=130

N525 L979 Cycle call for shaft measurement
in X/Y
N530 G00 Z160 Run up Z axis

N535 M30
```




Fig. 5.17 Measure shaft

### 5.3.3 L979 Measure slot (at random angles)

The following parameters must be defined prior to call:

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory for diameter) (see Section 2.3)
R13 = 0...359.5 R13 = 0/-360	Compensation angle position for monodirectional probe (see Section 2.5) Positioning direction of spindle with multidirectional probe and MDC 7004.0=1
R20	Centre point abscissa (in relation to workpiece zero point)
R21	Centre point ordinate (in relation to workpiece zero point)
R22	Probe type/probe number
R23 = 11	Measure slot
R24 = 0...360	Start angle (with reference to abscissa (horizontal axis))
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1..3)
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set point slot (according to drawing)

See Section 10.2 for result display parameters.

**Example: Measure slot with measuring cycle L979**  
(Data as in Fig. 5.20)

```

%MPF    9793
:
Machining centre program
:
N500    G54 T200           T number probe; select ZO
N505    G00 X150 Y170     Position probe in X and
                               Y axes near P1
N510    Z40 D99           Position Z axis level with P1
N515    R10=2030    R11= 10    R20=150    R21=130    Define parameters for measuring cycle
          R22=1      R23= 11    R24=70    R25=0
          R27=1      R28= 1    R29=3
          R33=0.002  R34= 0.03  R36=1    R37=0.06
          R40=0.03  R41=-0.03  R42=100
N525    L979             Cycle call for slot measurement
                               in X/Y
N530    G00 Z160         Run up Z axis
N535    M30

```




Fig. 5.18 Measure slot

### 5.3.4 L979 Measure web (at random angles)

The following parameters must be defined prior to call:

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory for diameter) (see Section 2.3)
R13 = 0...359.5 R13 = 0/-360	Compensation angle position for monodirectional probe (see Section 2.5) Positioning direction of spindle with multidirectional probe and MDC 7004.0=1
R19	Incremental infeed of hole axis with sign (travel over web)
R20	Centre point abscissa (in relation to workpiece zero point)
R21	Centre point ordinate (in relation to workpiece zero point)
R22	Probe type/probe number
R23 = 12	Measure web
R24 = 0...359.5	Start angle (with reference to abscissa (horizontal axis))
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1..3)
R33	Zero offset range
R34	Compensation area with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set point web (according to drawing)

See Section 10.2 for result display parameters.

**Example: Measure web with measuring cycle L979**  
(Data as in Fig. 5.21)

```
%MPF 9794
:
Machining centre program
:
N500 G54 T200           T number probe; select ZO
N505 G00 X260 Y130     Position probe in X and
                       Y axes near P1
N510 Z70 D99          Position Z axis level with P1
N515 R10=2030 R11=10 R19= 35 R20=220   Define parameters for measuring cycle
      R21=130 R22=1 R23= 12 R24=10
      R25=0 R27=1 R28= 1 R29=3
      R33=0.002 R34= 0.03 R36=1
      R37=0.06 R40=0.03 R41=-0.03 R42=100
N525 L979             Cycle call for web measurement
                       in X/Y
N530 G00 Z160         Run up Z axis
N535 M30
```




Fig. 5.19 Measure web

### 5.3.5 L979 ZO determination in hole (at random angles)

The following parameters must be defined prior to call:

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO entry Automatic ZO entry in ZO G54 ... G57 Automatic ZO entry in ZO G58
R13 = 0...359.5 R13 = 0/-360	Compensation angle position for monodirectional probe (see Section 2.5) Positioning direction of spindle with multidirectional probe and MDC 7004.0=1
R20	Centre point abscissa (in relation to workpiece zero point)
R21	Centre point ordinate (in relation to workpiece zero point)
R22 _	Number of measuring points/probe type/probe number
R23 = 21	ZO determination in hole
R24 = 0...359.5	Start angle
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R26 = 0...359.5	Indexing angle
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R31	Velocity for circular interpolation
R32	Set value diameter
R36	Safe area (centre point coordinates)

See Section 10.2 for result display parameters.

**Example: ZO determination in hole with measuring cycle L979** (Data as in Fig. 5.22)

```

%MPF  9795
N5     G54 T200           T number probe; select ZO
N10    G00 X240 Y130     Position probe in X and
                               Y axes near P1
N15    Z20 D99           Position Z axis level with P1
N20    R10=1            R20=180      R21=130      R22=1
                               Define parameters for measuring cycles
        R23=21          R24=10       R25=0        R26=90
        R27=1          R28=1        R31=1000     R32=130
        R36=1
N25    L979             Cycle call for ZO determination in X/Y
N30    G00 Z160         Withdraw Z axis from hole
:
Machining centre program
:
:
N...   M30
    
```




Fig. 5.20 ZO determination in hole

### 5.3.6 L979 ZO determination at shaft (at random angles)

The following parameters must be defined prior to call:

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO entry Automatic ZO entry in ZO G54 ... G57 Automatic ZO entry in ZO G58
R13 = 0...359.5 R13 = 0/-360	Compensation angle position for monodirectional probe (see Section 2.5) Positioning direction of spindle with multidirectional probe and MDC 7004.0=1
R20	Centre point abscissa (in relation to workpiece zero point)
R21	Centre point ordinate (in relation to workpiece zero point)
R22	Number of measuring points/probe type/probe number
R23 = 22	ZO determination at shaft
R24 = 0...359.5	Start angle (from the abscissa (horizontal axis))
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R26 = 0...359.5	Indexing angle
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R31	Velocity for circular interpolation
R32	Set value diameter
R36	Safe area (centre point coordinates)

See Section 10.2 for result display parameters.

**Example: ZO determination at shaft with measuring cycle L979**  
 (Data as in Fig. 5.23)

```

%MPF    9796
N5      G54 T200           T number probe; select ZO
N10     G00 X250 Y130     Position probe in X and
                               Y axes near P1
N15     Z70 D99          Position Z axis level with P1
N20     R10=1           R20=180       R21=130       R22=1           Define parameters for measuring cycle
        R23=22         R23=21       R24=10       R25=0
        R26=90         R27=1       R28=1       R31=1000
        R32=130        R36=1
N25     L979           Cycle call for ZO determination in X/Y
N30     G00 Z160       Withdraw Z axis
:
Machining centre program
:
:
N...    M30
    
```




Fig. 5.21 ZO determination at shaft

### 5.3.7 L979 ZO determination in slot (at random angles)

The following parameters must be defined prior to call:

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO entry Automatic ZO entry in ZO G54...G57 Automatic ZO entry in ZO G58
R13 = 0...359.5 R13 = 0/-360	Compensation angle position for monodirectional probe (see Section 2.5) Positioning direction of spindle with multidirectional probe and MDC 7004.0=1
R20	Centre point abscissa (in relation to workpiece zero point)
R21	Centre point ordinate (in relation to workpiece zero point)
R22 _	Probe type/probe number
R23 = 31	ZO determination in slot
R24 = 0...359.5	Start angle (from the abscissa (horizontal axis))
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R32	Set value slot width
R36	Safe area (centre point coordinate)

See Section 10.2 for result display parameters.

**Example: ZO determination in slot with measuring cycle L979**  
 (Data as in Fig. 5.24)

```

%MPF  9797
N5    G54 T200                T number probe; select ZO
N10   G00 X150 Y175          Position probe in X and
                                Y axes near P1
N15   Z40 D99                Position Z axis level with P1
N20   R10=1      R20=150     R21=130     R22=1      Define parameters for measuring cycle
      R23=31     R24=70     R25=0      R27=1
      R28=1     R32=100    R36=1
N25   L979                    Cycle call for ZO determination in X/Y
N30   G00 Z160                Withdraw Z axis
:
Machining centre program
:
:
N...  M30
    
```




Fig. 5.22 ZO determination in internal slot

### 5.3.8 L979 ZO determination at web (at random angles)

The following parameters must be defined prior to call:

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO entry Automatic ZO entry in ZO G54...G57 Automatic ZO entry in ZO G58
R13 = 0...359.5 R13 = 0/-360	Compensation angle position for monodirectional probe (see Section 2.5) Positioning direction of spindle with multidirectional probe and MDC 7004.0=1
R19	Incremental infeed of hole axis with sign (travel over web)
R20	Centre point abscissa (in relation to workpiece zero point)
R21	Centre point ordinate (in relation to workpiece zero point)
R22	Probe type/probe number
R23 = 32	ZO determination at web
R24 = 0...359.5	Start angle (from the abscissa (horizontal axis))
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R32	Set value web width
R36	Safe area (centre point coordinates)

See Section 10.2 for result display parameters.

**Example: ZO determination at web with measuring cycle L979** (Data as in Fig. 5.25)

```

%MPF    97978
N5      G54 T200           T number probe; select ZO
N10     G00 X290 Y130     Position probe in X and
                               Y axes near P1
N15     D99              Position Z axis level with P1
N20     R10=1            R19=-35      R20=220      Define parameters for measuring cycle
        R21=130         R22=1        R23=32        R24=10
        R25=0           R27=1        R28=1         R32=130
        R36=1
N25     L979            Cycle call for ZO determination in X/Y
N30     G00 Z160        Withdraw Z axis
:
Machining centre program
:
:
N...   M30
    
```




Fig. 5.23 ZO determination at web

## 5.4 L978 Workpiece measurement surface/angle/ZO determination (with and without differential measurement)

The measurement cycle makes it possible to measure blanks and zero offsets can be determined automatically relative to the workpiece zero point.

Zero offset can be determined either at a surface by single point measurement or by means of angular measurement between the blank (e.g. on a rotary table) and the main machine axes.

In addition, the cycle determines the dimensions of surfaces in relation to the workpiece zero point by single point measurement or paraxial multipoint measurement and performs automatic tool offset when necessary.

Differential measurements are also possible with this cycle.

### Differential measurement means:

The measuring point (only the first measuring point in the case of paraxial multipoint measurement and angular measurement) is measured twice with the spindle being rotated through 180°, i.e. the probe is turned by 180° between the two measurements. In this way, the trigger points are determined. The trigger point is stored in the MDC for the relevant axis direction. An uncalibrated probe can therefore be used for measurement.

### Preconditions for differential measurement:

- Oriented spindle stop (M19) by the NC
- Bidirectional/multidirectional probe
- Random positioning of probe in spindle between 0 and 360° (min. every 90°) (all-round coverage).
- **Monodirectional probe must be calibrated. Differential measurements cannot be performed with this probe.**

Selection is made by defining R23:

R23 = 0	ZO determination at surface	
R23 = 1	Measure surface	
R23 = 2	Paraxial multipoint measurement	
R23 = 3	Angular measurement	
R23 = 10	ZO determination at surface	with diff. measurement
R23 = 11	Measure surface	with diff. measurement
R23 = 12	Paraxial multipoint measurement	with diff. measurement
R23 = 13	Angular measurement	with diff. measurement

### Applicable types of probe: (see Section 1.3)

- In the case of milling and machining centres the probe must be entered as type 30 in the TOA memory.
- Multidirectional probe
- Bidirectional probe
- Monodirectional probe

### 5.4.1 L978 ZO determination on surface (1-point measuring cycle)

#### Function and application

The measuring cycle determines the actual value of a blank relative to the machine zero point.

An empirical value stored in the MDC is subsequently allowed for with the correct sign.

The multiplication factor for measurement path "2a" makes it possible to take into account the variation range of the blanks (set value).

The probe faces the measuring surface at a distance of "a" on completion of measurement.

No automatic ZO entry is carried out or alternatively additive input of the measuring axis difference is performed in the ZO memory specified, depending on the definition of R10.

#### Preconditions:

The probe must be positioned **with** tool offset and **without G53** to face the surface to be measured.

The following parameters must be defined prior to call:

Parameters	Description
R10 = 0 = 1...4 = 5	No automatic ZO entry Automatic ZO entry in ZO G54...G57 Automatic ZO entry in ZO G58
R11 = 0 > 0	Without empirical value Empirical value memory number (see Section 2.3)
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe number (see Section 2.6)
R23 = 0 = 10	ZO determination at surface ZO determination at surface with differential measurement
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R26 = 0...359.5	Start angle (with differential measurement only)
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R30 = 1...3	Number of measuring axis (see Section 2.12)
R32	Set value in relation to workpiece zero point
R36	Safe area

See Section 10.2 for result display parameters.

**Example: ZO determination on workpiece with cycle L978 in the X and Y axes**  
 (Data as in Fig. 5.26)

ZO is to be checked on a workpiece as shown in Fig. 5.26. Any deviation from the selected ZO caused by clamping tolerances is to be compensated for automatically by additive ZO to enable machining of the workpiece to be started.

Probe length (Z axis) in TO memory D99 (value 50)

```

%MPF  9781
N5    G54 T200                    T number probe; select ZO
N10   G00 G90 X-20 Y25           Position probe to face the
                                   measuring surface in X/Y
N15   Z10 D99                    Position probe in Z
                                   Select TO
N20   R10=1      R11=10      R22=1      R23=0      Define parameters for measuring cycle
       R25=0      R27=1      R28=2      R30=1
       R32=0      R36=3
N25   L978                        Cycle call for ZO determination
                                   in X axis
N30   G00 X-20                    Retract in X axis
N35   Y-20                        Position in Y axis
N40   X50                          Position in X axis
N45   R11=11 R30=2                Define parameters for measuring cycle
N50   L978                        ZO determination in Y axis
N55   G00 Y-20                    Retract in Y axis
N60   Z100                        Retract in Z axis
N65   X-40 Y80                    Retract in X/Y axis
:
:
Machining centre program
:
:
N900  M30
    
```




Fig. 5.24 ZO determination on surface

## 5.4.2 L978 1-point measurement

### Function and application

The measuring cycle ascertains the actual value of the workpiece in the selected measuring axis in relation to the zero point of the workpiece and the set/actual difference.

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

In addition, averaging is performed over a number of parts and the tolerance bands are checked (Section 1.7.1).

The probe faces the measuring surface at a distance of "a" on completion of measurement.

No automatic offset is carried out or alternatively length compensation or radius offset (difference halved) is performed, depending on the definition of R10.

### Precondition:

The probe must be positioned **with** tool offset and **without G53** to face the surface to be measured.

The following parameters must be defined prior to call:

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical and average value Empirical value memory number (average value memory for diameter) (see Section 2.3)
R13 = 0...359.5	Compensation angle position for monodirectional probe (see Section 2.5)
R22	Probe number (see Section 2.6)
R23 = 1 = 11	1-point measurement 1-point measurement with differential measurement
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R26 = 0...359.5	Start angle (with differential measurement only)
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor a for averaging (typically 1...3)
R30 = 1...3	Number of measuring axis (see Section 2.12)
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value (according to drawing)

See Section 10.2 for result display parameters.

**Example: 1-point measurement in X axis with cycle L978**




Fig. 5.25 1-point measurement

Probe length (Z axis) in TO memory D99 (value 50)

```

%MPF    9782
:
Machining centre program
:
N500    G54 T200           T number probe; select ZO
N505    G00 X120 Y150     Position probe in X and
                           Y axes to face the measuring point
N510    Z40 D99           Position Z axis level with
                           measuring point
N515    R10=1021    R11=10    R22= 1    R23=1    Define parameters for measuring cycle
        R25=0      R27=1     R28= 1    R29=3
        R30=1      R33=0.002  R34= 0.015 R36=1
        R37=0.06   R40=0.03   R41=-0.03 R42=100
N525    L978             Cycle call for 1-point measurement
                           in X axis
N530    G00 Z160         Run up Z axis
N535    M30
    
```

### 5.4.3 L978 Paraxial multipoint measurement

#### Function and application

The measuring cycle ascertains the actual value of the workpiece in the selected measuring axis in relation to the workpiece zero point and the set/actual difference.

In this cycle, the actual value is calculated on the basis of the arithmetic mean of "n" values offset by R19 along the measuring axis (R30).

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

In addition, averaging is performed over a number of parts and the tolerance bands are checked (see Section 1.7.1).

The probe faces the measuring surface at a distance of "a" on completion of measurement.

No automatic offset is carried out or alternatively length compensation or radius offset (difference halved) is performed, depending on the definition of R10.

When differential measurement is selected (R23 = 12) **only** MP1 is measured twice.

#### Preconditions:

- The probe must be positioned **with** tool offset and **without G53** to face the surface to be measured and measuring point number 1 (MP1) (allow for offset distance).
- Parameter R19 specifies the distance between two measuring points along the measuring axis.

**The following parameters must be defined prior to call:**

Parameters	Description
R08	Extended T address (see Section 2.2)
R09	T number (tool number) (see Section 2.2)
R10 = 0 > 0	No automatic tool offset Automatic tool offset (see Section 2.2)
R11 = 0 > 0	Without empirical value Empirical value memory number (see Section 2.3)
R13 = 0...359,5	Compensation angle position for monodirectional probe (see Section 2.5)
R19	Infeed offset axis (incremental)
R22	Probe number (see Section 2.6)
R23 = 2 = 12	Paraxial multipoint measurement Paraxial multipoint measurement with differential measurement
R24	Number of measuring points
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R26 = 0...359.5	Start angle (with differential measurement only)
R27 = 1...R <sub>max</sub>	Number of measurement at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor for measurement path "2a"
R29 = 1...R <sub>max</sub>	Weighting factor k for averaging (typically 1..3)
R30 = 102...302	Number of offset axis (see Section 2.12)
R33	Zero offset range
R34	Compensation range with averaging
R36	Safe area
R37	Dimensional difference check
R40	Upper tolerance limit (according to drawing)
R41	Lower tolerance limit (according to drawing)
R42	Set value (according to drawing)

See Section 10.2 for result display parameters.


**Example: Multipoint measurement in X axis with cycle L978**

Fig. 5.26 Paraxial multipoint measurement

Probe length (Z axis) in TO memory D99 (value 50)

```
%MPF 9783
```

```
:
```

```
Machining centre program
```

```
:
```

```
N500 G54 T200
```

T number probe; select Z0

```
N505 G00 X70 Y30
```

Position probe in X and Y

axes to face the measuring point

```
N510 Z40 D99
```

Position Z axis level with

measuring point

```
N515 R10=1021 R11=10 R19=10 R22=1
```

Define parameters for measuring

cycle

```
R23= 2 R24=4 R25=0 R27=1
```

```
R28= 1 R29=3 R30=102 R33=0.002
```

```
R34= 0.015 R36=1 R37=0.06 R40=0.03
```

```
R41=-0.03 R42=40
```

```
N525 L978
```

Cycle call for multipoint

measurement in Y axis

```
N530 G00 Z160
```

Run up Z axis

```
N535 X20 Y70
```

```
N540 M30
```

## 5.4.4 L978 Angular measurement (ZO determination)

### Function and application

The cycle makes it possible to determine the angular position or clamping position of a workpiece in relation to the set angle value R24 in relation to the offset axis (Fig. 5.27).

An empirical value stored in the SDC is subsequently allowed for with the correct sign.

The multiplication factor for measurement path "2a" makes it possible to take into account the variation range of the blanks (set value).

The probe faces the measuring surface by the amount "a" on completion of measurement.

No automatic ZO entry is carried out or alternatively additive input of the **rotary axis difference** (R31) is performed in the specified ZO memory, depending on the definition of R10.

When differential measurement is selected (R23 = 13) **only** MP1 is measured twice.

### Preconditions:

- The probe must be positioned **with** tool offset and **without G53** to face the first measuring point (MP1, see Fig. 5.26).
- Parameter R19 is used to specify the distance in the offset axis between MP1 and MP2 (positive values only).
- Measurement path "m" in the measuring axis must be less than the offset path (R19) (see Fig. 5.26).

It is therefore only possible to measure an angle of max. 44.999 degrees. However, the measurement can be performed from all sides.

The angle setpoint is the angle between the offset axis and the workpiece edge.

**The following parameters must be defined prior to call:**

Parameters	Description
R10 = 0 = 1...4 = 5 = 6	No automatic ZO entry Automatic entry in ZO G54...G57 of the rotary axis defined in R31 Automatic entry in ZO G58 of the rotary axis defined in R31 Automatic entry in angle for coordinate rotation (G58)
R11 = 0 > 0	Without empirical value Empirical value memory number (see Section 2.3)
R13 = 0...359,5	Compensation angle position for monodirectional probe (see Section 2.5)
R19	Incremental infeed offset axis (positive only)
R22	Probe number (see Section 2.6)
R23 = 3 = 13	Paraxial angle point measurement Paraxial angle point measurement with differential measurement
R24	Set value angle (max. +/- 44.99 degrees)
R25 R25 = 0	Variable measuring speed in mm/min Standard cycle value
R26 = 0...359.5	Start angle (for differential measurement only)
R27 = 1...R <sub>max</sub>	Number of measurements at same location (typically 1..3)
R28 = 1...R <sub>max</sub>	Multiplication factor measurement path "2a"
R30 = 102..302	Number of offset axis/measuring axis (see Section 2.12)
R31	Number of rotary axis
R32	Set value approach position with reference to workpiece zero and measuring axis
R36	Safe area

See Section 10.2 for result display parameters.

**Example: Angular measurement with cycle L978** (Data as in Fig. 5.29)




Fig. 5.27 Angular measurement

Probe length (Z axis) in TO memory D99 (value 50)

```

%MPF    9784
N5      G54 T200           T number probe; select ZO
N10     G00 X140 Y70      Position probe in X and Y
                               axes to face the measuring point
N15     Z40 D99           Position Z axis level with
                               measuring point
N20     R10=6      R11=10   R19=40   R22=1   Define parameters for measuring cycle
          R23=3      R24=0   R25=0   R27=1
          R28=5      R30=102 R31=4   R32=0
          R36=5
N25     L978             Cycle call for angular measurement
N30     G00 Z160         Run up Z axis
:
Machining centre program
:
:
N...    M30
    
```

END OF SECTION

## 6 Measuring Cycles for Turning and Milling Work

### 6.1 L981 Searching for a hole/slot

#### Function and application

Cycle L981 searches for the position of a hole/slot on a face or at a cylinder (outside or inside) with the aid of a probe on a rotary axis (C axis).

To begin with, the cycle uses the linear axis to position the ball center point of the probe on the center point circle of the hole/slot specified by R18. Following this, the reference plane defined by R2 is approached. Now, sensing (searching) of the workpiece can be started. A hole/slot is assumed to be found if the set approach value (R32) could be approached without a measuring signal. The search grid (in degrees) and the measuring speed can be preselected via R parameters.

After the hole/slot has been found, position determination is carried out in the rotary axis. In addition, the rotary axis position programmed prior to cycle call is used to calculate the deviation. The deviation is allowed for in a ZO memory if the deviation ascertained is less than the specified positional tolerance (R36), depending on the definition of R10. An alarm is triggered when the positional tolerance is exceeded.

The probe is in the hole or slot centre on completion of measurement.


#### Precondition:

The workpiece probe must be defined as type 30 (see Section 1.4.4).


#### Note:

Position determination in the linear axis can be carried out subsequently using cycle L977 (previously L982).

**Example:** Plane selection for searching for a hole/slot on the face:



**Example:** Plane selection for searching for a hole/slot on the cylinder:



**The following parameters must be defined prior to call:**

Parameters	Description
R1	Setpoint diameter hole/slot
R2	Reference plane
R10 = 0 = 1-4 = 5	No automatic ZO input Automatic ZO input in G54 - G57 Automatic ZO input in G58
R18	Centre point linear axis (in radius for transverse axis)
R22	Probe number
R23 = 1 = 2	On face At cylinder
R25 R25 = 0	Variable measuring speed Standard cycle velocity
R26	Search increment in degrees (positive only)
R27 = 1...R <sub>max</sub>	Number of measurements at same location
R32	Approach setpoint
R36	Safe area (positional tolerance)

**Example:** Determine positional deviation of a hole on a face




Fig. 6.1 Searching for a hole on the face

<b>%MPF</b>	<b>981</b>								
<b>N5</b>	<b>G16</b>	<b>X</b>	<b>C</b>	<b>X</b>	<b>Z</b>				Plane selection
<b>N10</b>	<b>G</b>	<b>X154</b>	<b>D33</b>						Position probe near the centre point circle of the hole
<b>N15</b>	<b>C0</b>								Position rotary axis
<b>N20</b>	<b>R1=30</b>	<b>R2=125</b>	<b>R10=5</b>	<b>R18=80</b>					Parameters for L981
	<b>R22=1</b>	<b>R23=1</b>	<b>R25=0</b>	<b>R26=5</b>					
	<b>R27=1</b>	<b>R32=100</b>	<b>R36=10</b>						
<b>N25</b>	<b>L981</b>								Search for hole
<b>N30</b>	<b>M30</b>								

END OF SECTION

## 7 Measuring in JOG Mode (SINUMERIK 880/880 GA2)

The function MEASURING IN JOG mode contains the following functions:


- Semi-automatic determining of tool lengths and storing of values in tool offset memory,
- semi-automatic determining of workpiece zero and storing of value in zero offset memory.

The functions are operated via softkeys and input displays. Incremental traversing (INC) is disabled in MEASURING IN JOG mode. The measuring process is aborted with RESET or on mode change.

### Caution!

Please make sure that you select the correct channel as the function MEASURING IN JOG mode is channel-dependent. If the incorrect channel is selected and the measuring process is activated the probe may be damaged.

The measuring function is selected from the row of softkeys in the JOG basic display.



### 7.1 Tool measurement

With this function it is possible to measure tools which are in the machine without previously having to enter the geometry data in a tool offset memory. This means that tools with unknown lengths can be measured.

The tool lengths can be entered in a tool offset memory automatically and are then immediately available for machining of the workpiece.

#### Prerequisites:

- The reference points have already been approached.
- The starting conditions for automatic mode have been fulfilled.
- The tool probe is swivelled in or retracted.
- The tool probe has been calibrated with measuring cycle L972/L975.
- Plane correctly defined, initial setting.

### 7.1.1 Operating and function sequence

1. The tool is in position or has been put in position manually.



2. The following screen form appears when you press the softkey MEASURE TOOL:

<b>JOG</b>	<b>1. 1</b>																																																
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">Tool measurement</td> <td style="width: 30%;"></td> <td style="width: 20%;">T0 area</td> <td style="width: 20%; text-align: right;">1</td> </tr> <tr> <td>Tool offset</td> <td style="text-align: right;">D 5</td> <td>Measurement parameter</td> <td style="text-align: right;">2</td> </tr> <tr> <td>Tool probe</td> <td style="text-align: right;">1</td> <td>(Measure radius -&gt; 0)</td> <td></td> </tr> <tr> <td>Tool type</td> <td style="text-align: right;">3</td> <td>(Measure L1 -&gt; 1)</td> <td></td> </tr> <tr> <td>Empir. value memory no.</td> <td style="text-align: right;">10</td> <td>(Measure L2 -&gt; 2)</td> <td></td> </tr> <tr> <td>Tool length</td> <td></td> <td>Empirical value</td> <td style="text-align: right;">0.020</td> </tr> <tr> <td>Actual position</td> <td></td> <td>REPOS offset</td> <td></td> </tr> <tr> <td>X</td> <td style="text-align: right;">0.000</td> <td>X</td> <td style="text-align: right;">0.000</td> </tr> <tr> <td>Y</td> <td style="text-align: right;">0.000</td> <td>Y</td> <td style="text-align: right;">0.000</td> </tr> <tr> <td>Z</td> <td style="text-align: right;">0.000</td> <td>Z</td> <td style="text-align: right;">0.000</td> </tr> <tr> <td>A1</td> <td style="text-align: right;">0.000</td> <td>A1</td> <td style="text-align: right;">0.000</td> </tr> <tr> <td>B1</td> <td style="text-align: right;">0.000</td> <td>B1</td> <td style="text-align: right;">0.000</td> </tr> </table>		Tool measurement		T0 area	1	Tool offset	D 5	Measurement parameter	2	Tool probe	1	(Measure radius -> 0)		Tool type	3	(Measure L1 -> 1)		Empir. value memory no.	10	(Measure L2 -> 2)		Tool length		Empirical value	0.020	Actual position		REPOS offset		X	0.000	X	0.000	Y	0.000	Y	0.000	Z	0.000	Z	0.000	A1	0.000	A1	0.000	B1	0.000	B1	0.000
Tool measurement		T0 area	1																																														
Tool offset	D 5	Measurement parameter	2																																														
Tool probe	1	(Measure radius -> 0)																																															
Tool type	3	(Measure L1 -> 1)																																															
Empir. value memory no.	10	(Measure L2 -> 2)																																															
Tool length		Empirical value	0.020																																														
Actual position		REPOS offset																																															
X	0.000	X	0.000																																														
Y	0.000	Y	0.000																																														
Z	0.000	Z	0.000																																														
A1	0.000	A1	0.000																																														
B1	0.000	B1	0.000																																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%; padding: 5px;">MEASURE</td> <td style="width: 20%;"></td> <td style="width: 20%;"></td> <td style="width: 20%;"></td> <td style="width: 20%;"></td> </tr> </table>		MEASURE																																															
MEASURE																																																	

*Input display for Tool measurement*




3. You enter the values in the different input fields using the alphanumeric keyboard

**Explanation of the input values:****TO area**

Number of the TO area in which the determined tool data for the tool being measured are to be stored.

The TO area is preselected via the channel and is displayed here.

**Tool offset**

Tool offset number D... The determined tool data are stored under this tool number.

**Tool type (1-39)**


Tool type of the tool to be measured.

1 - 9 : Calculation of the tool geometry via the set plane

10 - 39 : Additional information radius/L1/L2 required! See description below (measurement parameters).

**Tool probe**

Number of tool probe.

**Empirical value memory no.**


The number of the empirical value memory to be used must be entered here.

If the value "0" is entered the tool length required is calculated without using an empirical value.

If a value other than "0" is entered the contents of the chosen empirical value memory are displayed. This value is taken into account when the tool geometry is calculated. The empirical values must be entered/stored in the cycle setting data.



***The number of empirical value memories depends on the machine configuration.  
 (See information supplied by the machine tool manufacturer).***



**Measurement parameter (0 - 2)**


If a tool type 1 ... 9 is entered the tool geometry is calculated using the defined plane and the selected traversing axis, i.e. any entries in the input display at this point are of no significance.

If a tool type 10 ...39 is entered, the geometrical value which is to be used (radius, length L1 or L2) must be entered under measurement parameter.

Input	"0"	Measure radius
	"1"	Measure length L1
	"2"	Measure length L2



4. You position the tool near the tool probe by operating the JOG direction keys.



Tool measurement in JOG mode

- MEASURE** 5. The measuring function is activated once the softkey MEASURE has been operated. If incorrect values are entered, alarm 3050, "WRONG INPUT" is displayed. The dialog text MEASURING ACTIVE is displayed.

The displayed softkey function STORE is not enabled until the probe has been deflected.


<b>JOG</b>		<b>1.1</b>	
<pre> Tool measurement                TO area      1 Tool offset          D 5      Measurement parameter  2 Tool probe              1      (Measure radius  -&gt; 0) Tool type              3      (Measure L1     -&gt; 1) Empir. value memory no. 10    (Measure L2     -&gt; 2) Tool length                Empirical value  0.020 Actual position            REPOS offset X          0.000           X          0.000 Y          0.000           Y          0.000 Z          0.000           Z          0.000 A1         0.000           A1         0.000 B1         0.000           B1         0.000 </pre>			
MEASURING ACTIVE			
STORE			

Display after the softkey MEASURE has been pressed

6. The axis which is first traversed from zero speed and the direction define the direction of measurement and only with this value is it possible to traverse to the probe with the set measuring speed as in JOG mode.


Until the probe has been deflected, it is only possible to traverse along this axis in this direction. All other axes, directions and rapid traverse remain disabled.

It is possible to reduce the set measuring speed with feedrate override.



- As soon as the probe has been deflected, the traversing axis (measuring axis) is stopped and the selected tool geometry is calculated. The derived tool length is displayed (tool length).

The dialog text MEASURING ACTIVE is deleted and the STORE softkey is enabled.




Display after probe has been deflected



- When you press the softkey STORE, the measured tool length is stored in the selected tool offset memory. The P no. within the selected tool offset memory in which the determined value is entered is derived from the measurement plane, the measuring axis and the tool type.

Which measuring axis wear memory is deleted depends on the machine configuration.



After the value has been stored, the standard display TOOL OFFSET is automatically selected for the previously entered D no.

The dialog text RETRACT MEASURING PROBE appears.

JOG	1.1																																				
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">TOOL OFFSET</td> <td style="width: 30%; text-align: center;">T0 area</td> <td style="width: 40%; text-align: right;">1</td> </tr> <tr> <td>Current offset no.</td> <td style="text-align: center;">D 5</td> <td></td> </tr> <tr> <td>D005 0 Tool</td> <td></td> <td style="text-align: right;">123</td> </tr> <tr> <td>1 Tool type</td> <td></td> <td style="text-align: right;">3</td> </tr> <tr> <td>2 L1 geometry</td> <td></td> <td style="text-align: right;">120.231</td> </tr> <tr> <td>3 L2 geometry</td> <td></td> <td style="text-align: right;">0.0</td> </tr> <tr> <td>4 Diameter</td> <td></td> <td style="text-align: right;">0.0</td> </tr> <tr> <td>5 L1 wear</td> <td></td> <td style="text-align: right;">0.0</td> </tr> <tr> <td>6 L2 wear</td> <td></td> <td style="text-align: right;">0.0</td> </tr> <tr> <td>7 Diameter/radius</td> <td></td> <td style="text-align: right;">0.0</td> </tr> <tr> <td>8 L1 base</td> <td></td> <td style="text-align: right;">0.0</td> </tr> <tr> <td>9 L2 base</td> <td></td> <td style="text-align: right;">0.0</td> </tr> </table>		TOOL OFFSET	T0 area	1	Current offset no.	D 5		D005 0 Tool		123	1 Tool type		3	2 L1 geometry		120.231	3 L2 geometry		0.0	4 Diameter		0.0	5 L1 wear		0.0	6 L2 wear		0.0	7 Diameter/radius		0.0	8 L1 base		0.0	9 L2 base		0.0
TOOL OFFSET	T0 area	1																																			
Current offset no.	D 5																																				
D005 0 Tool		123																																			
1 Tool type		3																																			
2 L1 geometry		120.231																																			
3 L2 geometry		0.0																																			
4 Diameter		0.0																																			
5 L1 wear		0.0																																			
6 L2 wear		0.0																																			
7 Diameter/radius		0.0																																			
8 L1 base		0.0																																			
9 L2 base		0.0																																			
RETRACT MEASURING PROBE																																					
<table border="1" style="width: 100%; height: 30px; border-collapse: collapse;"> <tr> <td style="width: 25%;"></td> <td style="width: 25%;"></td> <td style="width: 25%;"></td> <td style="width: 25%;"></td> </tr> </table>																																					

*Tool offset memory display after retraction of probe*




9. You can retract the probe with the appropriate direction keys.



**The following applies when retracting the measuring probe:**

- The probe can only be retracted in the opposite direction to that of the measuring direction.
- All other axes, axis directions and rapid traverse are disabled.
- When the retraction path has been completed it again becomes possible to move along every axis and the basic display JOG appears.



If the measured value is not to be stored the function can be aborted with RESET or a mode change. The dialog text "JOG-MEASUREMENT ABORTED" appears on the screen. In this case retraction is not limited to a predefined distance, i.e. any axis can be traversed without limitation.

## 7.2 Workpiece measurement

With this function it is possible to determine the workpiece zero offsets using a workpiece probe in the machine. The resulting zero offsets are automatically loaded in the zero offset memories G54 to G57.

The zero offset memory G58/G59 and the external zero offset cannot be loaded with this function.

### Prerequisites

- The reference points have been approached.
- The starting conditions for automatic mode are fulfilled.
- The workpiece probe is in the turret or the spindle.
- The workpiece probe has been calibrated with measuring cycle L973/L976.
- Plane correctly defined, initial setting.

### 7.2.1 Operating and function sequence

1. The workpiece is clamped in position.



2. The following screen form appears when you press the softkey MEASURE WORKPIECE:

JOG		1.1	
Workpiece measurement			
Tool offset	D 2	Axis name L1	X
Workpiece probe	1	Axis name L2	Z
Emp. value memory no.	10	ZO (fine)	G57
Setpoint	200.000	Empirical value	0.025
Actual value			
Actual position		REPOS offset	
X	0.000	X	0.000
Y	0.000	Y	0.000
Z	0.000	Z	0.000
A1	0.000	A1	0.000
B1	0.000	B1	0.000
MEASURE			

*Input display for workpiece measurement*



3. You enter the values in the different input fields using the alphanumeric keyboard.


## Explanation of the input values:

### Tool offset

The tool offset number D...The geometry data of the workpiece probe are stored under this tool offset number.

### Workpiece probe

Number of the workpiece probe.



### Zero offset (fine)

Here you define in which zero offset memory the results of the measurement are to be stored.


### Empirical value memory no.

The number of the empirical value memory to be used must be entered here.

If the value "0" is entered the zero offset required is calculated without using an empirical value.

If a value other than "0" is entered the contents of the chosen empirical value memory are displayed. This value is taken into account when the zero offset at the workpiece is calculated.

The empirical values must be entered/stored in the cycle setting data.



### Setpoint

The zero offset is determined taking the preset workpiece setpoint into consideration.


### Axis names for L1/L2

The data for L1 and L2 must be assigned to axes so that the tool offset data of the workpiece probe can be used to determine the zero offset.

**X**

4. You position the workpiece probe close to and opposite the defined setpoint surface by operating the JOG direction keys.

**Z**




*Measuring the workpiece in JOG mode*

**MEASURE**

5. The measuring function is activated once the softkey MEASURE has been operated. If incorrect values are entered, alarm 3050, "WRONG INPUT" is displayed. The dialog text MEASURING ACTIVE is displayed.

The displayed softkey function STORE is not enabled until the workpiece probe has been deflected




Display after the softkey MEASURE has been pressed

- The axis which is first traversed from zero speed and the direction define the direction of measurement and only with this value is it possible to traverse the workpiece probe with the set measuring speed as in JOG mode.

Until the probe has been deflected, it is only possible to traverse along this axis in this direction. All other axes, directions and rapid traverse remain disabled.

It is possible to reduce the set measuring speed with feedrate override.



7. As soon as the probe gives a signal the traversing axis (measuring axis) is stopped. The workpiece actual value and the workpiece zero offset are calculated.

The derived actual value is displayed (actual value).

The dialog text MEASURING ACTIVE is deleted and the STORE softkey is enabled.

JOG		1.1	
Workpiece measurement			
Tool offset	D 2	Axis name L1	X
Workpiece probe	1	Axis name L2	Z
Emp. value memory no.	10	ZO (fine)	G57
Setpoint	200.000	Empirical value	0.025
Actual value	200.235		
Actual position		REPOS offset	
X	0.000	X	0.000
Y	0.000	Y	0.000
Z	0.000	Z	0.000
A1	0.000	A1	0.000
B1	0.000	B1	0.000
STORE			

*Display after workpiece probe has been retracted*

STORE

8. When you press the STORE softkey the determined ZO value is stored in the selected zero offset memory (fine).

After the value has been stored, the standard input display zero offset of the previously entered group is entered. The dialog text RETRACT MEASURING PROBE appears.

**Special case:**

If G53 is entered (into the input display before the measuring is started), neither is the zero offset value stored nor the zero offset input display called up, but the input display "MEASURE WORKPIECE" is displayed directly.

JOG		1.1	
SETTING DATA ZERO OFFSET (G57)			
coarse		fine	
X	0		0.235
Y	0		0
Z	0		0
A1	0		0
B1	0		0
RETRACT MEASURING PROBE			
STORE			

*Tool offset memory display after retraction of probe*


X

9. You can retract the probe with the appropriate direction keys.

Z

**The following applies when retracting the measuring probe:**

- The probe can only be retracted in the opposite direction to that of the measuring direction.
- All other axes, axis directions and rapid traverse are disabled.
- When the retraction path has been completed it again becomes possible to move along every axis and the basic display JOG appears.



If the measured value is not to be stored the function can be aborted with RESET or a mode change. The dialog text "JOG-MEASUREMENT ABORTED" appears on the screen. In this case retraction is not limited to a predefined distance, i.e. any axis can be traversed without limitation.

END OF SECTION

## 8 Automatic Workpiece Measurement in JOG Mode (SINUMERIK 840 SW2)

### 8.1 General

Automatic workpiece measurement in JOG mode is an extended version of the Siemens "Inprocess Measurement" cycles for SINUMERIK. With the JOG measuring function the distance between machine zero and the reference point (workpiece zero) can be determined and then stored with the softkeys "STORE ZO" and "STORE PRESET".

The difference between these cycles and conventional cycles lies in the way they are operated and parameterized.

Emphasis has been placed on implementing simple cycles which are easy to operate. Almost every type of workpiece found in practice is available to the operator in the various selection menus. Workpieces can be measured in the machining planes XY, ZX or YZ defined by G17, G18, G19.

Only the most essential parameters have to be set, such as:

- Drilling axis selection
- Number of probe
- Number of D offset in which probe geometry is entered
- Measuring speed
- Number of measurement repetitions
- Measurement path
- Number of zero offset
- Setpoint or estimated setpoint of several workpiece dimensions.

All intermediate positions are approached at the entered max. axis velocity in percent (NC MD 280\*) (if MDC 800.0=0 collision monitoring deactivated) or, if collision monitoring is active (MDC 800.0=1), at the positioning velocity entered in MDC 5.

## 8.1 General

The whole process is carried out in "JOG" mode. Once the measurement variants have been selected and the cycle parameters set, the probe must be positioned, for example, at the centre of the drill hole in "JOG" mode.

When the softkeys "MEASURING START" AND "CALIBRATE START" have been pressed, the control switches to "AUTOMATIC" mode and measuring cycle L887 is activated.

This process runs in the channel defined by the machine tool manufacturer and is initiated by the PLC if FX 34 is linked into the PLC.

Once "AUTOMATIC" mode is active, NC Start must be executed via the machine control panel.

If NC Start is not executed via the machine control panel within 30 seconds, the control returns to the start menu and switches back to "JOG" mode.

After NC Start and program end the control switches back to "JOG" mode and the selection display showing the results of the workpiece measurement is displayed.

**The following results are shown:**

- Actual value: e.g. diameter of drill hole
- Difference: Setpoint - actual value
- Axis position: 1st axis (abscissa) and 2nd axis (ordinate),  
e.g. the centre point coordinates of the hole.

The axis-specific measuring results can be displayed both as machine coordinates or as workpiece coordinates, although this display refers to the ZO memory G5x entered in the input display.

The display is selected via bit 3 of the cycle setting data SDC 800 (channel-oriented bits).

SDC 800.3 = 0      Display in machine coordinates

SDC 800.3 = 1      Display in workpiece coordinates

The user defines the memory in which the measured values are to be stored.

**There are two possibilities:**

When the measuring cycle has been processed the axis position is stored

- as a preset offset  
    → softkey "STORE PRESET"
- as a zero offset in zero offset coarse  
    → softkey "STORE ZO"

The user is now able process the measured values (centre point coordinates or coordinates of workpiece reference point) in the next NC part program.

You will discover from reading the User Guide that the cycles have to be set with many more parameters than are described here.

These other parameters are stored in measuring cycle L887.




**Selecting the measuring cycles:**

Select "JOG" mode

Prog. para.	Sett. data	Data I/O	Program.		Diagnostic	User
JOG						Mode grp.: 1
Program reset						Channel : 1
Actual value		REPOS offset		Program pointer		
X	20.478	0.000	% 300			N 0
Y	7.199	0.000	L 0	P 0	N 0	
Z	27.998	0.000	L 0	P 0	N 0	
Feedrate		Override	Set value		Auxiliary functions	
F = 0.00	30 %	F = 0.00M		T =	M =	
				D =	M =	
				H =	M =	
Spindle		Override	Position	Set value		
S 1 = 0	0 %	0.00	S 1 = 0			
Over-store		INC. variable	Measure workpiece			

When the softkey "MEASURE WORKPIECE" is pressed the selection display "WORKPIECE MEASUREMENT" appears in which the parameters are entered for the measuring cycles and the functions, measure workpiece, calibrate, store PRESET and store ZO can be selected.

8.1 General

Prog. para.	Sett. data	Data I/O	Program.		Diagnostic	User																																				
JOG						Mode grp.: 1																																				
Program reset						Channel: 1																																				
Workpiece measurement:																																										
																																										
<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2">RESULTS</th> <th colspan="2">INPUT</th> </tr> </thead> <tbody> <tr> <td>ACTUAL VALUE</td> <td>40.123</td> <td>DRILLING AXIS</td> <td><input type="text" value="1"/></td> </tr> <tr> <td>DIFFERENCE</td> <td>0.123</td> <td>MULTI. PROBE</td> <td>2</td> </tr> <tr> <td>1ST AXIS</td> <td>90.005</td> <td>D NUMBER</td> <td>15</td> </tr> <tr> <td>2ND AXIS</td> <td>13.141</td> <td>MEAS. SPEED</td> <td>20</td> </tr> <tr> <td></td> <td></td> <td>MEAS. REPETITION</td> <td>1</td> </tr> <tr> <td></td> <td></td> <td>MEAS. PATHs</td> <td>2</td> </tr> <tr> <td colspan="4" style="text-align:center;">-----</td> </tr> <tr> <td colspan="4" style="text-align:center;">STORE ZO in G56</td> </tr> </tbody> </table>				RESULTS		INPUT		ACTUAL VALUE	40.123	DRILLING AXIS	<input type="text" value="1"/>	DIFFERENCE	0.123	MULTI. PROBE	2	1ST AXIS	90.005	D NUMBER	15	2ND AXIS	13.141	MEAS. SPEED	20			MEAS. REPETITION	1			MEAS. PATHs	2	-----				STORE ZO in G56						
RESULTS		INPUT																																								
ACTUAL VALUE	40.123	DRILLING AXIS	<input type="text" value="1"/>																																							
DIFFERENCE	0.123	MULTI. PROBE	2																																							
1ST AXIS	90.005	D NUMBER	15																																							
2ND AXIS	13.141	MEAS. SPEED	20																																							
		MEAS. REPETITION	1																																							
		MEAS. PATHs	2																																							
-----																																										
STORE ZO in G56																																										
Axis number: 1=X (G19), 2=Y (G18), 3=Z (G17)																																										
Measure workpiece	Calibrate		Store PRESET	Store ZO																																						

## 8.2 Setting the parameters for workpiece measurement and calibration

The necessary entries are input with operator guidance in the selection display, "WORKPIECE MEASUREMENT". The following parameters must be set.

- Drilling axis  
Permissible input values are 1 for X axis (machining plane YZ)  
2 for Y axis (machining plane ZX)  
3 for Z axis (machining plane XY).
- Number of probe  
Depending on the number of workpiece probes defined in installation, any value between 1 and 14 can be entered.
- D number  
Here you enter the D number under which the geometry data of the probe are stored.
- Measuring speed  
Path increment a is usually 1mm but can be increased or decreased when calling measuring cycles with parameter R28. If a > 1 is defined, the approach velocity is automatically increased from 150mm/min to 300 mm/min. This value was selected to ensure that the braking distance is less than the permissible deflection of the probe.

- Measurement repetition  
 Here you enter the number of measurements at a certain measurement point.
- Measurement path s  
 Here you enter the multiplication factor for the measurement path 2a, where a = 1 mm. If, for example, 3 is entered, this corresponds to a measurement path of 3 x 2a = 6 mm where, within the range 3 mm before the expected set position and 3 mm beyond it, the probe is expected to switch on.
- Store ZO in G5..

Here any input value from 4 ≙ G54 to 7 ≙ G57 is permissible.


The results obtained from the workpiece measurement (axis coordinates) are stored in the zero offset memories defined G54 - G57 when you press the softkey "STORE ZO".

The active input field in inverted. In addition, a text appears in the comment line bottom left.

When you have entered the required values and have pressed the key , the value is accepted and displayed.

### 8.3 Calibrating probe in any hole


This function is selected by pressing the softkey "CALIBRATE" in the "WORKPIECE MEASUREMENT" selection display.

Prog. Para.	Sett. Data	Data I/O	Program.		Diagnostic	User
JOG						Mode grp.: 1
Program reset						Channel : 1
Workpiece measurement: Calibrating probe in any hole						
				D/L            R32= <input style="width: 40px;" type="text" value="40"/> Meas. type    R23 = <input style="width: 40px;" type="text" value="Plane"/> TRIGGERING POINTS: ABSCISSA: - DIRECTION 0 ABSCISSA:+ DIRECTION 0 ORDINATE: - DIRECTION 0 ORDINATE:+ DIRECTION 0 APPLICATE: - DIRECTION 0 APPLICATE:+ DIRECTION 0		
SETPOINT DIAMETER						
Calibr. start					Plane	Drilling axis






Once calibration type plane or drilling axis (Version 3.5 and higher) has been selected the only parameter that has to be entered is the setpoint diameter or the floor of the hole. The probe must be positioned in the centre of the hole at the calibrating depth.

The hole centre or the hole floor must be known. If this is not the case or the determined TRIGGERING points are very different, the centre point of the hole must be determined with measuring variant "Measure hole" or the hole floor must be determined with the measuring version "Measure surface" in the applicate. Calibration then has to be repeated.

When you press the softkey "CALIBRATION START" the control automatically switches to "AUTOMATIC" mode and measuring cycle L887 is selected. The measuring cycle is processed when "NC START" is operated. The determined trigger points are automatically stored in the relevant MDC area. The probe is located at the centre of the hole on completion of calibration. The control automatically switches to JOG mode and the selection display "WORKPIECE MEASUREMENT" appears on the screen. The determined trigger points are displayed when the softkey "CALIBRATION" is pressed.





## 8.4 Workpiece measurement

Prog. Para.	Sett. Data	Data I/O	Program.		Diagnostic	User	
JOG						Program reset	Mode grp.: 1 Channel : 1
Workpiece measurement:					Picture 1 of 2		
Hole	Shaft	Slot	Web	Surface			
							
Hole	Shaft	Slot	Web	Surface			


The following measurement variants are available:

- Measurement of a hole
- Measurement of a shaft
- Measurement of a slot
- Measurement of a web
- Measurement of a surface
- Measurement of an angle
- Measurement of a reference point on the workpiece

Prog. Para.	Sett. Data	Data I/O	Program.		Diagnostic	User
JOG						Program reset
					Mode grp.: 1	Channel : 1
Workpiece measurement:						Picture 2 of 2
Angle	Reference point					
						
Angle	Reference point					


When you press the softkey to select the desired measurement variant the corresponding input display appears in which several more parameters have to be set.

### 8.4.1 Measuring a hole

Prog. Para.	Sett. Data	Data I/O	Program.		Diagnostic	User	
JOG						Program reset	Mode grp.: 1 Channel : 1
Workpiece measurement: Measure hole							
 <div style="float: right; border: 1px solid black; padding: 5px; margin-top: 10px;">D R42= <input style="width: 50px;" type="text" value="40"/></div>							
SETPOINT DIAMETER							
Measure							

The only parameter that has to be set is the setpoint diameter of the hole. When you press the softkey "MEASURE", a selection display appears requesting you to position the probe at the centre of the hole.







### 8.4.2 Measuring a shaft

Prog. Para.	Sett. Data	Data I/O	Program.	Diagnostic	User				
JOG					Program reset	Mode grp.: 1 Channel : 1			
Workpiece measurement: Measure shaft									
<table border="1" style="margin-left: auto;"> <tr> <td>Zt R19=</td> <td style="width: 50px; text-align: center;">-20</td> </tr> <tr> <td>D R42=</td> <td style="width: 50px; text-align: center;">40</td> </tr> </table>						Zt R19=	-20	D R42=	40
Zt R19=	-20								
D R42=	40								
Infeed (incr.)									
Measure									





### 8.4.3 Measuring a slot

Prog. Para.	Sett. Data	Data I/O	Program.		Diagnostic	User
JOG						Mode grp.: 1
Program reset						Channel : 1
Workpiece measurement: Measure slot						
						
Set slot width						
Measure						


The following parameters must be set:

- Set slot width
- Number of axis along which measurement must be taken
  - 1 = abscissa
  - 2 = ordinate


When you press the softkey "MEASURE", a selection display appears requesting you to position the probe at the centre of the slot.



8.4.3 Measuring a slot



### 8.4.4 Measuring a web


Prog. Para.	Sett. Data	Data I/O	Program.		Diagnostic	User						
JOG						Program reset	Mode grp.: 1 Channel : 1					
Workpiece measurement: Measure web												
 <table border="1" data-bbox="1019 562 1291 745"> <tr> <td>Zt R19=</td> <td>-25</td> </tr> <tr> <td>B R42=</td> <td>50</td> </tr> <tr> <td>R30=</td> <td><input type="text" value="1"/></td> </tr> </table>							Zt R19=	-25	B R42=	50	R30=	<input type="text" value="1"/>
Zt R19=	-25											
B R42=	50											
R30=	<input type="text" value="1"/>											
Axis number measuring axis, 1=absc., 2=ord.												
Measure												

The following parameters have to be set:


- The infeed along the applicator with sign
- Set width of web
- Number of axis along which measurement is to be taken
  - 1 = abscissa
  - 2 = ordinate

When you press the softkey "MEASURE", a selection display appears requesting you to position the probe above the centre of the web.





### 8.4.5 Measuring a surface




The following parameters must be set:


- Set dimension L
- Number of axis along which measurement must be taken
  - 1 = abscissa
  - 2 = ordinate
  - 3 = applicate (drilling axis) (as from Version 3.5)

When you press the softkey "MEASURE", a selection display appears requesting you to position the probe opposite the surface.





## 8.4.6 Measuring an angle



The following parameters have to be set:

- The distance between the measuring points in the offset axis (positive values only)
- Number of axis along which measurement is to be taken
  - 1 = abscissa
  - 2 = ordinate
- Direction of measurement
  - 1 = Measurement to be taken in positive direction
  - 1 = Measurement to be taken in negative direction


### Note:

The measurement path "m" along the measuring axis must be smaller than the offset path R19. Therefore only an angle of max. 44.999° can be measured. However, the measurement can be taken from every side.


Measuring cycle L978 automatically calculates a measurement path as a function of the offset path that fulfils this condition. The measurement path S entered in the basic display is only taken into account if it is greater than the measurement path calculated by the cycle.

When you press the softkey "MEASURE", a selection display appears requesting you to position the probe between the measuring points on the workpiece.





### 8.4.7 Measuring a reference point on the workpiece

Prog. Para.	Sett. Data	Data I/O	Program.		Diagnostic	User												
JOG						Mode grp.: 1												
Program reset						Channel : 1												
Workpiece measurement: Measure reference point																		
 <table border="1" style="float: right; margin-top: 20px;"> <tr> <td>V</td> <td>R07=</td> <td><input type="text" value="30"/></td> </tr> <tr> <td>W1</td> <td>R06=</td> <td>10</td> </tr> <tr> <td>W2</td> <td>R05=</td> <td>120</td> </tr> <tr> <td>Zt</td> <td>R19=</td> <td>20</td> </tr> </table>							V	R07=	<input type="text" value="30"/>	W1	R06=	10	W2	R05=	120	Zt	R19=	20
V	R07=	<input type="text" value="30"/>																
W1	R06=	10																
W2	R05=	120																
Zt	R19=	20																
Offset probe (pos. only)																		
Measure																		


The following parameters have to be set:

- Offset of probe V (positive only)
- Angle 1 to axis 1 (abscissa)
- Angle 2 to axis 1
- Infeed in the applicate (drilling axis) incrementally to overtravelling the workpiece.

When you press the softkey "MEASURE", a selection display appears requesting you to position the probe at the reference point.



8.4.7 Measuring a reference point on the workpiece



END OF SECTION

## 9 Alarms

### 9.1 Measuring cycle alarms

Alarm Number	Alarm Group	Alarm is cancelled by ...	
4000	Measuring cycles	Press acknowledgement key	
4001 ... 4039	Measuring cycles	Press RESET key	
4040 ... 4049	Measuring cycles	Press acknowledgement key	
4050 ..4099	Mould making cycles	Press RESET key	
4100 ... 4299	Standard cycles partly meas. cycles	Press RESET key	
5000 ... 5299	User		

The table shows which alarms occur in the various cycles and can be output:

Cycle Alarm	L 8 8 7	L 9 3 1	L 9 3 2	L 9 3 3	L 9 3 4	L 9 3 5	L 9 3 6	L 9 3 7	L 9 3 8	L 9 3 9	L 9 6 1	L 9 6 2	L 9 6 3	L 9 6 4	L 9 6 5	L 9 6 6	L 9 6 7	L 9 6 8	L 9 6 9	L 9 7 0	L 9 7 1	L 9 7 2	L 9 7 3	L 9 7 4	L 9 7 6	L 9 7 7	L 9 7 8	L 9 7 9	L 9 8 0	L 9 8 1	L 9 8 2	L 9 8 8	L 9 8 9	
	4000																																	
4001																																		
4002																																		
4003																																		
4004																																		
4005																																		
4006																																		
4007																																		
4008																																		
4009																																		
4010																																		
4011																																		
4012																																		
4013																																		
4014																																		
4015																																		
4019																																		
4020																																		
4021																																		
4025																																		
4026																																		
4027																																		
4030																																		



Alarm is output directly by the cycle



Alarm is set and output by the calling cycle



## 9.2 Measuring cycle alarms

The following alarm texts are stored in the UMS.  
 They appear in the alarm line on the screen when an alarm occurs.


Alarm No.	Alarm Text	Cancel Alarm by ...
4000	Cancel alarm	
4001	Check MDC 0/1	
4002	Check MDC 2/3	
4003	Check MDC 1000 - 1019	
4004	Load MDC inhibited	
4005	MDC area exceeded	
4006	NC type or NC SW version wrong	
4007	Wrong MC programs loaded	
4008	Check MDC (Nxxxx)	
4009	Measurement not possible	
4010	Probe is defective	
4011	Probe does not switch	
4012	Probe collision	

Alarm No.	Alarm Text	Cancel Alarm by ...
4013	Check type in TO memory	
4014	STACK overflow	
4015	Check ZO number	
4019	Calculation not possible	
4020	No D No. received from PLC	
4021	PLC interface not ready	
4025	Tool tip position wrong	
4026	Toolnose location 9 defined	
4027	Toolnose loc. <1 or >10 def	
4030	Safe area exceeded	
4031	Applicate outside tolerance	
4032	Ordinate outside tolerance	
4033	Appl. & ord. outside tol.	
4038	Meas. termination/RESET	

Alarm No.	Alarm Text	Cancel Alarm by ...
4039	Program RESET necessary	
4040	Oversize	
4041	Undersize	
4042	Perm. dim. diff'ce. exceeded	
4048	No active tool available	
4049	Display selection not poss.	
4100	No D number active	
4121	Spindle not in tol. range	
4180	Option not available	
4200	Check definition R (Nxxxx)	
4219	Call cycle again	
4220	Parallel lines	

**Explanation of alarm 4200**

Example of an alarm line



It has been detected in the cycle running in channel 2 that parameter R32 has been defined incorrectly.

**9.3 Alarm description**

<b>4000</b>	<b>Cancel alarm</b>
Explanation:	Alarm line must be cleared to enable further alarms to be displayed by the measuring cycles.
Remedy:	Press acknowledgement key
<b>4001</b>	<b>Check MDC 0/1</b>
Explanation:	Only on installation
<b>4002</b>	<b>Check MDC 2/3</b>
Explanation:	Only on installation
<b>4003</b>	<b>Check MDC 1000 to 1019</b>
Explanation:	Only on installation
<b>4004</b>	<b>Load MDC inhibited</b>
Explanation:	Only on installation with L898/L969 Set MD 5012 bit 2 to "0"
<b>4005</b>	<b>MDC area exceeded</b>
Explanation:	Only on installation
<b>4006</b>	<b>NC type or NC SW-Version wrong</b>
Explanation:	NC type or NC software version wrong
Remedy:	Check MD 157

<b>4007</b>	<b>Wrong MC programs loaded</b>
Explanation:	Wrong auxiliary cycles (L93x, L96x)
Remedy:	Load auxiliary cycles from measuring cycle diskette (Version 20)

<b>4008</b>	<b>Check MDC (Nxxxxx)</b>
Explanation:	Block number = MDC number (as alarm 4200)
Remedy:	Correct MDC



<b>4009</b>	<b>Measurement not possible</b>
Explanation:	Coordinate rotation or scale factor is selected
Remedy:	Deselect coordinate rotation or scale factor before measuring cycle

<b>4010</b>	<b>Probe is defective</b>
Explanation:	The probe carries 1 signal already before the measurement path "2a" is started. <ul style="list-style-type: none"> <li>• Setpoint position has been specified incorrectly (probe deflected)</li> <li>• Probe fault, transmits 1 signal continuously.</li> </ul>

<b>4011</b>	<b>Probe does not switch</b>
Reason:	Probe "2a" has been completely traversed five times without a measuring signal having been transmitted. <ul style="list-style-type: none"> <li>• Set position has been incorrectly specified.</li> <li>• Probe does not transmit a signal despite being deflected.</li> </ul>

<b>4012</b>	<b>Probe collision</b>
Reason:	A switching signal has been transmitted as a result of intermediate positioning operations. <ul style="list-style-type: none"> <li>• Possibly collision</li> <li>• Set position has been incorrectly specified.</li> </ul>

<b>4013</b>	<b>Check type in TO memory</b>
Remedy:	Change type in TOA memory or for type 5-8, 10-19, check the number of the measuring axis
<b>4014</b>	<b>STACK overflow</b>
Explanation:	Change type in TO memory or check measuring axis with types 5 - 8, 10
<b>4015</b>	<b>Check ZO number</b>
Explanation:	Change ZO number in the input display
<b>4019</b>	<b>Calculation not possible (L979)</b>
Explanation:	The calculation results in a division by zero or a multiplication exceeding the R parameter format.
Remedy:	Change start angle (R 24) or indexing angle (R 26)
<b>4020</b>	<b>No D number received from PLC</b>
Explanation:	Tool not known in PLC
Remedy:	Check defining parameters R8/R9
<b>4021</b>	<b>PLC interface not ready</b>
Explanation:	PLC interface for tool management FB 121 DB 147 receives no feedback when a D number is requested.
Remedy:	Check PLC

<p><b>4025</b></p>	<p><b>Tool tip position wrong</b></p>
<p>Explanation:</p>	<p>The tool is to be measured in the X axis. The cycle wants to position the Z axis, but this would result in a collision with the measuring cube.</p>  <p style="text-align: center;">Tool cutting edge incorrectly positioned</p>
<p>Remedy:</p>	<p>Position tool in X axis before cycle call with greater positive value.</p>  <p style="text-align: center;">Tool cutting edge correctly positioned</p>

<p><b>4026</b></p>	<p><b>Toolnose location 9 defined</b></p>
<p>Explanation:</p>	<p>Tool point direction 9 cannot be measured with measurement variant "Automatic measuring" (R23 &gt; 1).</p>
<p>Remedy:</p>	<p>Use measurement variant 1.</p>

<b>4027</b>	<b>Toolnose loc. &lt; 1 or &gt; 10 def</b>
Explanation:	Only the following tool point directions (tool type) are permitted: 1, 2, 3, 4, 5, 6, 7, 8, 9 and 10.
<b>4030</b>	<b>Safe area exceeded</b>
Explanation:	The set/actual difference is greater than R36. The amount of the content of the wear memory plus the compensation value is greater than the value of NC MD 208/209. The measurement result is not accepted. <ul style="list-style-type: none"> <li>• Measuring error caused by probe</li> <li>• Measuring point contaminated</li> </ul> No tool offset has been carried out.
<b>4031</b>	<b>Applicate outside tolerance</b>
Explanation:	
<b>4032</b>	<b>Ordinate outside tolerance</b>
Explanation:	
<b>4033</b>	<b>Applic. &amp; ord. outside tolerance</b>
Explanation:	
<b>4038</b>	<b>Meas. termination / RESET</b>
Explanation:	Measuring error
Remedy:	Program can be continued with measurement abort signal or aborted by pressing the RESET key.

<b>4039</b>	<b>Program RESET necessary</b>
Explanation:	Measuring error
Remedy:	Program abort only possible by pressing the RESET key.

<b>4040</b>	<b>Oversize</b>
Explanation:	The set/actual difference is greater than the centre tolerance. There is too much material at the measuring point. Tool has been compensated for if R10 > 0.
Remedy:	Re-machining is possible.

<b>4041</b>	<b>Undersize</b>
Explanation:	The set/actual difference is less than the centre tolerance. There is too little material at the measuring point. Tool has been compensated for if R10 > 0.
Remedy:	Re-machining is not possible.

<b>4042</b>	<b>Perm. dim. diff'ce exceeded</b>
Explanation:	The set/actual difference is greater than R37. • Chipping of cutting edge • Too much wear in last cut, because hard spots have been encountered in the workpiece. No tool offset has been carried out.
Remedy:	Tool must be replaced.


<b>4048</b>	<b>No active tool available</b>
Explanation:	The tool to be compensated is not available in tool management. • Tool life exceeded • Twin tool not available

<b>4049</b>	<b>Display selection not poss.</b>
Explanation:	Measurement result display cannot be selected, because selection is possibly carried out by the PLC. Access to PLC data disabled by @ (PLC MD 6026.2).
<b>4100</b>	<b>No D number active</b>
Explanation:	No D number programmed in the program.
Remedy:	Enter D number in part program.
<b>4121</b>	<b>Spindle not in tol. range</b>
Explanation:	The spindle position is monitored in the cycle as soon as the function "M19 with axis motion" is activated. The measuring cycle is not continued, until the spindle has been in the exact stop for M19 for approx. 0.2 seconds.
Remedy:	This alarm is output, if this position is not reached within 6 seconds.
<b>4180</b>	<b>Option not available</b>
Remedy:	Retrofit measurement option (Service)
<b>4200</b>	<b>Check definition R(Nxxxx)</b>
Explanation:	Defining parameter incorrectly defined. Block number N = R parameter number.
Remedy:	Correct part program.
<b>4219</b>	<b>Call cycle again</b>
Explanation:	Measurement variant selected for JOG measuring not clearly defined.
Remedy:	Select measurement variant again after RESET.

<b>4220</b>	<b>Parallel lines</b>
Explanation:	The cycle cannot calculate any intersection points as the lines which have been measured run parallel to each other.

**Explanation of alarm 4200**

Example of an alarm line



It has been detected in the cycle running in channel 2 that parameter R32 has been defined incorrectly.

END OF SECTION

# 10 Lists

## 10.1 Overview of transfer parameters

### Parameter definition




Parameter must be defined.



Parameter is not set in the cycle for the measurement variant selected.



Definition of parameter depends on the measurement variant or machine configuration.




<b>L970</b>	<b><i>Tool measurement / Workpiece measurement</i></b>	
	<b>Possible axes Abscissa / Ordinate / Applicate</b>	
Variant R Param.	Tool measurement	Workpiece measurement
R23	0	1
R25	Variable measuring speed (if 0 rapid traverse/reduced rapid traverse)	
R30	Axis number of plane	
R32 <b>D</b>	Approach position	

**D** = Diameter value, in the case of axis diameter programming.

<b>L972</b>	<b>Tool measurement</b>		
<b>Possible axes Abcissa / Ordinate</b>			
Variant R Param.	Calibrate tool probe	Measure tool	Automatic tool measurement
R0			
R8			
R9			
R10			
R11	Empirical value memory number		
R12			
R13			
R18			Var. change position Ordinate
R19			Var. change position Abcissa
R20			
R21			
R22	Tool probe No. 1..[MDC 1001]		
R23	0	1	2 (12/22)
R24	Starting angle with tool types 26		
R25	Variable measuring speed (if 0 150/300 mm/min)		
R26			
R27	Number of measurements at same location		
R28	Multiplication factor for measurement path 2a		
R29			
R30	Axis number measuring axis		
R31			
R32			
R33	Zero offset range (lower limit)		
R34			

<b>L972</b>	<b>Tool measurement</b>		
	<b>Possible axes Abscissa / Ordinate</b>		
Variant R Param.	Calibrate tool probe	Measure tool	Automatic tool measurement
R36	Safe Area		
R37		Dimensional difference check	
R40			
R41			
R42			

**Explanation of R23:**



**Explanation of R30: NC MD 157 = x2xx**

- R30=1 Abscissa (X)
- R30=2 Ordinate (Y)
- R30=3 Applicate (Z)

**NC MD 157 = x1xx and MDC 7002 bit 1 =0: Axes exchanged**

- Axis definition via R30
- R30=1 Ordinate (X)
  - R30=2 Abscissa (Z)

**NC-MD157 = x1xx and MDZ 7002 bit 1 = 1**

- Axes not exchanged**  
Axis definition via R30 after G18 plane Z X
- R30=1 Abscissa (Z)
  - R30=2 Ordinate (X)


<b>L973</b>	<b>Workpiece measurement</b>	
	<b>Possible axes Abcissa / Ordinate</b>	
	Calibrate workpiece probe	
	with reference data	with arbitrary data
variant R Param.	Hole	Cube (Surface)
R0		
R8		
R10		
R11		
R12		
R13		
R18		
R19		
R20		
R21		
R22	Probe number 1.. [MDC 1003]	
R23	xxx02	Plane xxx22
R24		
R25	<b>Variable measuring speed (if 0 150 / 300 mm/min)</b>	
R26		
R27	Number of measurements at same location	
R28	Multiplication factor for measurement path 2a	
R29		
R30	Measuring axis	(Definition depending on R23)
R31	Axial direction 0 = positive / 1 = negative	(Definition depending on R23)
R32 <i>D</i>		Calibration setpoint
R33 <i>D</i>	Zero offset range (lower limit)	
R34		

**D** = Diameter value, if measuring axis in diameter programming.

<b>L973</b>	<b>Workpiece measurement</b>	
	<b>Possible axes Abscissa / Ordinate</b>	
	Calibrate workpiece probe with arbitrary data	
Variant R Param.	Hole	Cube (Surface)
R36 <b>D</b>	Safe area	
R37		
R40		
R41		
R42		

**D**=Diameter value, if measuring axis in diameter programming

**Explanation of R23:**



**Explanation of R30:** (see L972)

<b>L974</b>		<b>Workpiece measurement</b>					
		<b>Possible axes Abscissa / Ordinate</b>					
	ZO determination	Measuring					
Variant R Param.	1-point	1-point	1-point with reversal (M19 workpiece)	2-point at diameter	Multi-point on circumference (M19 workpiece)	Multi-point on cylinder	
R0							
R8		<b>Extended T address</b> (only if MDC 7000.0 = 1)					
R9		<b>Tool number (T address)</b> (only if MDC 7000.3 = 0)					
R10	ZO memory number	TO memory number (D number) (only if MDZ 7000.3=1)					
		Number of cutting edge (only if MDZ 7000.3=0)					
R11 [D]		<b>Empirical value memory number</b> (Average value)					
R12							
R13							
R18				Protection zone Ordinate PA (Radius)			
R19				Protection zone Abscissa LA		Offset Abscissa (incred.) LA	
R20							
R21							
R22		Probe number 1..[MDC 1003]					
R23	0	21	22	23 (24)	25	26	
R24					No. of measuring points		
R25		Variable measuring speed (if 0 150 / 300 mm/min)					

LA = Longitudinal axis  
 PA = Transverse axis  
 [D]= Memory content is a diameter value

<b>L974</b>		<b>Workpiece measurement</b>					
		<b>Possible axes Abscissa / Ordinate</b>					
		ZO deter- mination	Measuring				
Variant	1-point	1-point	1-point with reversal (M19 workpiece)	2-point at diameter	Multi- point on circumfer. (M19 workpiece)	Multi- point on cylinder	
R Param.							
R26			Start angle		Start angle =indexing angle		
R27	Number of measurements at same location						
R28	Multiplication factor for measurement path 2a						
R29		Weighting factor k for averaging					
R30	Measuring axis						
R31 <i>D</i>							
R32 <i>D</i>	Setpoint						
R33 <i>D</i>		Zero offset range (lower limit)					
R34 <i>D</i>		Compensation area with averaging					
R36 <i>D</i>	Safe area						
R37 <i>D</i>		Dimensional difference check					
R40 <i>D</i>		Upper tolerance limit (according to drawing)					
R41 <i>D</i>		Lower tolerance limit (according to drawing)					
R42 <i>D</i>		Setpoint (according to drawing)					

*D* = Diameter value, if measuring axis in diameter programming

#### Explanation of R23:

R23=23	External measurement	<b>with</b>	R18/R19
	Internal measurement	<b>without</b>	R18/R19
R23=24	Internal measurement	<b>with</b>	R18/R19

#### Explanation of R30: (see L972)


<b>L976</b>	<b>Workpiece measurement</b>				
	<b>Possible axes Abscissa / Ordinate / Applicate</b>				
	Calibrate workpiece probe with reference data			with arbitrary data	
Variant R Param.	Hole	Ball	Cube (Surface)	Hole	Cube (Surface)
R0					
R8					
R10					
R11					
R12	Reference data 1.. [MDC 1005]				
R13	<b>Compensation angle for monodirectional probe (if MDC 7004/0 = 1)</b>				
R18					
R19					
R20					
R21					
R22	Probe type/probe no. <small>Multidirectional probe 1.. [MDC 1003] Monodirectional probe 101..(100+ [MDC 1003])</small>				
R23	xxx00	<b>Plane</b> xxx10	xxx20	xxx02	<b>Plane</b> xxx22
R23	xxx01	<b>Applicate</b>		<b>Applicate</b> xxx23	
R24					
R25	<b>Variable measuring speed (if 0 150 / 300 mm/min)</b>				
R26					
R27	Number of measurements at same location				
R28	Multiplication factor for measurement path 2a				
R29					
R30	Measuring axis (Definition depending on R23)				
R31	Axial direction (Definition depending on R23) 0 = positive / 1 = negative				
R32 <b>D</b>				Calibration setpoint	
R33 <b>D</b>	Zero offset range (lower limit)				

<b>L976</b>		<b>Workpiece measurement</b>				
		<b>Possible axes Abcissa / Ordinate / Applicate</b>				
		Calibrate workpiece probe				
		with reference data			with arbitrary data	
Variant R Param.	Hole	Ball	Cube (Surface)	Hole	Cube (Surface)	
R34						
R36 <b>D</b>	Safe area					
R37						
R40						
R41						
R42						

**D**=Diameter value, if measuring axis in diameter programming.

**Explanation of R23**

R23= 5 4 3 2 1



**Explanation of R30:** (see L972)

<b>L977</b>	<b>Workpiece measurement</b>							
	<b>Possible axes Abscissa / Ordinate</b>							
	Measuring				ZO determination			
Variant R Param.	Hole	Shaft	Slot	Web	Hole	Shaft	Slot	Web
R0								
R8	<b>Extended T address</b> (only if MDC 7000.0 = 1)							
R9	<b>Tool No. (T address)</b> (only if MDC 7000.3 = 0)							
R10	TO memory No. (D number) (if MDC 7000.3=1)				ZO memory number			
	Number of cutting edge (if MDC 7000.3=0)							
R11	Empirical value memory number (Average value)							
R12								
R13	Compensation angle for monodirectional slot (if MDC 7004.0=1)							
R18								
R19		Infeed Applicate		Infeed Applicate		Infeed Applicate		Infeed Applicate
R20								
R21								
R22	<b>Probe type/probe No.</b> Multidirectional probe 1..[MDC 1003] Monodirectional probe 101..(100+[MDC 1003])							
R23	1	2	11	12	21	22	31	32
R24								
R25	<b>Variable measuring speed (if 0 150 / 300 mm/min)</b>							

<b>L977</b>		<b>Workpiece measurement</b>							
		<b>Possible axes Abscissa / Ordinate</b>							
		<b>Measuring</b>				<b>ZO determination</b>			
Variant R Param.		Hole	Shaft	Slot	Web	Hole	Shaft	Slot	Web
R26									
R27		Number of measurements at same location							
R28		Multiplication factor for measurement path 2a							
R29		Weighting factor k for averaging							
R30				Measuring axis				Measuring axis	
R31									
R32						Setpoint			
R33		Zero offset range (lower limit)							
R34		Compensation area with averaging							
R36		Safe area							
R37		Dimensional difference check							
R40		Upper tolerance limit (acc. to drawing)							
R41		Lower tolerance limit (acc. to drawing)							
R42		Setpoint (acc. to drawing)							

**Explanation of R30:** (see L972)

<b>L979</b>	<b>Workpiece measurement</b>			
	<b>Possible axes Abscissa / Ordinate / Applicate</b>			
	ZO determination	Measuring		ZO determination
Variant R Param.	1-point	1-point	Multi- point	Angle
R0				
R8		<b>Extended T address</b> (only if MDC 7000.0 = 1)		
R9		<b>Tool No. (T address)</b> (only if MDC 7000.3 = 0)		
R10	ZO memory no.	TO memory No. D number (s.L974/R10) Number of cutting edge (s.L974/R10)		ZO memory no.
R11	Empirical value memory number (Average value)			
R12				
R13	Compensation angle for monodir. probe (if MDC 7004.0=1) (s. L977/R13)			
R18				
R19			Infeed offset axis incremental positive only	
R20				
R21				
R22	<b>Probe type/probe No.</b> Multidirectional probe 1..[MDC 1003] Monodirectional probe 101..(100+[MDC 1003])			
R23	0 10 *	1 11 *	2 12 *	3 13 *
R24			Number of measuring points	Setpoint angle
R25	<b>Variable measuring speed (if 0 150 / 300 mm/min)</b>			

\* Differential measuring

<b>L978</b>	<b>Workpiece measurement</b>			
	<b>Possible axes Abscissa / Ordinate / Applicate</b>			
	ZO determination	Measuring		ZO determination
Variant R Param.	1-point	1-point	Multi- point	Angle
R26	<b>Start angle</b> (only for differential measurement)			
R27	Number of measurements at same location			
R28	Multiplication factor for measurement path 2a			
R29		Weighting factor k for averaging		
R30	Measuring axis			Measuring axis Offset axis
R31				Axis number Rotary axis
R32 <i>D</i>	Setpoint			Setpoint Approach position
R33 <i>D</i>		Zero offset range (lower limit)		
R34 <i>D</i>		Compensation area with averaging		
R36 <i>D</i>	Safe area			
R37 <i>D</i>		Dimensional difference check		
R40 <i>D</i>		Upper tolerance limit (according to drawing)		
R41 <i>D</i>		Lower tolerance limit (according to drawing)		
R42 <i>D</i>		Setpoint (according to drawing)		

**[D]** = Memory content is a diameter value  
**D** = Diameter value

} if measuring axis in diameter programming (not for angular measurement)

**Explanation of R30: (see L972)**

<b>L979</b>	<b>Workpiece measurement</b>								
	<b>Possible axes Abcissa / Ordinate</b>								
	Measuring				ZO determination				
Variant R Param.	Hole	Shaft	Slot	Web	Hole	Shaft	Slot	Web	
R0	internal								
R8	<b>Extended T address</b> (only if MDC 7000.0 = 1)								
R9	<b>Tool No (T address)</b> (only if MDC 7000.3 = 0)								
R10	TO memory No. (D number) (if MDC 7000/3=1)				ZO memory number				
	Number of cutting edge (if MDC 7000/3=0)								
R11	Empirical value number (average value)								
R12									
R13	Compensation angle for monodirectional probe (if MDC 7004.0=1)								
R18									
R19					Infeed Applicate				Infeed Applicate
R20 <b>D</b>	<b>Centre point abscissa</b>								
R21 <b>D</b>	<b>Centre point ordinate</b>								
R22	<p style="text-align: center;"><b>Number of measuring points/probe type/probe No.</b></p> <div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>R22 = 4</p> </div> <div> <p>Probe No. 0=Multidirectional probe /1= Monodirectional probe 0=3-point /1= 4-point</p> </div> </div>								
R23	1	2	11	12	21	22	31	32	
R24	Starting angle (from the abscissa (horizontal axis))								
R25	<b>Variable measuring speed (if 0 150 / 300 mm/min)</b>								

<b>L979</b>		<b>Workpiece measurement</b>							
		<b>Possible axes Abcissa / Ordinate</b>							
		<b>Measuring</b>				<b>ZO determination</b>			
Variant R Param.		Hole	Shaft	Slot	Web	Hole	Shaft	Slot	Web
R26		Indexing angle				Indexing angle			
R27		Number of measurements at same location							
R28		Multiplication factor for measurements path 2a							
R29		Weighting factor k for averaging							
R30									
R31		Velocity for circular interpolation				Velocity for circular interpolation			
R32						Set value			
R33		Zero offset range (lower limit)							
R34		Compensation area with averaging							
R36		Safe area							
R37		Dimensional difference check							
R40		Upper tolerance limit (according to drawing)							
R41		Lower tolerance limit (according to drawing)							
R42		Setpoint (according to drawing)							

**D**=Diameter value, if axis in diameter programming

<b>L981</b>	<b>Workpiece measurement</b>	
	<b>Possible axes Abscissa / Ordinate</b>	
Variant R Param.	on face	Searching for a hole / slot   on cylinder
R1	Set diameter	
R2 <b>D</b>	Reference plane	
R10	ZO memory number	
R11		
R18 <b>D</b>	Centre point linear axis	
R19		
R22	Probe No. 1.. [MDC 1003]	
R23	1	2
R25	<b>Variable measuring speed (if 0 150 / 300 mm/min)</b>	
R26	Search increment in degrees (positive only)	
R27	Number of measurements at same location	
R29		
R30		
R31		
R32 <b>D</b>	Approach setpoint	
R33		
R34		
R36	Safe area in degrees	


**D** = Diameter value, if axis in diameter programming

<b>L982</b>	<b>Tool measurement</b>		
<b>Possible axes Abscissa / Ordinate / Applicate</b>			
Variant	Calibrate	Measure	Automatic
R-Param.	tool probe	tool	tool measurement
R0			
R8			
R9			
R10			
R11		Empirical value memory number	
R12			
R13			Angle offset with R23 102
R18			Variable change position Ordinate
R19			Variable change position Abscissa
R20			
R21			
R22	Probe No. 1.. [MDC 1001]		
R23	0	1	2 (12/22)
R24			
R25	Variable measuring speed (if 0 150/300 mm/min)		
R26		Starting angle with tool types 26	
R27	Number of measurements at same location		
R28	Multiplication factor for measurement path 2a		
R29			
R30	Axis number measuring axis		
R31			
R32			
R33	Zero offset range (lower limit)		
R34			

<b>L972</b>	<b><i>Tool measurement</i></b>		
	<b>Possible axes Abcissa / Ordinate</b>		
Variant R-Param.	Calibrate tool probe	Measure tool	Automatic tool measurement
R36	Safe area		
R37		Dimensional difference check	
R40			
R41			
R42			


**Explanation of R23:**

R23= 4 3 2 1



Tool length in TO memory	
before	after
measurement	measurement
0	PF
1	SF
2	SF

R23= 4 3 2 1

**Explanation of R30: NC-MD 157 = x2xx**

R30=1 Abscissa (X)  
R30=2 Ordinate (Y)  
R30=3 Applicate (Z)

**NC-MD 157 = x1xx and MDZ 7002 bit 1 =0:****Axes exchanged**

Axis definition via R30

R30=1 Ordinate (X)  
R30=2 Abscissa (Z)

**NC-MD 157 = x1xx and MDZ 7002 bit 1 =1:****Axes not exchanged**

Axis definition via R30 after G18 plane Z X

R30=1 Abscissa (Z)  
R30=2 Ordinate (X)

## 10.1.1 Compatibility list, Version 10 to Version 20

### L971/L972

		Version 10	Version 20 onwards
R20	Omitted	Control parameter	————
R22	New	————	Tool probe No.
R23		Tool length definition	Control parameter
R25	New	————	Variable measuring speed

Function of L971 now by calling L972. L971 is only an auxiliary program.


**L973** only for calibrating the workpiece probe.  
No blank measurement!

		Version 10	Version 20 onwards
R11	Omitted	EV memory number	————
R21	Omitted	Control parameter	————
R22		Probe type	Probe no.
R23		Control parameter	Control parameter
R25	New	————	Var. measuring speed
R34	Omitted	Compensation area with averaging	————

**L974** now also for blank measurement!

		Version 10	Version 20 onwards
R22	New	————	Probe no.
R23		Number of measurements	Control parameter
R24		Control parameter	Number of measurements
R25		Control parameter	Var. measuring speed
R26		Offset	Now R19
R35	Omitted	Tolerance	Now R40/R41

## 10.2 Result displays



Result displays are available for displaying the measurement results. These displays are automatically shown on the screen on completion of the cycle.

The numbers in the fields of the displays shown indicate the R parameter in which the relevant data must be entered.

AUTOMATIC		- CH1		
Tool measurement:		Measurement result		Cycle 215
Input data		Output data		
Measurement variant	23	Measure (calibrate)	Actual value	Difference
D memory No.	212	L1 1.5 (Abscissa - R.)	200	201
Tool type	216	L2 1.5 (Abscissa +R.)	202	203
EV memory No.	213	D/R 1.5 (Ordinate - R.)	204	205
Empirical value	214	L1 2.5 (Ordinate +R.)	206	207
Safe area	36	L2 2.5 (Applicate - R.)	208	209
Perm. dim. diff'ce	37	D/R 2.5 (Applicate +R.)	210	211
Probe No.	218	-----		
Data	217	Alarm No.	219	

*Measurement result display for tool measurement*


<b>AUTOMATIC</b>		<b>- CH1</b>	
<b>Workpiece measurement:</b>	<b>Measurement result</b>	<b>Cycle 215</b>	
Input data	Output data		
Measurement variant      23		Actual value	Difference
Safe area                      36	Probe ball	200	201
Lower limit                    33	Abscissa      - direction	202	203
Probe No.                      218	Abscissa      +direction	204	205
Data                              217	Ordinate     - direction	206	207
	Ordinate     +direction	208	209
	Applicate    - direction	210	211
	Applicate    +direction	212	213
	Position     abscissa	214	
	Position     ordinate	216	
	Alarm No.	219	

Measurement result display for workpiece probe calibration

<b>AUTOMATIC</b>		<b>- CH1</b>	
<b>Workpiece measurement:</b>	<b>Measurement result</b>	<b>Cycle 215</b>	
Input data	Output data		
Measurement variant      23	Diameter /width	1st axis	2nd axis
Safe area                      36	Set value                      206	207	208
Perm. dim. diff'ce        37	Actual value                  209	210	211
D/ZO memory No.        216	Tolerance upper limit      200	201	202
Probe No.                      218	Tolerance lower limit      203	204	205
Data                              217	Difference                    212	213	214
	Compensation value        50		
	Alarm No.	219	

Measurement result display for workpiece measurement

## 10.3 Result parameters

	<p><b>Display of measurement results in R parameters</b>  <b>R40-R49 can be determined by MDC.</b></p> <p><b>(See machine tool manufacturer's specifications)</b></p>	
---	---	---

### Result parameters:

<b>L972</b>	<b>Tool measurement</b>			
<b>P No.</b>	<b>Calibration</b>		<b>Measurement</b>	
R200	Trigger point minus direction	Actual value Abscissa	L1 (1st cutting edge)	Actual value
R201	Trigger point minus direction	Difference Abscissa	L1 (1st cutting edge)	Difference
R202	Trigger point plus direction	Actual value Abscissa	L1 (1st cutting edge)	Actual value
R203	Trigger point plus direction	Actual value Abscissa	L1 (1st cutting edge)	Difference
R204	Trigger point minus direction	Actual value Ordinate	D/R (1st cutting edge)	Actual value
R205	Trigger point minus direction	Difference Ordinate	D/R (1st cutting edge)	Difference
R206	Trigger point plus direction	Actual value Ordinate	L1 (2nd cutting edge)	Actual value
R207	Trigger point plus direction	Difference Ordinate	L1 (2nd cutting edge)	Difference
R208	Trigger point minus direction	Actual value Applicate	L2 (2nd cutting edge)	Actual value
R209	Trigger point minus direction	Actual value Applicate	L2 (2nd cutting edge)	Difference
R210	Trigger point plus direction	Actual value Applicate	D/R (2nd cutting edge)	Actual value
R211	Trigger point plus direction	Difference Applicate	D/R (2nd cutting edge)	Difference
R212			D memory No.	
R213			EV memory No.	
R214			Empirical value	
R215	Cycle No.			
R216			Tool type	
R217	MDC area probe data			
R218	Probe number			
R219	Alarm number			

**Result parameters:**

<b>L973</b>	<b><i>Workpiece measurement</i></b>			
<b>P No.</b>	<b>Calibration</b>			
R200	Probe ball diameter			Actual value
R201	Probe ball diameter			Difference
R202	Trigger point	Actual value	minus direction	Abscissa
R203	Trigger point	Difference	minus direction	Abscissa
R204	Trigger point	Actual value	plus direction	Abscissa
R205	Trigger point	Difference	plus direction	Abscissa
R206	Trigger point	Actual value	minus direction	Ordinate
R207	Trigger point	Difference	minus direction	Ordinate
R208	Trigger point	Actual value	plus direction	Ordinate
R209	Trigger point	Difference	plus direction	Ordinate
R210	Trigger point	Actual value	minus direction	Applicate
R211	Trigger point	Difference	minus direction	Applicate
R212	Trigger point	Actual value	plus direction	Applicate
R213	Trigger point	Difference	plus direction	Applicate
R214	Positional deviation abscissa			
R215	Cycle number			
R216	Positional deviation ordinate			
R217	MDC area probe data			
R218	Probe number			
R219	Alarm number			

**Result parameters:**

<b>L974</b>	<b><i>Workpiece measurement</i></b>	
<b>P No.</b>	<b>Measuring / ZO determination</b>	
R200 R40	Upper tolerance limit	Measuring axis
R201		
R202		
R203 R41	Lower tolerance limit	Measuring axis
R204		
R205		
R206 R42	Setpoint	Measuring axis
R207	Setpoint	Abscissa / Applicate
R208	Setpoint	Ordinate
R209 R43	Actual value	Measuring axis
R210		
R211		
R212 R44	Difference	Measuring axis
R213		
R214		
R215		Cycle number
R216 R46		D memory number / ZO memory number
R217		MDC area Probe data
R218		Probe number
R219		Alarm number
R50		Compensation value

**Result parameters:**

<b>L976</b>	<b><i>Workpiece measurement</i></b>			
<b>P No.</b>	<b>Calibration</b>			
R200	Probe ball diameter			Actual value
R201	Probe ball diameter			Difference
R202	Trigger point	Actual value	minus direction	Abscissa
R203	Trigger point	Difference	minus direction	Abscissa
R204	Trigger point	Actual value	plus direction	Abscissa
R205	Trigger point	Difference	plus direction	Abscissa
R206	Trigger point	Actual value	minus direction	Ordinate
R207	Trigger point	Difference	minus direction	Ordinate
R208	Trigger point	Actual value	plus direction	Ordinate
R209	Trigger point	Difference	plus direction	Ordinate
R210	Trigger point	Actual value	minus direction	Applicate
R211	Trigger point	Difference	minus direction	Applicate
R212	Trigger point	Actual value	plus direction	Applicate
R213	Trigger point	Difference	plus direction	Applicate
R214	Positional deviation abscissa			
R215	Cycle number			
R216	Positional deviation ordinate			
R217	MDC area probe data			
R218	Probe number			
R219	Alarm number			

## Result parameters:

L977		Workpiece measurement			P No.	Measur. /ZO determin.
		Measurement		ZO determination		
		Hole Shaft	Slot/ Web	Hole Shaft	Slot/ Web	
R40	Upper tolerance limit	Upper tolerance limit				R200 Upper tolerance limit Hole/shaft/slot/web
R41	Lower tolerance limit	Lower tolerance limit				R201 Upper tolerance limit Centre point Abscissa
R42	Setpoint diameter	Setpoint width	Setpoint CP Abscissa	Set value slot/ web centre		R202 Upper tolerance limit Centre point Ordinate
R43	Actual value diameter	Actual value width	Setpoint CP Ordinate			R203 Lower tolerance limit Hole/shaft/slot/web
R44	Difference diameter	Difference width	Actual value CP abscissa	Actual val slot/ web width		R204 Lower tolerance limit Centre point Abscissa
R45	Actual value Abscissa	Slot/ web centre Meas. axis	Actual val. CP Ordinate			R205 Lower tolerance limit Centre point Ordinate
R46	Actual value Ordinate		Difference CP Abscissa			R206 Setpoint Hole/shaft/slot/web
R47	D memory number	D memory number	Difference CP Ordinate			R207 Set value Centre point Abscissa
R48			ZO memory number	ZO memory number		R208 Setpoint Centre point Ordinate
R49						R209 Actual value Diameter Hole/shaft/slot/web
R50	Compensation value					R210 Actual value Centre point Abscissa
						R211 Actual value Centre point Ordinate
						R212 Difference Diameter Hole/shaft/slot/web
						R213 Difference Centre point Abscissa
						R214 Difference Centre point Ordinate
						R215 Cycle number
						R216 D memory number / ZO memory number
						R217 MDC area Probe data
						R218 Probe number
						R219 Alarm number
						R50 Compensation value

**Result parameters:**

<b>L978</b>	<b><i>Workpiece measurement</i></b>	
<b>P No.</b>	<b>Measurement/ZO determination</b>	
R200 R40	Upper tolerance limit	Measuring axis
R201		
R202		
R203 R41	Lower tolerance limit	Measuring axis
R204		
R205		
R206 R42	Setpoint	Measuring axis
R207	Setpoint	Abscissa / Applicate
R208	Setpoint	Ordinate
R209 R43	Actual value	Measuring axis
R210		
R211		
R212 R44	Difference	Measuring axis
R213		
R214		
R215		Cycle number
R216 R47		D memory number / ZO memory number
R217		MDC area Probe data
R218		Probe number
R219		Alarm number
R50		Compensation value

## Result parameters:

L979		Workpiece measurement			P No.	Measurem./ZO determin.
Measurement		ZO determination				
	Hole Shaft	Slot/ Web	Hole Shaft	Slot/ Web		
					R200	Upper tolerance limit Hole/shaft/slot/web
R40	Upper tolerance limit	Upper tolerance limit			R201	Upper tolerance limit Centre point Abscissa
R41	Lower tolerance limit	Lower tolerance limit			R202	Upper tolerance limit Centre point Ordinate
R42	Setpoint Diameter	Setpoint Width	Setpoint CP Abscissa	Setpoint Slot/ Web centre	R203	Lower tolerance limit Hole/shaft/slot/web
R43	Actual value Diameter	Actual value Width	Setpoint CP Ordinate		R204	Lower tolerance limit Centre point Abscissa
R44	Difference Diameter	Difference Width	Actual val. CP Abscissa	Actual val. Slot/ Web centre	R205	Lower tolerance limit Centre point Ordinate
R45	Actual value Abscissa	Slot/ Web centre Meas. axis	Actual val. CP Ordinate	Actual val. CP Ordinate	R206	Setpoint Hole/shaft/slot/web
R46	Actual val. Ordinate		Difference CP Abscissa	Difference CP Abscissa	R207	Setpoint Centre point Abscissa
R47	D memory number	D memory number	Difference CP Ordinate	Difference CP Ordinate	R208	Setpoint Centre point Ordinate
R48			ZO memory number	ZO memory number	R209	Actual value Diameter Hole/shaft/slot/web
R49					R210	Actual value Centre point Abscissa
R50	Compensation value				R211	Actual value Centre point Ordinate
					R212	Difference Diameter Hole/shaft/slot/web
					R213	Difference Centre point Abscissa
					R214	Difference Centre point Ordinate
					R215	Cycle number
					R216	D memory number / ZO memory number
					R217	MDC area Probe data
					R218	Probe number
					R219	Alarm number
					R50	Compensation value

**Result parameters:**

<b>L981</b>	<b><i>Workpiece measurement</i></b>
<b>P No.</b>	<b>ZO determination</b>
R200	
R201	
R202	
R203	
R204	
R205	
R206	Diameter
R40	Hole Slot
R207	Setpoint
R43	Position Hole/Slot
R208	
R209	
R210	Actual value
R45	Position Hole/Slot
R211	
R212	
R213	Actual value
R47	Position Hole/Slot
R214	
R215	Cycle number
R216	ZO memory number
R46	
R217	MDC area Probe data
R218	Probe number
R219	Alarm number
R50	Compensation value

**Result parameters:**

<b>L982</b>	<b><i>Tool measurement</i></b>			
<b>P No.</b>	<b>Calibration</b>		<b>Measurement</b>	
R200	Trigger point minus direction	Actual value Abcissa	L1 (1st cutting edge)	Actual value
R201	Trigger point minus direction	Difference Abcissa	L1 (1st cutting edge)	Difference
R202	Trigger point plus direction	Actual value Abcissa	L1 (1st cutting edge)	Actual value
R203	Trigger point plus direction	Actual value Abcissa	L1 (1st cutting edge)	Difference
R204	Trigger point minus direction	Actual value Ordinate	D/R (1st cutting edge)	Actual value
R205	Trigger point minus direction	Difference Ordinate	D/R (1st cutting edge)	Difference
R206	Trigger point plus direction	Actual value Ordinate	L1 (2nd cutting edge)	Actual value
R207	Trigger point plus direction	Difference Ordinate	L1 (2nd cutting edge)	Difference
R208	Trigger point minus direction	Actual value Applicate	L2 (2nd cutting edge)	Actual value
R209	Trigger point minus direction	Actual value Applicate	L2 (2nd cutting edge)	Difference
R210	Trigger point plus direction	Actual value Applicate	D/R (2nd cutting edge)	Actual value
R211	Trigger point plus direction	Difference Applicate	D/R (2nd cutting edge)	Difference
R212			D memory No.	
R213			EV memory No.	
R214			Empirical value	
R215	Cycle number			
R216			Tool type	
R217	MDC area probe data			
R218	Probe number			
R219	Alarm number			

## 10.4 Setting data for measuring cycles

### 10.4.1 Cycle setting data memory (SDC)

Empirical values and average values of the measuring cycles are stored in the cycle setting data memory (SDC).

The SDC memory is divided in the following areas:

#### 10.4.1.1 Channel-oriented values

SDC No.	Designation	Standard value	Maximum input value	Reference system	Input unit
0 . . . 99	Siemens (Measuring cycles)	—	—	—	—
400 . . . 499	User	—	—	—	—



#### 10.4.1.2 Channel-oriented bits

SDC No.	Bit No.							
	7	6	5	4	3	2	1	0
800 . . . 819	Siemens (Measuring cycles)							
820 . . . 849	Siemens							
900 . . . 949	User							

### 10.4.2 SDC Channel-oriented values

SDC No.	Designation	Standard value	Maximum input value	Reference system	Input unit
0	Internal data	–	–	–	–

SDC No.	Designation	Standard value	Maximum input value	Reference system	Input unit
1 . . . 99	Empirical values/ average values	0	0 to +/-99999999	–	–

	<i>The number of EV/AV available is determined via MDC. (See machine tool manufacturer's specifications)</i>	
---	--	---

### 10.4.3 Channel-oriented bits

SDC No.	Bit No.							
	7	6	5	4	3	2	1	0
800						Display in workpiece coordinates when measuring in JOG mode 840/840C	Check Cycle MD	Check transfer parameters

**Bit 3** Bit 3=1: Display in workpiece coordinates.

**Bit 1** Bit 1=1: Cycle MD are checked.

**Bit 0** Bit 0=1: Transfer parameters are checked.

SDC No.	Bit No.							
	7	6	5	4	3	2	1	0
801 . . . 809	Reserved							

END OF SECTION

# 11 Abbreviations

AV	Average value
AVmem	Average value memory
HSS	Hole/Shaft/Slot
EV	Empirical value
EVmem	Empirical value memory
M version	Milling machine control
MDC	Machine data for cycles (Cycle machine data)
NC MD	NC machine data
OGM	Operator guidance macro
SDC	Setting data for cycles (Cycle setting data)
SW	Software version
T version	Turning machine control
UMS	User memory submodule

END OF SECTION